Hong Kong- Zhuhai- Macao Bridge

Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Notifications of Environmental Quality Limits Exceedances Notification No.: 201

Date of Notification: 2 February 2015

Works Inspected: Data collected from water sampling works on 12 January 2015 and the test report was issued on 19 January

2015.

Monitoring Location: Water Quality Monitoring Stations

Parameter: Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID- EBB TIDE (mg/L)	MEASURED AT MID- FLOOD TIDE (mg/L)
SS	IS(Mf)9	DA	23.5 and 120% of upstream control station's suspended solid at the same tide of the same day (i.e. CS2: 5.73 x 120% = 6.9 mg/L for mid ebb) AND CS(Mf)5: 3.53 x 120% = 4.2 mg/L for mid flood)	34.4 and 130% of upstream control station's suspended solid at the same tide of the same day (i.e. CS2: 5.73 x 130% = 7.5 mg/L for mid ebb) AND CS(Mf)5: 3.53 x 130% = 4.6 mg/L for mid flood)	4.7	24.4

Notes:

DA means depth average.

Bold Italic means AL exceedances.

Bold Italic with underline means LL exceedances.

Possible reason for Action or Limit Level Non-compliance:

On 12 January 2015, an AL exceedance of suspended solid at station IS(Mf)9 was recorded during the mid-flood tide. The exceedance have been investigated and are considered unlikely to be related to contract works due to the following reasons:

1. Seawall construction works at Zones 1 and 2 were carried out within silt curtain as recommended in the EIA Report.

2. The ranges of suspended solid at stations IS(Mf)9 during the baseline monitoring are shown as below:

Station	Range of Susper	nded Solid (mg/L) Mid- Ebb Tide	Range of Susp	pended Solid (m	g/L) Mid- Flood Tide
IS(Mf)9	5.5	to	20.1	7.3	to	26.0


The measured value at station IS(Mf)9 was below the range of suspended solid during baseline monitoring for the midflood tide. There was no specific activities recorded during the monitoring period that would cause any significant impacts on the monitoring results.

3. No leakage of turbid water or any abnormity or malpractice was observed during the sampling exercise.

As such, the suspended solid levels recorded at this station are considered to be attributed to other external factors rather than the contract works.

Actions taken/ to be taken:

As the suspended solid levels recorded beyond the water quality criteria were not related to contract works, no immediate actions are considered necessary.



Reviewed by : Claudine Lee Title : ET Leader

Date : 2 February 2015

Hong Kong- Zhuhai- Macao Bridge

Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Notifications of Environmental Quality Limits Exceedances Notification No.: 202

Date of Notification: 10 February 2015

Works Inspected: 24-hr TSP monitoring was undertaken on 21 January 2015 and the test report was issued on

29 January 2015.

Monitoring Location: AMS5 - Ma Wan Chung Village

Parameter: 24-hour TSP monitoring

Action & Limit Level (AL & LL) / Measured Level:

PARAMETER	STATION	AL (μg/m³)	LL (μg/m³)	MEASURED LEVEL, μg/m³
24-hr TSP (8:00 – 8:00 hours)	Ma Wan Chung Village (AMS5)	164	260	189

Notes: **Bold Italic** means AL exceedance

Bold Italic with underline means LL exceedance

Possible reason for Action or Limit Level Non-compliance:

An Action Level exceedance of 24-hr TSP level was recorded at AMS5, Ma Wan Chung Village, on 21 January 2015.

According to the information provided by the Contractor, the following construction activities were undertaken during the sampling period:

Zone 1

Seawall construction works

Zone 3A


Seawall construction works

The general weather condition at Tung Chun was foggy during the dust sampling period. The Air Quality Health Index recorded by EPD at the Tung Chung station during the sampling period ranged from 4 (moderate) to 10+ (serious). The measured 24-hour TSP level at AMS5 was $57 \, \mu \text{g/m}^3$ on 27 January 2015 which was below the action and limit levels. Therefore, it is considered that the exceedance on 21 January 2015 was not related to the construction activities of the Contract and was caused by poor weather condition.

Actions taken/ to be taken:

As the 24-hr TSP exceedance was not related to project works, no immediate actions are considered necessary. However, the Contractor is reminded to implement dust control measures throughout the construction phase.

Reviewed by	: Claudine Lee	Title : ET Leader
	<u>Cl</u> .	Date: 10 February 2015



Hong Kong- Zhuhai- Macao Bridge

Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Notifications of Environmental Quality Limits Exceedances Notification No.: 203

Date of Notification: 10 February 2015

Works Inspected: 24-hr TSP monitoring was undertaken on 21 January 2015 and the test report was issued on

29 January 2015.

Monitoring Location: AMS6 - Dragon Air Building

Parameter: 24-hour TSP monitoring

Action & Limit Level (AL & LL) / Measured Level:

PARAMETER	STATION	AL (μg/m³)	LL (μg/m³)	MEASURED LEVEL, μg/m³
24-hr TSP (8:00 – 8:00 hours)	Dragon Air Building (AMS6)	173	260	212

Notes: **Bold Italic** means AL exceedance

Bold Italic with underline means LL exceedance

Possible reason for Action or Limit Level Non-compliance:

An Action Level exceedance of 24-hr TSP level was recorded at AMS6, Dragon Air Building, on 21 January 2015.

According to the information provided by the Contractor, the following construction activities were undertaken during the sampling period:

Zone 1

Seawall construction works

Zone 3A


Seawall construction works

The general weather condition at Tung Chun was foggy during the dust sampling period. The Air Quality Health Index recorded by EPD at the Tung Chung station during the sampling period ranged from 4 (moderate) to 10+ (serious). The measured 24-hour TSP level at AMS6 was 77 μ g/m³ on 27 January 2015 which was below the action and limit levels. Therefore, it is considered that the exceedance on 21 January 2015 was not related to the construction activities of the Contract and was caused by poor weather condition.

Actions taken/ to be taken:

As the 24-hr TSP exceedance was not related to project works, no immediate actions are considered necessary. However, the Contractor is reminded to implement dust control measures throughout the construction phase.

Reviewed by	: Claudine Lee	Title : E	ET Leader	
	Clare.	Date : _10	February 2015	



Hong Kong- Zhuhai- Macao Bridge

Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Notifications of Environmental Quality Limits Exceedances Notification No.: 204

Date of Notification: 10 February 2015

Works Inspected: Data collected from water sampling works on 21 January 2015 and the test report was issued on 28 January

2015.

Monitoring Location: Water Quality Monitoring Stations

Parameter: Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID- EBB TIDE (mg/L)	MEASURED AT MID- FLOOD TIDE (mg/L)
SS	SR5	DA	23.5 and 120% of upstream control station's suspended solid at the same tide of the same day (i.e.	34.4 and 130% of upstream control station's suspended solid at the same tide of the same day (i.e.	9.6	29.2
SS	IS10	DA	CS2: 12.88 x 120% = 15.5 mg/L for mid ebb) AND CS(Mf)5: 7.3 x 120% = 8.8 mg/L for mid flood)	CS2: 12.88 x 130% = 16.7 mg/L for mid ebb) AND CS(Mf)5: 7.30 x 130% = 9.5 mg/L for mid flood)	9.2	28.6

Notes:

DA means depth average.

Bold Italic means AL exceedances.

Bold Italic with underline means LL exceedances.

Possible reason for Action or Limit Level Non-compliance:

On 21 January 2015, AL exceedances of suspended solid at stations SR5 and IS10 were recorded during the mid-flood tide. The exceedances have been investigated and are considered unlikely to be related to contract works due to the following reasons:

I. Seawall construction works at Zones 1 and 3A were carried out within silt curtain as recommended in the EIA Report.

2. The ranges of suspended solid at stations SR5 and IS10 during the baseline monitoring are shown as below:

Station	Range of Suspe	nded Solid (mg/L	.) Mid- Ebb Tide	Range of Susp	oended Solid (m	g/L) Mid- Flood Tide
SR5	6.7	to	16.5	6.5	to	31.2
IS10	6.1	to	20.2	7.2	to	16


The measured value at station SR5 was below the range of suspended solid during baseline monitoring for the mid-flood tide. The measured value at station IS10 was above the range of suspended solid during baseline monitoring for the mid-flood tide. However, there were no specific activities recorded during the monitoring period that would cause any significant impacts on the monitoring results.

3. No leakage of turbid water or any abnormity or malpractice was observed during the sampling exercise.

As such, the suspended solid levels recorded at this station are considered to be attributed to other external factors rather than the contract works.

Actions taken/ to be taken:

As the suspended solid levels recorded beyond the water quality criteria were not related to contract works, no immediate actions are considered necessary.



Reviewed by : Claudine Lee Title : ET Leader

Date: 10 February 2015

Hong Kong- Zhuhai- Macao Bridge

Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Notifications of Environmental Quality Limits Exceedances Notification No.: 205

Date of Notification: 10 February 2015

Works Inspected: Data collected from water sampling works on 23 January 2015 and the test report was issued on 29 January

2015.

Monitoring Location: Water Quality Monitoring Stations

Parameter: Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID- EBB TIDE (mg/L)	MEASURED AT MID- FLOOD TIDE (mg/L)
SS	SR5	DA	23.5 and 120% of upstream control station's suspended solid at the same tide of the same day (i.e.	34.4 and 130% of upstream control station's suspended solid at the same tide of the same day (i.e.	10.5	25.7
SS	SR10A	DA	(i.e. CS2: 8.77 x 120% = 10.5 mg/L for mid ebb) AND CS(Mf)5: 5.95 x 120% = 7.1 mg/L for mid flood)	CS2: 8.77 x 130% = 11.4 mg/L for mid ebb) AND CS(Mf)5: 5.95 x 130% = 7.7 mg/L for mid flood)	7.2	<u>35.1</u>

Notes:

DA means depth average.

Bold Italic means AL exceedances.

Bold Italic with underline means LL exceedances.

Possible reason for Action or Limit Level Non-compliance:

On 23 January 2015, an AL exceedance of suspended solid at station SR5 and a LL exceedance of suspended solid at station SR10A were recorded during the mid-flood tide. The exceedances have been investigated and are considered unlikely to be related to contract works due to the following reasons:

1. Seawall construction works at Zones 1 and 2 were carried out within silt curtain as recommended in the EIA Report.

2. The ranges of suspended solid at stations SR5 and SR10A during the baseline monitoring are shown as below:

Station	Range of Susper	nded Solid (mg/L) Mid- Ebb Tide	Range of Susp	ended Solid (m	g/L) Mid- Flood Tide
SR5	6.7	to	16.5	6.5	to	31.2
SR10A	3.6	to	17	4.8	to	19.2


The measured value at station SR5 was below the range of suspended solid during baseline monitoring for the mid-flood tide. The measured value at station SR10A was above the range of suspended solid during baseline monitoring for the mid-flood tide. However, there was no specific activities recorded during the monitoring period that would cause any significant impacts on the monitoring results.

3. No leakage of turbid water or any abnormity or malpractice was observed during the sampling exercise.

As such, the suspended solid levels recorded at this station are considered to be attributed to other external factors rather than the contract works.

Actions taken/ to be taken:

As the suspended solid levels recorded beyond the water quality criteria were not related to contract works, no immediate actions are considered necessary.



Reviewed by : Claudine Lee Title : ET Leader

Date: 10 February 2015

Hong Kong- Zhuhai- Macao Bridge

Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Notifications of Environmental Quality Limits Exceedances Notification No.: 206

Date of Notification: 10 February 2015

Works Inspected: Data collected from water sampling works on 26 January 2015 and the test report was issued on 2 February

2015.

Monitoring Location: Water Quality Monitoring Stations

Parameter: Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID- EBB TIDE (mg/L)	MEASURED AT MID- FLOOD TIDE (mg/L)
SS	IS5	DA	23.5 and 120% of upstream control station's suspended solid at the same tide of the same day (i.e. CS2: 4.45 x 120% = 5.3 mg/L for mid ebb) AND CS(Mf)5: 3.22 x 120% = 3.9 mg/L for mid flood)	34.4 and 130% of upstream control station's suspended solid at the same tide of the same day (i.e. CS2: 4.45 x 130% = 5.8 mg/L for mid ebb) AND CS(Mf)5: 3.22 x 130% = 4.2 mg/L for mid flood)	25.8	9.6

Notes:

DA means depth average.

Bold Italic means AL exceedances.

Bold Italic with underline means LL exceedances.

Possible reason for Action or Limit Level Non-compliance:

On 26 January 2015, an AL exceedance of suspended solid at station IS5 was recorded during the mid-ebb tide. The exceedance has been investigated and is considered unlikely to be related to contract works due to the following reasons:

1. Seawall construction works at Zones 1 and 2 were carried out within silt curtain as recommended in the EIA Report.

2. The ranges of suspended solid at station IS5 during the baseline monitoring are shown as below:

Station	Range of Suspe	nded Solid (mg/L	.) Mid- Ebb Tide	Range of Sus	pended Solid (mo	g/L) Mid- Flood Tide
IS5	8.1	to	25.7	7	to	23.7


The measured value at station IS5 was slightly above the range of suspended solid during baseline monitoring for the mid-ebb tide. However, there was no specific activities recorded during the monitoring period that would cause any significant impacts on the monitoring results.

3. No leakage of turbid water or any abnormity or malpractice was observed during the sampling exercise.

As such, the suspended solid levels recorded at this station are considered to be attributed to other external factors rather than the contract works.

Actions taken/ to be taken:

As the suspended solid levels recorded beyond the water quality criteria were not related to contract works, no immediate actions are considered necessary.



Reviewed by : Claudine Lee Title : ET Leader

Date: 10 February 2015

Summary of Notifications of Summons and Prosecutions

Total No. of Notifications of Summons / Prosecutions Received	No. of Notifications of Summons / Prosecutions Received during Reporting Period	Status of Notifications of Summons / Prosecutions
0	0	N/A