Appendix L

Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

 Table L1
 Cumulative Statistics on Exceedances

Parameters	Level of Exceedance	Total No. recorded in this reporting month	Total No. recorded since Contract commencement
1-hr TSP	Action	5	101
	Limit	3	11
24-hr TSP	Action	0	10
	Limit	0	4
Water Quality	Action	1	167
	Limit	0	19
Impact Dolphin	Action	0	11
Monitoring	Limit	1	17

Table L2 Cumulative Statistics on Complaints, Notifications of Summons and Successful Prosecutions

Reporting Period	Cumulative Statistics						
	Complaints	Notifications of	Successful				
		Summons	Prosecutions				
This Reporting Month (November 2019)	0	0	0				
Total No. received since Contract commencement	17	1	0				

Email message

Environmental Resources Management

To Ramboll Hong Kong, Limited (ENPO)

2507, 25/F One Harbourfront 18 Tak Fung Street Hunghom, Kowloon

Hong Kong

From ERM- Hong Kong, Limited

Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660

Ref/Contract number Contract No. HY/2012/08 Tuen Mun-Chek Lap

Kok Link-Northern Connection Sub-sea Tunnel

Section

Subject Notification of Exceedance for Air Quality

Impact Monitoring

Date 18 November 2019



Dear Sir or Madam,

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

0212330_4November2019_1hrTSP_Station ASR1 0212330_4November2019_1hrTSP_Station ASR5

One Action Level and One Limit Level Exceedances were recorded on 4 November 2019.

Regards,

Dr Jasmine Ng

Environmental Team Leader

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us.



CONTRACT NO. HY/2012/08 TUEN MUN - CHEK LAP KOK LINK NORTHERN CONNECTION SUB-SEA TUNNEL SECTION


Air Quality Impact Monitoring Notification of Exceedance

Log No.		Action Level Exceedance				
Ü	0212330	4November2019_1hrTSP_Station ASR5				
		Limit Level Exceedance				
	0212330	_4November2019_1hrTSP_Station ASR1				
		[Total No. of Exceedances = 2]				
Date		4 November 2019 (Measured)				
	14 Novemb	er 2019 (Laboratory results received by ERM)				
Monitoring Station	AS	R1, ASR5, ASR6, ASR10 and AQMS1				
Parameter(s) with Exceedance(s)		1-hr TSP				
Action Levels	24-hr TSP (μg/m³)	ASR1 = 213				
		ASR5 = 238				
		AQMS1 = 213				
		ASR6 = 238				
		ASR10 = 214				
	1-hr TSP (μg/m³)	ASR1 = 331				
		ASR5 = 340				
		AQMS1 = 335				
		ASR6 = 338				
		ASR10 = 337				
Limit Levels	1-hr TSP (μg/m³)	500				
	24-hr TSP (μg/m³)	260				
Measured Levels	Action Level Exceedance for 1-hr	TSP is observed at ASR5 (398 µg/m3) during 0826 - 0926 hrs.				
	Limit Level Exceedance for 1-hr TSP is observed at ASR1 (626 µg/m3) during 0839 - 0939 hrs.					
Works Undertaken (at	On 4 November 2019, Road and D	Orainage Works were carried out on site.				
the time of monitoring event)						

Possible Reason for	The exceedance is unlikely to be due to this Contract, in view of the following:
Action or Limit Level	According to the construction information provided by the Contractor, only Road and
Exceedance(s)	Drainage Works were carried out on site on 4 November 2019.
Actions Taken/To Be Taken	 The exceedance is unlikely to be due to this Contract as dust suppression measures were implemented properly on site. Water spraying was applied on site to prevent dust. Water spraying was also applied on exposed soil within the Contract site and associated works areas. With reference to the recorded wind direction (ranged between 14° and 16°, blowing from a north-easterly direction) and wind speed (2.2 m/s) during the works period, Stations ASR1 are located downstream to the construction works at Portion N-A. However, only Road & Drainage Works was carried out at Portion N-A on 4 November 2019, Stations ASR1 are located downstream to the construction works at Portion N-A during the 1-hour TSP monitoring. However, with similar wind speed and wind direction in the 2nd and 3rd hour, the exceedance was only recorded in the 1st hour of 1-hour TSP monitoring with the same construction works and dust mitigation measures being carried out. Road & Drainage Works carried out at Portion N-A are unlikely to cause significant dust impact. Stations ASR5 are located upstream to the construction works at Portion N-A during the recorded exceedance. Therefore, the exceedance is unlikely to be related to this Contract. Based on the above, the exceedance is unlikely to be due to this Contract. The Contractor has been reminded to implement the required mitigation measures as per the EP, approved EIA and Updated EM&A Manual including watering to maintain all exposed road surfaces and dust sources wet, use of sprinklers for water spraying, covering the materials having the potential to create dust by clean tarpaulin, use of water truck and watering on all exposed soil
	within the Contract site throughout the construction period.
Remarks	The monitoring results, wind data and the locations of air quality monitoring stations are attached.

Air quality monitoring results on 4/11/2019										
Project	Contract	Date	Station	Weather	Start time	Parameters	Results	Unit		
TMCLKL	HY/2012/08	2019-11-04	AQMS1	Sunny	8:50	1-hour TSP	154	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	AQMS1	Sunny	9:52	1-hour TSP	147	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	AQMS1	Sunny	10:54	1-hour TSP	143	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR1	Sunny	8:39	1-hour TSP	626	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR1	Sunny	9:41	1-hour TSP	264	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR1	Sunny	10:43	1-hour TSP	251	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR10	Sunny	8:02	1-hour TSP	117	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR10	Sunny	9:04	1-hour TSP	83	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR10	Sunny	10:06	1-hour TSP	105	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR5	Sunny	8:26	1-hour TSP	398	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR5	Sunny	9:28	1-hour TSP	251	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR5	Sunny	10:30	1-hour TSP	242	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR6	Sunny	8:14	1-hour TSP	202	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR6	Sunny	9:16	1-hour TSP	174	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR6	Sunny	10:18	1-hour TSP	169	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	AQMS1	Sunny	11:56	24-hour TSP	80	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR1	Sunny	11:45	24-hour TSP	141	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR10	Sunny	11:08	24-hour TSP	70	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR5	Sunny	11:32	24-hour TSP	146	ug/m3		
TMCLKL	HY/2012/08	2019-11-04	ASR6	Sunny	11:20	24-hour TSP	106	ug/m3		

Meteorological Data for Impact Monitoring in the reporting period							
Date (yy-mm-dd)	Time (24hrs)	Average of Wind Speed (m/s)	Average of Wind Direction(degree)				
19/11/04	0:00	1.3	342				
19/11/04	1:00	1.8	17				
19/11/04	2:00	2.7	341				
19/11/04	3:00	3.1	359				
19/11/04	4:00	3.6	3				
19/11/04	5:00	3.6	4				
19/11/04	6:00	1.8	14				
19/11/04	7:00	1.3	342				
19/11/04	8:00	2.2	16				
19/11/04	9:00	2.2	14				
19/11/04	10:00	1.8	12				
19/11/04	11:00	2.2	30				
19/11/04	12:00	1.8	23				
19/11/04	13:00	1.8	16				
19/11/04	14:00	1.3	18				
19/11/04	15:00	1.3	25				
19/11/04	16:00	1.8	347				
19/11/04	17:00	1.8	332				
19/11/04	18:00	1.8	313				
19/11/04	19:00	0.9	326				
19/11/04	20:00	0.4	324				
19/11/04	21:00	0.4	320				
19/11/04	22:00	0.9	328				
19/11/04	23:00	1.8	343				





Contract No. HY/2012/08 Tuen Mun – Chek Lap Kok Link Northern Connection Sub-sea Tunnel Section

Weekly Water Spraying Record 每週灌水檢查記錄

Sit		登位置: 月:	Northern Landfall					2019		
	<u>Time</u> 時間	Monday 星期一	<u>Tuesday</u> 星期二	Wednesday 星期三	Thursday 星期四	Friday 星期五	Saturday 星期六	Sunday 星期日		
1	8:00 - 8:45	/	/	/		7				
2	8:45 - 9:30	V.	V	V	/	1	1	1		
3	9:30 - 10:15	1	1/1	1	V	V				
4	10:15 - 11:00	V.		V.			/	1		
5	11:00 - 11:45		1/,		/		/			
6	11:45 - 12:30		1			/	V	1/		
7	12:30 - 13:15	<i>\cdot\cdot\cdot\cdot\cdot\cdot\cdot\cdot</i>		<i>Y.</i>		$\sqrt{}$	/	1		
8	13:15 - 14:00		1/		1/1		/			
9	14:00 - 14:45		/	<u> </u>	V,	1	/	1		
10	14:45 – 15:30		$\sqrt{}$			V	/	1		
11	15:30 – 16:45	V.	/			1	V			
12	16:45 – 17:30		V	/	/	1/		1		
	Verified by Site Foreman 地盤科文簽署確認	7	7	F	7	7	F	7		
Nigi	Night shift 夜間工作 (if necessary 如需要)									
	17:30 – 19:00									
	19:00 – 20:30									
	20:30 – 22:00									
	22:00 – 23:00									

*Please -

tick $(\sqrt{})$ in the box if complete the spraying of water. circle (O) in the box if it is raining.

*如果 - 已經完成灑水,請於方格內加上剔號(√)。 是下兩天, 請於方格內加上圓圈(O)。

Remarks:

- (1) Pursuant to EP Clause 3.15, the Permit Holder shall undertake watering at least 12 times per day on all exposed soil within the Project site and associated work areas in Tuen Mun area throughout the construction phase.
- (2) Spraying position includes the main haul road, open area, slopes, stockpiles and any other dusty materials.
- (3) If it is raining, no water spraying is needed.
- (4) The no of spraying will be increased due to site condition.

備註:

- (1) 根據環境許可證 3. 15 條例,在整個施工階段內,許可證持有人須每天至少 12 次在屯門區項目工地和 相關的工作區域內的所有暴露土壤灑水。
- (2) 灑水位置包括主要運輸道路,空曠地帶,斜坡,存料堆,以及任何其他產生塵埃物料。
- (3) 當下兩時, 地盤將不需要灑水。
- (4) 如果地盤情況更改或有需要時,灑水次數會相應增加。

Email message **Environmental** Resources Management

To Ramboll Hong Kong, Limited (ENPO) 2507, 25/F One Harbourfront

18 Tak Fung Street Hunghom, Kowloon

Hong Kong

Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660

From ERM- Hong Kong, Limited

Contract No. HY/2012/08 Tuen Mun-Chek Lap

Kok Link-Northern Connection Sub-sea Tunnel

Section

Subject Notification of Exceedance for Air Quality

Impact Monitoring

Date 19 November 2019



Dear Sir or Madam,

Ref/Project number

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

0212330_7November2019_1hrTSP_Station ASR5

One Action Level Exceedance was recorded on 7 November 2019.

Regards,

Dr Jasmine Ng

Environmental Team Leader

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us.



CONTRACT NO. HY/2012/08 TUEN MUN – CHEK LAP KOK LINK – NORTHERN CONNECTION SUB-SEA TUNNEL SECTION


Air Quality Impact Monitoring Notification of Exceedance

Log No.	Action Level Exceedance							
	0212330_7November2019_1hrTSP_Station ASR5							
		[Total No. of Exceedances = 1]						
Date		7 November 2019 (Measured)						
	19 Novem	ber 2019 (Laboratory results received by ERM)						
Monitoring Station	A	SR1, ASR5, ASR6, ASR10 and AQMS1						
Parameter(s) with		1-hr TSP						
Exceedance(s)								
Action Levels	24-hr TSP (μg/m³)	ASR1 = 213						
		ASR5 = 238						
		AQMS1 = 213						
		ASR6 = 238						
		ASR10 = 214						
	1-hr TSP (μg/m³)	ASR1 = 331						
		ASR5 = 340						
		AQMS1 = 335						
		ASR6 = 338						
		ASR10 = 337						
Limit Levels	1-hr TSP (μg/m³)	500						
	24-hr TSP (μg/m³)	260						
Measured Levels	Action Level Exceedance for 1-h	r TSP is observed at ASR5 (479 μg/m3) during 1324- 1424hrs.						
Works Undertaken (at	On 7 November 2019, Road and	Drainage Works were carried out on site.						
the time of monitoring								
event)								
Possible Reason for	The exceedance is unlikely to be	due to this Contract, in view of the following:						
Action or Limit Level	According to the construction	ction information provided by the Contractor, only Road and						
Exceedance(s)	Drainage Works were car	rried out on site on 7 November 2019.						
	The exceedance is unlikely	ly to be due to this Contract as dust suppression measures were						
	implemented properly or	n site. Water spraying was applied on site to prevent dust. Water						
	spraying was also applied	d on exposed soil within the Project site and associated works areas.						
	With reference to the reco	orded wind direction (ranged between 16° and 304°, blowing from a						
		resterly direction) and wind speed (1.8 - 2.2 m/s) during the works						
	1	e located upstream to the construction works at Portion N-A.						
	Therefore, the exceedance	e is unlikely to be related to this Contract.						
		nce is unlikely to be due to this Contract.						
Actions Taken / To Be		ed to implement the required mitigation measures as per the EP,						
Taken		&A Manual including watering to maintain all exposed road						
	1	se of sprinklers for water spraying, covering the materials having						
		ean tarpaulin, use of water truck and watering on all exposed soil						
	within the Project site throughou							
	,	•						

Remarks	The monitoring results, wind data, water spraying record and the locations of air quality monitoring
	stations are attached.

Project	Contract	Date	Station	Weather	Start time	Parameters	Results	Unit
TMCLKL	HY/2012/08	2019-11-07	AQMS1	Sunny	13:46	1-hour TSP	85	ug/m3
TMCLKL	HY/2012/08	2019-11-07	AQMS1	Sunny	14:48	1-hour TSP	66	ug/m3
TMCLKL	HY/2012/08	2019-11-07	AQMS1	Sunny	15:50	1-hour TSP	72	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR1	Sunny	13:35	1-hour TSP	239	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR1	Sunny	14:37	1-hour TSP	180	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR1	Sunny	15:39	1-hour TSP	160	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR10	Sunny	13:01	1-hour TSP	93	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR10	Sunny	14:03	1-hour TSP	55	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR10	Sunny	15:05	1-hour TSP	53	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR5	Sunny	13:24	1-hour TSP	479	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR5	Sunny	14:26	1-hour TSP	161	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR5	Sunny	15:28	1-hour TSP	147	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR6	Sunny	13:13	1-hour TSP	212	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR6	Sunny	14:15	1-hour TSP	117	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR6	Sunny	15:17	1-hour TSP	85	ug/m3
TMCLKL	HY/2012/08	2019-11-07	AQMS1	Sunny	16:52	24-hour TSP	86	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR1	Sunny	16:41	24-hour TSP	158	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR10	Sunny	16:07	24-hour TSP	66	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR5	Sunny	16:30	24-hour TSP	196	ug/m3
TMCLKL	HY/2012/08	2019-11-07	ASR6	Sunny	16:19	24-hour TSP	105	ug/m3

	Meteorological Data for Impact Monitoring in the reporting period							
Date (yy-mm-dd)	Time (24hrs)	Average of Wind Speed (m/s)	Average of Wind Direction(degree)					
19/11/07	0:00	0	-					
19/11/07	1:00	0	-					
19/11/07	2:00	0.4	22					
19/11/07	3:00	0.9	25					
19/11/07	4:00	1.8	32					
19/11/07	5:00	1.8	21					
19/11/07	6:00	1.3	22					
19/11/07	7:00	1.8	31					
19/11/07	8:00	1.8	15					
19/11/07	9:00	1.8	4					
19/11/07	10:00	2.2	33					
19/11/07	11:00	2.2	33					
19/11/07	12:00	2.2	16					
19/11/07	13:00	1.8	16					
19/11/07	14:00	2.2	304					
19/11/07	15:00	2.7	316					
19/11/07	16:00	1.3	341					
19/11/07	17:00	1.8	316					
19/11/07	18:00	1.8	327					
19/11/07	19:00	0.4	318					
19/11/07	20:00	0	-					
19/11/07	21:00	0.4	336					
19/11/07	22:00	1.3	313					
19/11/07	23:00	1.8	357					





Contract No. HY/2012/08 Tuen Mun – Chek Lap Kok Link Northern Connection Sub-sea Tunnel Section

Weekly Water Spraying Record 每週灌水檢查記錄

Sit		登位置: 月:	Northern Landfall					2019		
	<u>Time</u> 時間	Monday 星期一	<u>Tuesday</u> 星期二	Wednesday 星期三	Thursday 星期四	Friday 星期五	Saturday 星期六	Sunday 星期日		
1	8:00 - 8:45	/	/	/		7				
2	8:45 - 9:30	V.	V	V	/	1	1	1		
3	9:30 - 10:15	1	1/1	1	V	V				
4	10:15 - 11:00	V.		V.			/	1		
5	11:00 - 11:45		1/,		/		/			
6	11:45 - 12:30		1			/	V	1/		
7	12:30 - 13:15	<i>\cdot\cdot\cdot\cdot\cdot\cdot\cdot\cdot</i>		<i>Y.</i>		$\sqrt{}$	1	1		
8	13:15 - 14:00		1/		1/1		/			
9	14:00 - 14:45		/	<u> </u>	V,	1	/	1		
10	14:45 – 15:30		$\sqrt{}$			V	/	1		
11	15:30 – 16:45	V.	/			1	V			
12	16:45 – 17:30		V	/	/	1/		1		
	Verified by Site Foreman 地盤科文簽署確認	7	7	F	7	7	F	7		
Nigi	Night shift 夜間工作 (if necessary 如需要)									
	17:30 – 19:00									
	19:00 – 20:30									
	20:30 – 22:00									
	22:00 – 23:00									

*Please -

tick $(\sqrt{})$ in the box if complete the spraying of water. circle (O) in the box if it is raining.

*如果 - 已經完成灑水,請於方格內加上剔號(√)。 是下兩天, 請於方格內加上圓圈(O)。

Remarks:

- (1) Pursuant to EP Clause 3.15, the Permit Holder shall undertake watering at least 12 times per day on all exposed soil within the Project site and associated work areas in Tuen Mun area throughout the construction phase.
- (2) Spraying position includes the main haul road, open area, slopes, stockpiles and any other dusty materials.
- (3) If it is raining, no water spraying is needed.
- (4) The no of spraying will be increased due to site condition.

備註:

- (1) 根據環境許可證 3. 15 條例,在整個施工階段內,許可證持有人須每天至少 12 次在屯門區項目工地和 相關的工作區域內的所有暴露土壤灑水。
- (2) 灑水位置包括主要運輸道路,空曠地帶,斜坡,存料堆,以及任何其他產生塵埃物料。
- (3) 當下兩時, 地盤將不需要灑水。
- (4) 如果地盤情況更改或有需要時,灑水次數會相應增加。

Email message

Environmental Resources Management

To Ramboll Hong Kong, Limited (ENPO)

2507, 25/F One Harbourfront 18 Tak Fung Street Hunghom, Kowloon

Hong Kong

From ERM- Hong Kong, Limited

Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660

Ref/Contract number Contract No. HY/2012/08 Tuen Mun-Chek Lap

Kok Link-Northern Connection Sub-sea Tunnel

Section

Subject Notification of Exceedance for Air Quality

Impact Monitoring

Date 4 December 2019



Dear Sir or Madam,

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

0212330_28November2019_1hrTSP_Station ASR1

0212330 28November2019 1hrTSP Station ASR1

0212330_28November2019_1hrTSP_Station ASR1

 $0212330_28 November 2019_1 hr TSP_Station~ASR5$

0212330_28November2019_1hrTSP_Station ASR5

Two Limit Level and Three Action Level Exceedances were recorded on 28 November 2019.

Regards,

Dr Jasmine Ng

Environmental Team Leader

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us.



CONTRACT NO. HY/2012/08 TUEN MUN – CHEK LAP KOK LINK – NORTHERN CONNECTION SUB-SEA TUNNEL SECTION

Air Quality Impact Monitoring Notification of Exceedance

Log No.		Action Level Exceedance								
Log No.	0212220	28November2019_1hrTSP_Station ASR1								
		28November2019_1hrTSP_Station ASR1								
	0212330_28November2019_1hrTSP_Station ASR5									
	Limit Level Exceedance									
	0212330_28November2019_1hrTSP_Station ASR1									
	0212330_28November2019_1hrTSP_Station ASR5 [Total No. of Exceedances = 5]									
Date		28 November 2019 (Measured)								
	4 December 2019 (Laboratory results received by ERM)									
Monitoring Station	AS	R1, ASR5, ASR6, ASR10 and AQMS1								
Parameter(s) with		1-hr TSP								
Exceedance(s)										
Action Levels	24-hr TSP (μg/m³)	ASR1 = 213								
		ASR5 = 238								
		AQMS1 = 213								
		ASR6 = 238								
		ASR10 = 214								
	1-hr TSP (μg/m³)	ASR1 = 331								
		ASR5 = 340								
		AQMS1 = 335								
		ASR6 = 338								
		ASR10 = 337								
Limit Levels	1-hr TSP (μg/m³)	500								
	24-hr TSP (μg/m³)	260								
Measured Levels	Action Level Exceedance for 1-hr	TSP is observed at ASR1 (452 μg/m³) during 0940- 1040hrs.								
	Action Level Exceedance for 1-hr TSP is observed at ASR1 (385 µg/m³) during 1042- 1142hrs.									
	Action Level Exceedance for 1-hr TSP is observed at ASR5 (500 μg/m³) during 0927- 1027hrs.									
	Limit Level Exceedance for 1-hr TSP is observed at ASR1 (577 µg/m³) during 0838- 0938hrs.									
	Limit Level Exceedance for 1-hr TSP is observed at ASR5 (534 µg/m³) during 0802- 0902hrs.									
Works Undertaken (at	On 28 November 2019, Road and	Drainage Works were carried out on site.								
the time of monitoring										
event)										

Possible Reason for	The exceedance is unlikely to be due to this Contract, in view of the following:
Action or Limit Level	According to the construction information provided by the Contractor, only Road and
Exceedance(s)	Drainage Works were carried out on site on 28 November 2019.
	 The exceedance is unlikely to be due to this Contract as dust suppression measures were implemented properly on site. Water spraying was applied on site to prevent dust. Water spraying was also applied on exposed soil within the Contract site and associated works areas. Photo record is provided. With reference to the recorded wind direction (ranged between 14° and 34°, blowing from a north-easterly direction) and wind speed (2.2 - 2.7 m/s) during the works period, Stations ASR5 are located upstream to the construction works at Portion N-A. Stations ASR1 are located downstream to the construction works at Portion N-A. However, Road & Drainage Works carried out at Portion N-A with implementation of dust mitigation measures are unlikely to cause significant dust impact. Based on the above, the exceedance is unlikely to be due to this Contract.
Actions Taken / To Be	The Contractor has been reminded to implement the required mitigation measures as per the EP,
Taken	approved EIA and Updated EM&A Manual including watering to maintain all exposed road
	surfaces and dust sources wet, use of sprinklers for water spraying, covering the materials having
	the potential to create dust by clean tarpaulin, use of water truck and watering on all exposed soil
	within the Contract site throughout the construction period.
Remarks	The monitoring results, wind data and the locations of air quality monitoring stations are attached.



Annex A Photos provided by the Contractor

*Note: Photos taken on 28/11/2019



Water truck was used for water spraying to prevent dust. (Works Area Portion N-A)



Water spraying was applied on main haul road to prevent dust. (Works Area Portion N-A)



Annex A Photos provided by the Contractor

*Note: Photos taken on 28/11/2019




Exposed soi is covered by tarpaulin sheet to prevent dust. (Works Area Portion N-C)



Water spraying was applied on main haul road to prevent dust. (Works Area Portion N-C)

	Meto	eorological Data for Impact Monitoring in	n the reporting period
Date (yy-mm-dd)	Time (24hrs)	Average of Wind Speed (m/s)	Average of Wind Direction(degree)
19/11/28	0:00	0	-
19/11/28	1:00	0.4	346
19/11/28	2:00	1.8	2
19/11/28	3:00	2.2	331
19/11/28	4:00	0.9	20
19/11/28	5:00	1.3	341
19/11/28	6:00	1.3	339
19/11/28	7:00	1.3	357
19/11/28	8:00	2.2	24
19/11/28	9:00	2.7	14
19/11/28	10:00	2.2	34
19/11/28	11:00	1.8	344
19/11/28	12:00	1.8	311
19/11/28	13:00	1.8	310
19/11/28	14:00	1.8	336
19/11/28	15:00	1.3	341
19/11/28	16:00	1.8	337
19/11/28	17:00	1.3	340
19/11/28	18:00	1.8	338
19/11/28	19:00	1.8	335
19/11/28	20:00	2.2	3
19/11/28	21:00	2.2	20
19/11/28	22:00	2.7	24
19/11/28	23:00	2.2	30

Project	Contract	Date	Station	Weather	Start time	Parameters	Results	Unit
TMCLKL	HY/2012/08	2019-11-28	AQMS1	Sunny	8:49	1-hour TSP	187	ug/m3
TMCLKL	HY/2012/08	2019-11-28	AQMS1	Sunny	9:51	1-hour TSP	161	ug/m3
TMCLKL	HY/2012/08	2019-11-28	AQMS1	Sunny	10:53	1-hour TSP	143	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR1	Sunny	8:38	1-hour TSP	577	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR1	Sunny	9:40	1-hour TSP	452	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR1	Sunny	10:42	1-hour TSP	385	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR10	Sunny	8:00	1-hour TSP	125	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR10	Sunny	9:02	1-hour TSP	139	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR10	Sunny	10:04	1-hour TSP	143	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR5	Sunny	8:02	1-hour TSP	534	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR5	Sunny	9:27	1-hour TSP	500	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR5	Sunny	10:29	1-hour TSP	299	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR6	Sunny	8:13	1-hour TSP	216	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR6	Sunny	9:15	1-hour TSP	183	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR6	Sunny	10:17	1-hour TSP	175	ug/m3
TMCLKL	HY/2012/08	2019-11-28	AQMS1	Sunny	11:55	24-hour TSP	96	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR1	Sunny	11:44	24-hour TSP	207	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR10	Sunny	11:06	24-hour TSP	71	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR5	Sunny	11:31	24-hour TSP	131	ug/m3
TMCLKL	HY/2012/08	2019-11-28	ASR6	Sunny	11:19	24-hour TSP	109	ug/m3





Contract No. HY/2012/08 Tuen Mun – Chek Lap Kok Link Northern Connection Sub-sea Tunnel Section

Weekly Water Spraying Record 每週灑水檢查記錄

Site Location 地盤位置:Northern Landfall Date 日期:Z5 Nov Z019 to 至 0/ Dec Z019											
	Time 時間	Monday 星期一	<u>Tuesday</u> 星期二	Wednesday 星期三	Thursday 星期四	<u>Friday</u> 星期五	Saturday 星期六	Sunday 星期日			
1	8:00 - 8:45						/				
2	8:45 - 9:30	$\sqrt{}$	\sim	$\sqrt{}$	V.	\		V			
3	9:30 - 10:15	$\sqrt{}$	\checkmark	$\sqrt{}$		$\sqrt{}$	V.	V			
4	10:15 - 11:00	$\sqrt{}$	\checkmark		$\sqrt{}$						
5	11:00 - 11:45		\checkmark		√.	/	\checkmark	V			
6	11:45 - 12:30	V		\checkmark	\checkmark	$\sqrt{}$	V	1			
7	12:30 - 13:15	\checkmark	\checkmark	V	\checkmark	/	V	V			
8	13:15 - 14:00	\checkmark	\checkmark		V	$\sqrt{}$	$\sqrt{}$	V			
9	14:00 - 14:45	V	V	✓	$\sqrt{}$	V		V			
10	14:45 – 15:30	V	\checkmark	\checkmark		V.	$\sqrt{}$	$\overline{}$			
11	15:30 – 16:45	V	\checkmark	$\sqrt{}$	V		V	V			
12	16:45 – 17:30	V	$\sqrt{}$	\checkmark	\/			1/			
	Verified by Site Foreman 地盤科文簽署確認	7	7	7	7	7	7	7			
Nigh	nt shift 夜間工作 (i	f necessary	如需要)								

17:30 – 19:00		
19:00 - 20:30		
20:30 - 22:00		
22:00 - 23:00		

*Please -

tick $(\sqrt{})$ in the box if complete the spraying of water. circle (O) in the box if it is raining.

*如果 - 已經完成灑水,請於方格內加上剔號(√)。 是下兩天, 請於方格內加上圓圈(O)。

Remarks:

- (1) Pursuant to EP Clause 3.15, the Permit Holder shall undertake watering at least 12 times per day on all exposed soil within the Project site and associated work areas in Tuen Mun area throughout the construction phase.
- (2) Spraying position includes the main haul road, open area, slopes, stockpiles and any other dusty materials.
- (3) If it is raining, no water spraying is needed.
- (4) The no of spraying will be increased due to site condition.

備註:

- (1) 根據環境許可證 3.15 條例,在整個施工階段內,許可證持有人須每天至少 12 次在屯門區項目工地和 相關的工作區域內的所有暴露土壤灑水。
- (2) 灑水位置包括主要運輸道路,空曠地帶,斜坡,存料堆,以及任何其他產生塵埃物料。
- (3) 當下雨時, 地盤將不需要灑水。
- (4) 如果地盤情況更改或有需要時,灑水次數會相應增加。

Email message Environmental Resources Management

To Ramboll Hong Kong Limited (ENPO)

2507,

From

Subject

Date

ERM- Hong Kong, Limited

25/F One Harbourfront, 18 Tak Fung Street, Hung Hom, Hong Kong Telephone: (852) 2271 3113 Facsimile: (852) 2723 5660

E-mail: jasmine.ng@erm.com

Ref/Project number

Contract No. HY/2012/08 Tuen Mun-Chek Lap

Kok Link-Northern Connection Sub-sea Tunnel

Section

Notification of Exceedance for Water Quality

Impact Monitoring

19 November 2019

ERM

Dear Sir or Madam,

Please find the Notification of Exceedance (NOE) of the following Log no.: Action Level Exceedance

0212330_1 November 2019_ Depth_averaged SS_E_Station IS(Mf)16

A total of one Action Level exceedance was recorded on 1 November 2019.

Regards,

Dr Jasmine Ng

Environmental Team Leader

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us.



CONTRACT NO. HY/2012/08 TUEN MUN - CHEK LAP KOK LINK NORTHERN CONNECTION SUB-SEA TUNNEL SECTION

Marine Water Quality Impact Monitoring Notification of Exceedance

Date 1 November 2019 Depth_averaged SS_E_Station IS(Mf)16 [Total No. of Exceedances = 1]	Log No.	Action Level Exceedance									
Date	2081101										
Date 1 November 2019 (Measured) 4 November 2019 (In situ results received by ERM) 12 November 2019 (Laboratory results received by ERM) Station CS(Mf)5, SR4a, SR4(N2), IS8(N), IS(Mf)16, IS(Mf)9, CS(Mf)3(N), SR7, IS17, IS(Mf)11 Station Parameter(s) with Exceedance(s) Action Levels SS 120% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 23.5 mg/L Measured Levels Action Level Exceedance Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) According to the information provided by the Contractor, no marine works was carried out on 1 November 2019. The exceedances are unlikely to be due to the Contract, in view of the following: - All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Level during both mid-ebb and mid-flood tides on the same day. - As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. - As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.											
### A November 2019 (In situ results received by ERM) 12 November 2019 (Laboratory results received by ERM) **CS(Mf)5, SR4a, SR4(N2), IS8(N), IS(Mf)16, IS(Mf)9, CS(Mf)3(N), SR7, IS17, IS(Mf)11 **Station** **Parameter(s) with Exceedance(s) **Action** **Levels** **Action** **Levels** **Description** **Action** **Levels** **Action** **Levels** **Action** **Levels** **Action** **Levels** **Action** **Levels** **Action** **Levels** **Action** **Level** **Action** **An Immonitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. **As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. **As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded.** **Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract. **According** **According** **According** **Description** **Descript											
Monitoring Station Scaling CS(Mf)5, SR4a, SR4(N2), IS8(N), IS(Mf)16, IS(Mf)9, CS(Mf)3(N), SR7, IS17, IS(Mf)11 Suspended solids (mg/L) Suspende	Date										
Monitoring Station CS(Mf)5, SR4a, SR4(N2), IS8(N), IS(Mf)16, IS(Mf)9, CS(Mf)3(N), SR7, IS17, IS(Mf)11											
Station Parameter(s) with Exceedance(s) Action Levels Ss 120% of upstream control station at the same tide of the same day and 95%-ile of baseline data, i.e., 23.5 mg/L Limit Levels SS 130% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 34.4 mg/L Measured Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged S5 = 24.8 mg/L) Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(Exceedance(S) The exceedances are unlikely to be due to the Contract, in view of the following: • All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. • As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.											
Parameter(s) with Exceedance(s) Action SS 120% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 23.5 mg/L Limit Levels SS 130% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 34.4 mg/L Measured Levels 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedances are unlikely to be due to the Contract, in view of the following: • All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. • As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Ŭ	g CS(Mf)5, SR4a, SR4(N2), IS8(N), IS(Mf)16, IS(Mf)9, CS(Mf)3(N), SR7, IS17, IS(I	Mf)11								
Suspended solids (mg/L)											
Exceedance(s) Action Levels SS 120% of upstream control station at the same tide of the same day and 95%-ile of baseline data, i.e., 23.5 mg/L Limit Levels SS 130% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 34.4 mg/L Measured Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) The exceedances are unlikely to be due to the Contract, in view of the following: • All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. • As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Parameter(s)										
Action Levels SS 120% of upstream control station at the same tide of the same day and 95%-ile of baseline data, i.e., 23.5 mg/L Limit Levels SS 130% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 34.4 mg/L Measured Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) The exceedances are unlikely to be due to the Contract, in view of the following: • All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. • As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.		Sucporded colids (mg/I)									
Action Levels SS 120% of upstream control station at the same tide of the same day and 95%-ile of baseline data, i.e., 23.5 mg/L 130% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline data, i.e., 34.4 mg/L Measured Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) According to the information provided by the Contractor, no marine works was carried out on 1 November 2019. Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedances are unlikely to be due to the Contract, in view of the following: • All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. • As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Exceedance(Suspended solids (Ilig/ L)									
Levels	s)										
Limit Levels SS 130% of upstream control station at the same tide of the same day and 10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseling data, i.e., 34.4 mg/L Measured Levels 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out to the Contract, in view of the following: • All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. • As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Action	SS 120% of upstream control station at the same tide	e of the same day and								
Measured Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) According to the information provided by the Contractor, no marine works was carried out on 1 November 2019. Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Levels	95%-ile of baseline data, i.e., 23.5	mg/L								
Measured Levels Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L)	Limit Levels	1									
Action Level Exceedance 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L)		10mg/L for WSD Seawater Intakes at Tuen Mun and 99%-ile of baseline									
Levels 1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L) Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no marine works was carried out on 1 November 2019. The exceedances are unlikely to be due to the Contract, in view of the following: All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.		data, i.e., 34.4 mg/L									
Works Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no marine works was carried out on 1 November 2019. The exceedances are unlikely to be due to the Contract, in view of the following: All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Measured	-									
Undertaken (at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Levels	1. Mid-ebb at IS(Mf)16 (Depth-averaged SS = 24.8 mg/L)									
(at the time of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Works	According to the information provided by the Contractor, no marine works was carried out on	1 November 2019.								
of monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Undertaken	en en									
monitoring event) Possible Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	(at the time	e									
Possible Reason for Action or Limit Level Exceedance(s) The exceedances are unlikely to be due to the Contract, in view of the following: All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	of										
Possible Reason for Action or Limit Level Exceedance(s) The exceedances are unlikely to be due to the Contract, in view of the following: All monitored parameters, except SS, at all monitoring stations were in compliance with the Action and Limit Levels during both mid-ebb and mid-flood tides on the same day. As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	monitoring	g									
 Reason for Action or Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract. 	event)										
Action or Limit Level Exceedance(s) Levels during both mid-ebb and mid-flood tides on the same day. As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Possible	The exceedances are unlikely to be due to the Contract, in view of the following:									
 Limit Level Exceedance(s) As no marine works was carried out on 1 November 2019, the exceedance is unlikely to be caused by the marine works of this Contract. As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract. 	Reason for	All monitored parameters, except SS, at all monitoring stations were in compliance with t	he Action and Limit								
Exceedance(s) As no infanite works was carried out of 1 November 2019, the exceedance is unlikely to be caused by the infanite works of this Contract. • As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Action or	Levels during both mid-ebb and mid-flood tides on the same day.									
 Exceedance(s) As reported by the Contractor, no discharge of organic matters into waters from landside works area was recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract. 		• As no marine works was carried out on 1 November 2019, the exceedance is unlikely to b	e caused by the marine								
recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	Exceedance(
recorded. Therefore, exceedance recorded at IS(Mf)16 during mid-ebb tide is unlikely to be caused by the marine works of this Contract.	s)	As reported by the Contractor, no discharge of organic matters into waters from landside	works area was								
marine works of this Contract.											
			Ť								
Actions No immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Actions	No immediate action is considered necessary. The ET will monitor for future trends in exceed	ances.								
Taken/To	Taken/To	·									
Be Taken	-										
Remarks The monitoring results on 1 November 2019 and locations of water quality monitoring stations are attached.	Remarks	The monitoring results on 1 November 2019 and locations of water quality monitoring stations	are attached.								

TMCLKL H		Date (yyyy-mm- dd)	Tide	Station	Start Time	Level	Lev_Cod	Replicate	Temperature (°C)	рН	Salinity (ppt)	DO (mg/L)	Average DO (mg/L)	Turbidity (NTU)	Depth- Averaged Turbidity	SS (mg/L)	Depth- Averaged SS
	HY/2012/08	2019-11-01	Mid-Ebb	CS(Mf)5	16:08	Surface	1	1	26.8	8.1	32.1	5.6		4.2		6.8	
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	CS(Mf)5	16:08	Surface	1	2	26.8	8.1	32.1	5.6	5.5	4.0]	6.4]
TMCLKL HY	HY/2012/08	2019-11-01	Mid-Ebb	CS(Mf)5	16:08	Middle	2	1	26.7	8.1	32.5	5.5] 3.3	5.7	5.5	6.6	6.9
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	CS(Mf)5	16:08	Middle	2	2	26.7	8.1	32.4	5.4		5.5] 3.3	6.4	
	HY/2012/08	2019-11-01	Mid-Ebb	CS(Mf)5	16:08	Bottom	3	1	26.7	8.1	32.6	5.5	5.5	6.7		7.4	_
	HY/2012/08		Mid-Ebb	CS(Mf)5	16:08	Bottom	3	2	26.7	8.1	32.6	5.5		6.6		7.5	
	HY/2012/08		Mid-Ebb	CS(Mf)3(N)	15:21	Surface	1	1	26.6	8.1	30.5	6.1	-	4.9		8.2	4
	HY/2012/08		Mid-Ebb	CS(Mf)3(N)	15:21	Surface	1	2	26.7	8.2	30.3	6.1	6.1	4.2		8.1	-
			Mid-Ebb	CS(Mf)3(N)	15:21	Middle Middle	2	1	26.3	8.1	31.6	6.2	-	9.3	8.1	9.7	9.8
	HY/2012/08 HY/2012/08		Mid-Ebb Mid-Ebb	CS(Mf)3(N) CS(Mf)3(N)	15:21 15:21	Bottom	3	2	26.4 26.3	8.2	31.4 31.8	6.1 6.3	 	8.5 10.9	1	8.6 12.4	-
	HY/2012/08		Mid-Ebb	CS(Mf)3(N)	15:21	Bottom	3	2	26.3	8.2	31.8	6.2	6.3	10.9		11.7	-
	HY/2012/08		Mid-Ebb	IS(Mf)16	14:38	Surface	1	1	26.6	8.1	31.6	6.0		8.6		23.1	
			Mid-Ebb	IS(Mf)16	14:38	Surface	1	2	26.7	8.2	31.6	6.0	1 1	8.6	1	23.3	-
	HY/2012/08		Mid-Ebb	IS(Mf)16	14:38	Middle	2	1	20.7	0.2	31.0	0.0	6.0	0.0	1	23.3	-
	HY/2012/08		Mid-Ebb	IS(Mf)16	14:38	Middle	2	2					1 1		9.2		24.8
	HY/2012/08	2019-11-01	Mid-Ebb	IS(Mf)16	14:38	Bottom	3	1	26.4	8.1	31.6	6.1	6.4	9.7	1	26.1	1
	HY/2012/08		Mid-Ebb	IS(Mf)16	14:38	Bottom	3	2	26.4	8.2	31.6	6.0	6.1	9.7	1	26.5	1
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	SR4a	14:28	Surface	1	1	26.6	8.1	31.5	5.9		6.4		11.5	
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	SR4a	14:28	Surface	1	2	26.6	8.2	31.5	5.9	5.9	5.9	1	11.7	1
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	SR4a	14:28	Middle	2	1					3.9		7.4		10.2
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	SR4a	14:28	Middle	2	2] /.4] 10.2
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	SR4a	14:28	Bottom	3	1	26.6	8.1	31.5	6.1	6.0	8.8		8.6	_
	HY/2012/08		Mid-Ebb	SR4a	14:28	Bottom	3	2	26.5	8.2	31.5	5.9	0.0	8.5		9.0	
	HY/2012/08		Mid-Ebb	SR4(N2)	14:24	Surface	1	1	26.8	8.1	31.4	6.0		4.9		5.3	_
	HY/2012/08		Mid-Ebb	SR4(N2)	14:24	Surface	1	2	26.8	8.2	31.4	6.0	6.0	4.8		5.9	4
			Mid-Ebb	SR4(N2)	14:24	Middle	2	1							5.0		7.4
	<u> </u>		Mid-Ebb	SR4(N2)	14:24	Middle	2	2	26.7	0.1	24.5	C 1	-	F 4	-	0.0	-
		2019-11-01	Mid-Ebb	SR4(N2)	14:24	Bottom	3	1	26.7	8.1	31.5	6.1 6.1	6.1	5.1	1	9.0 9.5	-
			Mid-Ebb Mid-Ebb	SR4(N2) IS8(N)	14:24 14:20	Bottom Surface	1	2 1	26.7 26.6	8.1	31.4 31.4	6.0	+	5.1 11.8		6.5	
-	HY/2012/08		Mid-Ebb	IS8(N)	14:20	Surface	1	2	26.6	8.2	31.4	5.9	 	11.5	1	6.8	-
-			Mid-Ebb	IS8(N)	14:20	Middle	2	1	20.0	0.2	31.4	3.3	6.0	11.5	1	0.0	1
	HY/2012/08		Mid-Ebb	IS8(N)	14:20	Middle	2	2					1 1		11.9		8.2
			Mid-Ebb	IS8(N)	14:20	Bottom	3	1	26.6	8.1	31.4	6.0		12.1		9.4	1
			Mid-Ebb	IS8(N)	14:20	Bottom	3	2	26.6	8.2	31.4	6.0	6.0	12.2	1	10.2	1
	HY/2012/08	2019-11-01	Mid-Ebb	IS(Mf)9	14:14	Surface	1	1	26.4	8.1	31.5	6.0		11.9		12.9	
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	IS(Mf)9	14:14	Surface	1	2	26.4	8.2	31.4	6.0	6.0	11.4	1	12.1	1
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	IS(Mf)9	14:14	Middle	2	1] 6.0		12.1		13.5
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	IS(Mf)9	14:14	Middle	2	2							12.1] 13.3
TMCLKL H	HY/2012/08	2019-11-01	Mid-Ebb	IS(Mf)9	14:14	Bottom	3	1	26.3	8.1	31.5	6.1	6.1	12.7		14.9]
TMCLKL H	HY/2012/08		Mid-Ebb	IS(Mf)9	14:14	Bottom	3	2	26.3	8.2	31.5	6.1	0.1	12.5		14.2	
			Mid-Ebb	IS(Mf)11	14:52	Surface	1	1	26.5	8.1	31.6	6.1		7.0		11.0	」
	HY/2012/08		Mid-Ebb	IS(Mf)11	14:52	Surface	1	2	26.7	8.2	31.6	6.1	6.0	5.6		10.6	」
			Mid-Ebb	IS(Mf)11	14:52	Surface	2	1	26.2	8.1	31.6	5.8		11.7	10.2	11.3	11.3
	HY/2012/08		Mid-Ebb	IS(Mf)11	14:52	Surface	2	2	26.2	8.2	31.6	5.8		10.6		11.4	-
	-		Mid-Ebb	IS(Mf)11	14:52	Surface	3	1	26.2	8.1	31.6	6.0	6.0	12.8		11.8	-
-	HY/2012/08		Mid-Ebb	IS(Mf)11	14:52	Surface	3	2	26.2	8.2	31.6	5.9	-	13.4		11.7	
	HY/2012/08		Mid-Ebb	SR7	15:47	Surface	1	2	26.7	8.1	31.8	6.0	 	5.7	-	10.0	-
-	HY/2012/08 HY/2012/08		Mid-Ebb Mid-Ebb	SR7 SR7	15:47 15:47	Surface Surface	2	2 1	26.7	8.2	31.7	6.0	6.0	5.1	1	9.8	- I
		-	Mid-Ebb	SR7	15:47	Surface	2	2					 		7.3		10.2
	HY/2012/08		Mid-Ebb	SR7	15:47	Surface	3	1	26.4	8.1	31.8	6.1		9.1	1	10.6	
	HY/2012/08		Mid-Ebb	SR7	15:47	Surface	3	2	26.5	8.2	31.8	6.0	6.1	9.1	1	10.3	1
	HY/2012/08	-	Mid-Ebb	IS17	14:44	Surface	1	1	26.8	8.1	31.8	5.9		4.2		5.1	+
	HY/2012/08		Mid-Ebb	IS17	14:44	Surface	1	2	26.9	8.2	31.8	5.9	† †	4.1	1	5.8	1
-			Mid-Ebb	IS17	14:44	Surface	2	1	26.4	8.1	31.7	5.9	5.9	5.7	1	6.4	1
	HY/2012/08			IS17	14:44	Surface	2	2	26.4	8.2	31.7	5.9	1 1	5.5	5.2	7.1	6.7

Project	Contract	Date (yyyy-mm dd)	1- Tide	Station	Start Time	Level	Lev_Cod	Replicate	Temperature (°C)	рН	Salinity (ppt)	DO (mg/L)	Average DO (mg/L)	Turbidity (NTU)	Depth- Averaged Turbidity	SS (mg/L)	Depth- Averaged SS
TMCLKL	HY/2012/08	2019-11-01	Mid-Ebb	IS17	14:44	Surface	3	1	26.4	8.1	31.7	6.1	6.1	5.9		7.6	
TMCLKL	HY/2012/08	2019-11-01	Mid-Ebb	IS17	14:44	Surface	3	2	26.4	8.2	31.7	6.1	0.1	5.9		8.1	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)5	9:14	Surface	1	1	26.3	8.2	31.8	5.8]	5.2		7.7	<u> </u>
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)5	9:14	Surface	1	2	26.3	8.0	31.8	5.8	5.8	5.1		7.9	_
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)5	9:14	Middle	2	1	26.3	8.1	31.8	5.8	4 - 1	10.4	8.7	7.4	7.7
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)5	9:14	Middle	2	2	26.3	8.0	31.8	5.8		10.5		7.8	-
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)5	9:14	Bottom	3	1	26.3	8.1	31.8	5.8	5.8	10.3	1	7.3	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)5	9:14	Bottom	3	2	26.3	8.0	31.8	5.8		10.7		7.9	
TMCLKL TMCLKL	HY/2012/08 HY/2012/08	2019-11-01 2019-11-01	Mid-flood Mid-flood	CS(Mf)3(N) CS(Mf)3(N)	10:07 10:07	Surface Surface	1 1	2	26.3 26.3	8.2	30.6 30.6	6.0 6.0	-{	5.3	•	7.4 7.1	-
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)3(N)	10:07	Middle	2	1	26.1	8.2	30.8	6.1	6.1	8.2	1	7.1	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)3(N)	10:07	Middle	2	2	26.2	8.1	30.8	6.1	†	7.5	8.0	7.3	7.3
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)3(N)	10:07	Bottom	3	1	26.1	8.2	30.9	6.1		11.0		7.5	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	CS(Mf)3(N)	10:07	Bottom	3	2	26.1	8.1	30.9	6.1	6.1	10.8	1	7.2	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)16	10:55	Surface	1	1	26.3	8.2	31.6	5.9		15.0		19.6	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)16	10:55	Surface	1	2	26.3	8.1	31.6	5.8	1 [14.8		19.9	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)16	10:55	Middle	2	1					5.9		15.1		22.0
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)16	10:55	Middle	2	2							15.1		22.0
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)16	10:55	Bottom	3	1	26.3	8.2	31.6	6.0	6.0	15.2]	24.4]
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)16	10:55	Bottom	3	2	26.3	8.1	31.6	6.0	0.0	15.5		24.2	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4a	11:05	Surface	1	1	26.3	8.2	31.5	5.7]	6.9		10.6	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4a	11:05	Surface	1	2	26.3	8.1	31.5	5.7	5.7	6.6		11.1	_
TMCLKL	HY/2012/08	2019-11-01	-	SR4a	11:05	Middle	2	1					4 .		7.1		11.1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4a	11:05	Middle	2	2	25.0	0.1							4
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4a	11:05	Bottom	3	1	26.3	8.1	31.6	5.9	5.9	7.5		11.5	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4a	11:05	Bottom	3	2	26.4	8.1	31.6	5.9		7.4		11.2	
TMCLKL TMCLKL	HY/2012/08 HY/2012/08	2019-11-01 2019-11-01		SR4(N2) SR4(N2)	11:10 11:10	Surface Surface	1	2	26.3 26.3	8.2	31.4 31.4	6.0 6.0	-	5.9 6.0		3.7	-
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4(N2)	11:10	Middle	2	1	20.3	0.1	51.4	6.0	6.0	6.0		5.7	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4(N2)	11:10	Middle	2	2					 		9.4		4.0
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4(N2)	11:10	Bottom	3	1	26.4	8.2	31.3	6.1		12.6	•	4.2	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR4(N2)	11:10	Bottom	3	2	26.4	8.1	31.3	6.1	6.1	12.9	1	4.4	1
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS8(N)	11:15	Surface	1	1	26.3	8.2	31.6	6.1		8.5		7.9	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS8(N)	11:15	Surface	1	2	26.3	8.1	31.6	6.0	1	8.2	1	7.4	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS8(N)	11:15	Middle	2	1					6.1		8.6		7.9
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS8(N)	11:15	Middle	2	2							0.0] /.9
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS8(N)	11:15	Bottom	3	1	26.3	8.2	31.6	6.2	6.2	8.7		8.3	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS8(N)	11:15	Bottom	3	2	26.3	8.2	31.6	6.2	0.2	8.8		7.9	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)9	11:23	Surface	1	1	26.3	8.2	31.6	5.9]	15.4		12.9	_
TMCLKL	HY/2012/08	2019-11-01		IS(Mf)9	11:23	Surface	1	2	26.3	8.1	31.6	5.9	5.9	14.7		13.3	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)9	11:23	Middle	2	1					4 .		16.8		13.3
TMCLKL	HY/2012/08	2019-11-01		IS(Mf)9	11:23	Middle	2	2									4
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)9	11:23	Bottom	3	1	26.3	8.2	31.7	6.1	6.1	18.5		13.1	4 l
TMCLKL	HY/2012/08	2019-11-01	Mid-flood Mid-flood	IS(Mf)9	11:23 10:38	Bottom Surface	3	2	26.3	8.1	31.7	6.0 5.0		18.4		13.7	
TMCLKL TMCLKL	HY/2012/08 HY/2012/08	2019-11-01 2019-11-01	Mid-flood	IS(Mf)11 IS(Mf)11	10:38	Surface	1 1	2	26.2 26.2	8.2	31.6 31.6	5.9 5.9	 	9.9 9.0		10.1 10.9	
TMCLKL	HY/2012/08 HY/2012/08	2019-11-01		IS(Mf)11	10:38	Surface	2	1	26.1	8.2	31.6	5.9	5.9	12.8		11.5	
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)11	10:38	Surface	2	2	26.1	8.1	31.6	5.9	1	12.7	12.7	11.7	11.2
TMCLKL	HY/2012/08	2019-11-01		IS(Mf)11	10:38	Surface	3	1	26.1	8.2	31.6	6.0		15.8		11.7	† l
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS(Mf)11	10:38	Surface	3	2	26.1	8.1	31.6	6.0	6.0	15.7	1	11.6	† l
TMCLKL	HY/2012/08	2019-11-01		SR7	9:40	Surface	1	1	26.1	8.2	31.6	6.2		10.0		9.6	
TMCLKL	HY/2012/08	2019-11-01		SR7	9:40	Surface	1	2	26.1	8.1	31.6	6.1	1 ,	9.9	1	9.9	1 l
TMCLKL	HY/2012/08	2019-11-01		SR7	9:40	Surface	2	1					6.2		10.0] 103
TMCLKL	HY/2012/08	2019-11-01		SR7	9:40	Surface	2	2					<u>] </u>		10.0		10.3
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	SR7	9:40	Surface	3	1	26.0	8.1	31.7	6.3	6.3	9.9]	10.9]
TMCLKL	HY/2012/08	2019-11-01		SR7	9:40	Surface	3	2	26.1	8.1	31.6	6.2	0.3	10.3		10.7	
TMCLKL	HY/2012/08	2019-11-01		IS17	10:47	Surface	1	1	26.2	8.2	31.7	5.9		5.0		6.4	1 7
	i e	2019-11-01	Mid-flood		10:47	Surface	1	2	26.2	8.1	31.7	5.9	6.0	5.0		6.3	<u> </u>
TMCLKL		2019-11-01		IS17	10:47	Surface	2	1	26.1	8.2	31.7	6.0		5.1	5.5	7.7	7.8
		2019-11-01		IS17	10:47	Surface	2	2	26.1	8.1	31.7	6.0		5.0		7.4	4
TMCLKL	<u> </u>	2019-11-01		IS17	10:47	Surface	3	1	26.1	8.2	31.7	6.2	6.2	6.2		9.6	4 l
TMCLKL	HY/2012/08	2019-11-01	Mid-flood	IS17	10:47	Surface	3	2	26.1	8.1	31.7	6.1		6.4		9.2	




Figure 1



