




Remark(*): The monitoring results in October and November 2018 for AMS2 are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.




Remark(*): Air Quality Monitoring at AMS3C has been undertaking by the ET for Contract No. HY/2013/04 since 20 August 2018. The monitoring results in October and November 2018 for AMS3C are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.




Remark(*): The monitoring results in October and November 2018 for AMS7B are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.




Remark(*): The monitoring results in October and November 2018 for AMS2 are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.




Remark: Air Quality Monitoring at AMS3C has been undertaking by the ET for Contract No. HY/2013/04 since 20 August 2018. The monitoring results in October and November 2018 for AMS3C are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.




Remark(*): The monitoring results in October and November 2018 for AMS7B are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.




Remark(*): The monitoring results in October and November 2018 for MNS2 are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.



Remark(*): Noise Monitoring at NMS3C has been undertaking by the ET for Contract No. HY/2013/04 since 20 August 2018. The monitoring results in October and November 2018 for MNS3C are reported in the monthly EM&A Reports prepared for Contract No. HY/2013/04.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.

(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.


(iii) There are construction activities of work bridge poor SPA(N), the water quality monitoring to an activities of work bridge poor SPA(N), the water quality monitoring to an activities at warm warm was a specific to an activities of work bridge poor SPA(N).


(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.






(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.
(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.
(iii) The results are statistically activities of wards bridge ages (SPA(N)) the water quality monitoring to 17 September 2018 was cancelled.


(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.





(III) There are construction activities of work bridge hear SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.

(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.


(iii) There are construction activities of work bridge poor SPA(N), the water quality monitoring to an activities of work bridge poor SPA(N), the water quality monitoring to an activities at warm warm was a specific to an activities of work bridge poor SPA(N).


(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.





(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.

(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.

(iii) There are construction activities of work bridge poor SPA(N), the water quality monitoring to an activities of work bridge poor SPA(N), the water quality monitoring to an activities at warm warm was a specific to an activities of work bridge poor SPA(N).

(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.

(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.


(iii) There are construction activities of work bridge poor SPA(N), the water quality monitoring to an activities of work bridge poor SPA(N), the water quality monitoring to an activities at warm warm was a specific to an activities of work bridge poor SPA(N).


(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.






(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.
(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.
(iii) The results are statistically activities of wards bridge ages (SPA(N)) the water quality monitoring to 17 September 2018 was cancelled.


(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.





(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







Notes:(i) Due to the typhoon signal was hoisted, the water quality monitoring (mid-ebb tide) on 12 September 2018 was cancelled.

(ii) Due to the typhoon signal was hoisted, the water quality monitoring on 17 September 2018 was cancelled.


(iii) There are construction activities of work bridge poor SPA(N), the water quality monitoring to an activities of work bridge poor SPA(N), the water quality monitoring to an activities at warm warm was a specific to an activities of work bridge poor SPA(N).


(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.







⁽iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.





(iii) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.





(III) There are construction activities of work bridge near SR4(N), the water quality monitoring team were unable to access station SR4(N) during September 2018 due to safety reason. The water quality monitoring for SR4(N) were conducted at the nearest location of SR4(N) as much as practical.