MATERIALAB CONSULTANTS LIMITED

Room 723 & 725, 7/F, Block B, Profit Industrial Building, 1-15 Kwai Fung Crescent, Kwai Fong, Hong Kong.

Tel : (852)-24508238 Fax : (852)-24508032 Email : mcl@fugro.com




Report No.: 0165/15/ED/1178


Figure 3

Water Quality Monitoring Stations

The copyright of this document is owned by MateriaLab Consultants Ltd. It may not be reproduced except with prior written approval from the Company.







SR5(N)

SR6 SR7

SRIDA

SR10B(N)

CS(Mf)3

CS(MF)3(N)

CS(MF)5

CS4

CSA

SR3 (N)

SR10A (N)

SR10B (N2)





FIGURE 4.1- LOCATION OF WATER QUALITY MONITORING STATIONS

SETTING OUT SCHEDULE

MON TOR ING STATIONS	CO-ORDINATES	
	EASTING	NORTHENG
155	811579	817106
15(M#)6	812101	817873
157	812244	818777
158	814251	818412
15(WF)9	813273	818850
IS10	812577	820670
IS10(N)	812942	820455
[\$(Wf)11	813562	820716
15(MF)16	814328	819497
1517	814539	820391
SR3 (N)	510659	516591
SR4(N)	814705	817859
SR5	811489	820455
SR5(N)	812569	821475
SR6	805837	821818
SR7	814293	821431
SRIDA (N)	523644	523454
SR10B (N2)	823689	523159
CS(NF)3	809989	821117
CS(MF)3(N)	806814	822355
CS(NF)5	817990	821129
C54	810025	824004
CS6	817028	823992
CSA	818103	823064