
Appendix F

Post-Construction Water Quality Monitoring Results and Graphical Presentation







Figure F1 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F2 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F3 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F4 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F5 Post-Construction Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F6 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F7 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F8 Post-Construction Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F9 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in mid-depth waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F10 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in mid-depth waters during mid-flood tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

Environmental Resources Management



No marine works was carried out in the reporting period.







Figure F11 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F12 Post-Construction Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F13 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F14 Post-Construction Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F15 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F16 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F17 Post-Construction Monitoring – Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F18 Post-Construction Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F19 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-ebb tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F20 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F21 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F22 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-ebb tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F23 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-flood tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(MF)5.

No marine works was carried out in the reporting period.









Figure F24 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-flood tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F25 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-flood tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F26 Post-Construction Monitoring – Mean Level of depthaveraged Turbidity (NTU) during mid-flood tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F27 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-ebb tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F28 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F29 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-ebb tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.







Figure F30 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-ebb tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.









Figure F31 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-flood tide between 27 November 2019 and 23 December 2019 at CS(Mf)3(N) and CS(Mf)5.

No marine works was carried out in the reporting period.









Figure F32 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-flood tide between 27 November 2019 and 23 December 2019 at IS(Mf)16 and IS(Mf)9.

No marine works was carried out in the reporting period.








Figure F33 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-flood tide between 27 November 2019 and 23 December 2019 at IS8(N) and SR4(N2).

No marine works was carried out in the reporting period.






Figure F34 Post-Construction Monitoring – Mean depth-averaged level of Suspended Solids (mg/L) during mid-flood tide between 27 November 2019 and 23 December 2019 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period.) In-situ monitoring is taken according to the requirement specified in the EM&A Manual, i.e. 3 water depth namely 1m below sea surface, mid-depth and 1m above sea bed. If the water depth is less than 3m, mid-depth sampling only. If water depth less than 6m, mid-depth may be omitted.

No marine works was carried out in the reporting period.

