Contract No. HY/2011/03

Hong Kong – Zhuhai – Macao Bridge

Hong Kong Link Road -

Section Between Scenic Hill and Hong Kong Boundary Crossing Facilities

Environmental Monitoring and Audit

Landscape Monitoring Report

(Long Term Management)

1 March 2021 to 28 February 2022

Counter-signed by:

Name: William Wong

Post: SE2/SD, Highways Department

Date: 28 July 2022

Contract No. HY/2011/03 Hong Kong- Zhuhai- Macao Bridge Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Establishment Inspection Checklist

Covering Period:		Period 6 1 January 2022 – 28 February 2022	Reported By:	Joy	ce Woi	ng	lens s
Time:		09:30 a.m. – 12:00 p.m.	Weather Condition: Rainy (21 February 2022			ary 2022)	
Participants:		Alan Lam (Arup), Derek Ng (C	hina State) and Th	neo Chan (R	ambol)	hath .
1	Zoning Acco (HyD/LU)	rding to Maintenance Authorities		N/A or not observed	Yes	No	Remarks / Photo
1.1	Is watering pr	rovided to all plants to ensure satis al and automatic irrigation)?	factory growth and	\checkmark			Not observed
1.2	Are tree stake chaffing of ba	es, guys and ties provided properly firk?	or safety and avoid	\checkmark			N/A No tree planted
1.3	Are trees or lin	mb overhanging braches pruned?		\checkmark			N/A No tree planted
1.4	After exceptional weather conditions, are proper action implemented to replace dead plants, repair damaged plants, bed in all plants that have blown over, frim up all other plants and immediately thereafter, remove dead plants and plants debris from the site?						N/A
1.5	Are litter and	debris removed?	ich in wir etapem von	\checkmark	qi 🗐 li	n y	Not observed
1.6	Are planting a	reas matched with the approved lan	dscape plan?	Bon of Ref	\checkmark		renA Blas
1.7	Is planting pat	ttern matched with the approved land				V .	
1.8	Are planting landscape pla	locations and spacing matching n?	sasz sz a ch			(co)	
1.9	Are the plant landscape pla	ting species on the site matched with the approved		aine II ol t			avegli i tak
1.10	Are the plants	ts in satisfied condition?		o H		\checkmark	See Photo P1 & P2
			Transless abyce				paiA Ca
2	Zoning Acco	rding to Maintenance Authorities	oka siyon se yara a ba si kana beyam	N/A or not observed	Yes	No	Remarks / Photo
2.1		rovided to all plants to ensure satisfactory growth and all and automatic irrigation)?			$\sqrt{}$		pred .
2.2	Are tree stake chaffing of bar	es, guys and ties provided properly for safety and avoid		TO WE WAS	\checkmark		1997
2.3	Are trees or lin	mb overhanging braches pruned?		V			Not observed
2.4	to replace dea	onal weather conditions, are proper action implemented ad plants, repair damaged plants, bed in all plants that over, frim up all other plants and immediately thereafter, plants and plants debris from the site?				\checkmark	See Photo P3 to P14
2.5	Are litter and	debris removed?		\checkmark			Not observed
2.6	Are planting a	areas matched with the approved landscape plan?		Mitar at at	\checkmark		ien ord
2.7	Is planting pat	ttern matched with the approved land	dscape plan?		$\sqrt{}$		
2.8	Are planting lo	locations and spacing matching with the approved			\checkmark		,
2.9		ing species on the site matched with the approved			\checkmark		
2.10		in satisfied condition?		,		\checkmark	See Photo P3 to P14

Contract No. HY/2011/03 Hong Kong- Zhuhai- Macao Bridge Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Establishment Inspection Checklist

3	Zoning According to Maintenance Authorities (TD or Others)	N/A or not observed	Yes	No	Remarks / Photo
3.1	Is watering provided to all plants to ensure satisfactory growth and health (manual and automatic irrigation)?		\checkmark		
3.2	Are tree stakes, guys and ties provided properly for safety and avoid chaffing of bark?	\checkmark			N/A No tree planted
3.3	Are trees or limb overhanging branches pruned?	\checkmark			N/A No tree planted
3.4	After exceptional weather conditions, are proper action implemented to replace dead plants, repair damaged plants, bed in all plants that have blown over, frim up all other plants and immediately thereafter, remove dead plants and plants debris from the site?	\checkmark			N/A
3.5	Are litter and debris removed?	\checkmark			Not observed
3.6	Are planting areas matched with the approved landscape plan?		$\sqrt{}$		
3.7	Is planting pattern matched with the approved landscape plan?		\checkmark		
3.8	Are planting locations and spacing matching with the approved landscape plan?		\checkmark		
3.9	Are the planting species on the site matched with the approved landscape plan?		\checkmark		
3.10	Are the plants in satisfied condition?				See Photo P15
4	Zoning According to Maintenance Authorities (AAHK)	N/A or not observed	Yes	No	Remarks / Photo
4.1	Is watering provided to all plants to ensure satisfactory growth and health (manual and automatic irrigation)?		\checkmark		
4.2	Are tree stakes, guys and ties provided properly for safety and avoid chaffing of bark?	\checkmark			N/A
4.3	Are trees or limb overhanging braches pruned?	\checkmark			N/A
4.4	After exceptional weather conditions, are proper action implemented to replace dead plants, repair damaged plants, bed in all plants that have blown over, frim up all other plants and immediately thereafter, remove dead plants and plants debris from the site?	\checkmark			N/A
4.5	Are litter and debris removed?	\checkmark			Not observed
4.6	Are planting areas matched with the approved landscape plan?		\checkmark		E
4.7	Is planting pattern matched with the approved landscape plan?		\checkmark		
4.8	Are planting locations and spacing matching with the approved landscape plan?	8	\checkmark		0
4.9	Are the planting species on the site matched with the approved landscape plan?		\checkmark		
4.10	Are the plants in satisfied condition?			9	N/A Maintananaa
					Maintenance works in progress Photo F1
			() ()	ā	
5	General Document	N/A or not observed	Yes	No	Remarks / Photo
5.1	Are the records of watering, fertilizing, weeding, pruning and mowing kept for checking?		\checkmark		

Follow up actions for previous Site Audit:

HyD - Along Expressway of HKLR:

- 1. The maintenance authorities were reminded to remove the weeds (unwanted species) promptly.
- 2. The maintenance authorities were reminded to replace the unhealthy plants.

LCSD - Between Flight Training Centre and HMA:

- 3. The maintenance authorities were reminded to provide proper maintenance.
- 4. The maintenance authorities were reminded to provide proper maintenance.
- The maintenance authorities were reminded to provide proper maintenance.
- 6. The maintenance authorities were reminded to provide proper maintenance.
- 7. The maintenance authorities were reminded to provide proper maintenance.
- The maintenance authorities were reminded to provide proper maintenance.

LCSD - Next to Shaft 3:

- 9. The maintenance authorities were reminded to provide proper maintenance.
- 10. The maintenance authorities were reminded to provide proper maintenance.
- 11. The maintenance authorities were reminded to provide proper maintenance.
- 12. The maintenance authorities were reminded to provide proper maintenance.
- 13. The maintenance authorities were reminded to provide proper maintenance.

TD / Others - Next to HMA Admiration Building:

14. The maintenance authorities were reminded to remove the weeds (unwanted species) promptly.

AAHK - Along Airport Road:

15. The maintenance work is in progress. (See Photo F1)

Observations:

HyD – Along Expressway of HKLR:

- 1. Serious weeds affecting planted species were observed. (See Photo P1).
- 2. Plants with unsatisfied condition (i.e. unhealthy plants) were observed. (See Photo P2)

LCSD - Between Flight Training Centre and HMA:

- 3. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P3)
- 4. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P4)
- 5. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P5)
- 6. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P6)
- 7. Plants with unsatisfied condition were observed. (See Photo P7)
- 8. Tree with unsatisfied condition (i.e. fallen tree) was observed. (See Photo P8)

LCSD - Next to Shaft 3:

- 9. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P9)
- 10. Tree with unsatisfied condition (i.e. fallen tree) was observed. (See Photo P10)
- 11. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P11)
- 12. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P12)
- 13. Tree with unsatisfied condition (i.e. fallen tree) was observed. (See Photo P13)
- 14. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P12)

TD / Others - Next to HMA Admiration Building:

15. Serious weeds affecting planted species were observed. (See Photo P14)

Corrective Actions (if any):

HyD - Along Expressway of HKLR:

- 1. The maintenance authorities should be reminded to remove the weeds (unwanted species) promptly.
- 2. The maintenance authorities should be reminded to replace the unhealthy plants.

LCSD - Between Flight Training Centre and HMA:

- 3. The maintenance authorities should be reminded to provide proper maintenance.
- 4. The maintenance authorities should be reminded to provide proper maintenance.
- 5. The maintenance authorities should be reminded to provide proper maintenance.
- 6. The maintenance authorities should be reminded to provide proper maintenance.
- 7. The maintenance authorities should be reminded to provide proper maintenance.
- 8. The maintenance authorities should be reminded to provide proper maintenance.

Contract No. HY/2011/03 Hong Kong- Zhuhai- Macao Bridge Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Establishment Inspection Checklist

LCSD - Next to Shaft 3:

- 9. The maintenance authorities should be reminded to provide proper maintenance.
- 10. The maintenance authorities should be reminded to provide proper maintenance.
- 11. The maintenance authorities should be reminded to provide proper maintenance.
- 12. The maintenance authorities should be reminded to provide proper maintenance.
- The maintenance authorities should be reminded to provide proper maintenance.
- 14. The maintenance authorities should be reminded to provide proper maintenance.

TD / Others - Next to HMA Admiration Building:

15. The maintenance authorities should be reminded to remove the weeds (unwanted species) promptly.

General Conclusion:

Reported by

During the site inspection, a number of trees with unsatisfied condition (i.e. fallen tree) were observed at LCSD Area. In addition, serious weeds and plants with unsatisfied condition were observed at HyD and TD/Others.

Proper planting maintenances should be provided on the planting areas / trees to enhance the aesthetic degree, and ensure planting species/conditions are matched with the approval landscape plan.

The planting areas along Expressway of HKLR (HyD), between Flight Training Centre and HMA (LCSD), next to Shaft 3 (LCSD), next to HMA Admiration Building (TD / Others) were handed over to the relevant authorities. The maintenance authorities should be reminded to provide proper maintenance.

The planting areas along airport road were handed over to AAHK. Such areas are under maintenance.

(ET's Representative):	Joyce Wong	Title:	Environmental Team	_
Signature:	Wory	, Date:	21 February 2022	_
Reviewed by (RSS Landscape Representative):	Alen Lam	Title:	RWS I	-
Signature:	Law	Date:	14 Mar, 2.22	_
Contractor's Representative:	Derok Ng	Title:	Assistant Environmental (Office
Signature:	J.	Date:	14 March 2022	_
Checked by (IEC's Representative):	Theo Chan	Title:	Assistant Environmental Consultant	-
Signature:		Date:	14 March 2022	_

Location	Photo Record					
AAHK – Along Airport Road		Photo Record				
	Photo F1 - The maintenance work is in progress.					

Location	Photo Record				
HyD – Along Expressway of HKLR Photo P1- Serious weeds affecting planted species were observed.		Photo P2 - Plants with unsatisfied condition (i.e. unhealthy plants) were observed.			
LCSD	Photo P3 - Trees with unsatisfied condition (i.e. fallen tree) were observed.	Photo P4 - Trees with unsatisfied condition (i.e. fallen tree) were observed.	Photo P5 - Trees with unsatisfied condition (i.e. fallen tree) were observed.		
	Between Flight Training Centre and HMA	Between Flight Training Centre and HMA	Between Flight Training Centre and HMA		



LCSD	Photo P12 - Trees with unsatisfied condition (i.e. fallen tree) were observed.	Photo P13 - Tree with unsatisfied condition (i.e. fallen tree) was observed.	Photo P14 - Tree with unsatisfied condition (i.e. fallen tree) was observed.
	Next to Shaft 3	Next to Shaft 3	
TD / Others – Next to HMA Admiration	Photo P15 - Serious weeds affecting planted species were observed.		
Building			

Recent Condition on Site



Photo 01: LCSD Area - Zone G




Photo 02: LCSD Area - Zone G



Photo 03: LCSD Area - Zone G



Photo 04: LCSD Area - Zone G



Photo 05: LCSD Area - Zone G



Photo 06: LCSD Area - Zone G




Photo 07: LCSD Area - Zone G



Photo 08: LCSD Area – Zone G



Photo 09: LCSD Area - Zone G



Photo 10: LCSD Area – Zone G



Photo 11: LCSD Area - Zone G



Photo 12: LCSD Area - Zone B



Photo 13: LCSD Area - Zone B



Photo 14: LCSD Area - Zone B




Photo 15: LCSD Area - Zone B



Photo 16: LCSD Area – Zone B



Photo 17: LCSD Area - Zone B




Photo 18: LCSD Area - Zone B




Photo 19: LCSD Area - Zone B




Photo 20: LCSD Area – Zone B




Photo 21: LCSD Area – Zone B




Photo 22: LCSD Area – Zone B



Photo 23: LCSD Area - Zone B



Photo 24: LCSD Area - Zone C



Photo 25: LCSD Area - Zone C



Photo 26: LCSD Area - Zone C



Photo 27: LCSD Area - Zone C



Photo 28: LCSD Area - Zone C



Photo 29: LCSD Area - Zone C



Photo 30: LCSD Area - Zone C




Photo 31: LCSD Area - Zone F



Photo 32: LCSD Area - Zone F



Photo 33: LCSD Area - Zone F



Photo 34: LCSD Area - Zone D



Photo 35: LCSD Area - Zone D



Photo 36: LCSD Area - Zone D



Photo 37: LCSD Area - Zone D



Photo 38: LCSD Area - Zone D



Photo 39: LCSD Area - Zone D



Photo 40: LCSD Area - Zone D



Photo 41: LCSD Area - Zone E



Photo 42: LCSD Area - Zone E



Photo 43: LCSD Area - Zone E



Photo 44: LCSD Area - Zone E



Photo 45: LCSD Area - Zone E



Photo 46: LCSD Area - Zone E



Photo 47: LCSD Area - Zone E



Photo 48: LCSD Area - Zone E



Photo 49: LCSD Area - Zone E



Photo 50: LCSD Area - Zone E



Photo 51: LCSD Area - Zone E



Photo 52: LCSD Area - Zone E

Annex A

Location Plan

Contract No. HY/2011/03 - Maintenance Authorities for Landscape Works



Annex B Planting Schedule **AAHK LAND PLANTING SCHEDULE**

TREE PLANTING				
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	SPACING (mm)
BV	Bauhinia variegata	宮粉羊蹄甲	3500(H) x 50(DBH)	(As shown)

SHRUB PLANTING						
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY
OF	Osnabthus fragrans	桂花	600(H) x 300(SP)	Ac2	(As shown)	_
NO	Nerium oleander	夾竹桃	600(H) x 300(SP)	Ac4	(As shown)	-
BG	Bougainvillea glabra	光葉子花	600(H) x 300(SP)	AG1 / As2	750	2/m ²
DC .	Rhododendron spp.	杜鵑	300(H) x 150(SP)	Ac3	(As shown)	-%
FS Knododendron spp.	(1)上月辰	300(11) x 130(3F)	As2	480	5/m ²	

TURFING			
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)
ZS	Zoysia sp.	結縷草	150(H)

HYDROSEEDING					
SPECIES CODE	BOTANICAL NAME	CHINESE NAME			
Cda	Cynodon dactylon	百慕達草			
Pno	Paspalum notatum	百喜草			
Lpe	Loium perenne	黑麥草			

HYD LAND PLANTING SCHEDULE

SHRUB PLANTIN	SHRUB PLANTING							
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY		
LI ·	Lagerstroemia indica	細葉紫薇	600(H)	HG5	1000	1/m ²		
RS	Rhododendron spp.	杜鵑	300(H)	HG1 / HG5 / HG6 / HG7	380	8/m ²		
AA	Agave angustifolia	狹葉龍舌蘭	300(H)	HG3	700	2/m ²		
IC	Ixora chinensis	育制的存在	300(H)	HG6	380	8/m ²		
*NH	Nephrolepis hirsutula	毛葉腎蕨	300(H)	HG7	270	16/m ²		

GROUNDCOVER	PLANTING					
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY
LM	Lantana montevidensis	小葉馬纓丹	150(H)	HG1 / HG3 / HG4 / HG7	380	8/m ²

NOTES:

^{*} Variation work request by SCI for additional planting work to increase density.

TD/OTHERS LAND PLANTING SCHEDULE

SHRUB PLANTING	SHRUB PLANTING						
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY	
CP	Caesalpinia pulcherrima	洋金鳳	300(H)	Ms4	750	2/m ²	
CH	Calliandra haematocephala	紅絨球	300(H)	Ms4	750	2/m ²	
MA	Malvaviscus arboreus var.	懸鈴花	300(H)	Ms4	750	2/m ²	
HS -	Hippeastrum spp.	朱頂紅	300(H)	MG7	350	10/m ²	
IT.	Iris tectorum	鳶尾	300(H)	MG7	240	20/m ²	
NH	Nephrolepis hirsutula	毛葉腎蕨	300(H)	MG7 / Ms4	450	6/m ²	
SR	Strelitzia reginae	鶴望蘭	300(H)	MG7	480	5/m ²	

GROUNDCOVER	GROUNDCOVER PLANTING					
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY
TS	Tradescantia spathacea'Dwarf'	紫露草 (矮蚌花)	150(H)	Ms4	450	6/m ²
SP	Syngonium podophyllum	合果芋	150(H)	MG7	480	5/m ²

CLIMBER PLANTING						7
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY
EA	EA Epipremnum aureum		600(L)	Ms4	450	6/m ²
	Lpiprenmam aaream	綠蘿 600(L)	000(L)	Mz1	500	-
FP	Ficus pumila	薜荔	600(L)	Mz1	500	-

TURFING			
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)
ZS	Zoysia sp.	結縷草	150(H)

HYDROSEEDING				
SPECIES CODE	BOTANICAL NAME	CHINESE NAME		
Cda	Cynodon dactylon	百慕達草		
Pno	Paspalum notatum	百喜草		
Lpe	Loium perenne	黑麥草		

LCSD LAND PLANTING SCHEDULE

TREE PLANTING				,
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	SPACING (mm)
BV	Bauhinia variegata	宮粉羊蹄甲	3500(H) x 75(DBH)	(As shown)
TM	Terminalia mantaly	小葉欖仁樹	3500(H) x 75(DBH)	(As shown)
AL	Albizia lebbek	大葉合歡	3500(H) x 75(DBH)	(As shown)
SS	Senna siamea	鐵刀木	3500(H) x 75(DBH)	(As shown)
BX	Bauhinia variegata var. Candida	白花洋紫荊	3500(H) x 75(DBH)	(As shown)
BP	Bauhinia purpurea	紅花羊蹄甲	3500(H) x 75(DBH)	(As shown)
PR	Plumeria rubra	雞蛋花	2000(H) x 25(DBH)	(As shown)
GR	Grevillea robusta	銀樺	2000(H) x 25(DBH)	(As shown)
CV	Callistemon viminalis	串錢柳	2000(H) x 25(DBH)	(As shown)
TC	Tabebuia chrysantha	黃花風鈴木	2000(H) x 25(DBH)	(As shown)
TP	Thespesia populnea	恒春黃槿	2000(H) x 25(DBH)	(As shown)
AC	Acacia confusa	臺灣相思	150 - 900(H)	(As shown)
RM	Ravenala madagascariensis	旅人蕉	2500(H)	(As shown)
CO	Caryota mitis	魚尾葵	2500(H)	(As shown)
PL	Phoenix loureiroi	刺葵	2500(H)	(As shown)
SN	Strelitzia nicolai	大鶴望蘭	2500(H)	(As shown)

LCSD LAND PLANTING SCHEDULE

SHRUB PLANTING							
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY	
AG	Agave americana	龍舌蘭	300(H)	LG4	1000	1/m ²	
AA	Agave angustifolia	狹葉龍舌蘭	300(H)	LG3	1000	1/m ²	
BG	Bougainvillea glabra	业在了#	300(H)	LG1	750	2/m ²	
		光葉子花		LG8	1000	1/m ²	
CU	Cuphea hyssopifolia	細葉雪茄花	300(H)	LT5	450	6/m ²	
		加朱子加10		Ls3	380	8/m ²	
HR	Hibiscus rosa-sinensis	大紅花	300(H)	LT4	750	2/m ²	
		/\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		LG5	1000	1/m ²	
HS	Hippeastrum spp.	朱頂紅	300(H)	LG7	270	16/m ²	
IT .	Iris tectorum	鳶尾	300(H)	LG7 / Ls2	215	25/m ²	
LI	Lagerstroemia indica	細葉紫薇	300(H)	LT4	750	2/m ²	
		本条版		Ls2	1000	1/m ²	
MA	Malvaviscus arboreus var.	懸鈴花	300(H)	LT4	750	2/m ²	
NH	Nephrolepis hirsutula	毛葉腎蕨	300(H)	LG7 / Ls3	380	8/m ²	
		· 一、一、一、一、一、一、一、一、一、一、一、一、一、一、一、一、一、一、一、		LG8	1000	1/m ²	
NO	Nerium oleander	夾竹桃	300(H)	LT4	750	2/m ²	
PM	Phyllanthus myrtifolius	105	300(H)	LT1	550	4/m ²	
		錫蘭葉下珠		LT2	380	8/m ²	
				Ls3	480	5/m ²	
RS	Rhododendron spp.	杜鵑	300(H)	LT3	600	3/m ²	
		1工月间		LG6 / Ls2 / Ls3	380	8/m ²	
SR	Strelitzia reginae	鶴望蘭	300(H)	LG7 / Ls2	480	5/m ²	

LCSD LAND PLANTING SCHEDULE

GROUNDCOVER PLANTING							
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY	
ÓŊ	Ophiopogon japonicus	麥冬	150(H)	LG3 / LG4 / LG6	240	20/m ²	
SP	Syngonium podophyllum	合果芋	150(H)	LG7	360	9/m ²	
TS	Tradescantia spathacea'Dwarf'	矮蚌花	150/LI)	LG1 / LG5	350	10/m ²	
			150(H)	LG8	1000 -	1/m ²	
WT	Wedelia trilobata	蟛蜞菊		LG2	450	6/m ²	
			150(H)	*LG2 in Planter L22 to L26	225	23/m ²	
ZC	Zephyranthes Candida	蔥蓮	150(H)	LG3	240	20/m ²	
ZR	Zephyranthes rosea	玫瑰蔥蓮	150(H)	LG4 / LG6	240	20/m ²	
TS1	Tradescantia spathacea	大蚌花	150(H)	*LG5 in Planter L22 to L26	175	38/m ²	


CLIMBER PLANTING							
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)	Planting Pattern	SPACING (mm)	UNIT QTY	
EA ·	Epipremnum aureum	綠蘿	600(L)	LG8	1000	1/m ²	

TURFING			
SPECIES CODE	BOTANICAL NAME	CHINESE NAME	SIZE (mm)
ZS	Zoysia sp.	結縷草	150(H)

NOTES:

* Variation work request by SCI for additional planting work to increase density.

Contract No. HY/2011/03 - Establishment Works of Soft Landscape Works of HyD/LU




Planting Area:

- A. Along expressway of HKLR
- B. Tunnel SHT West Portal Slope
- C. Others

Contract No. HY/2011/03 – Establishment Works of Soft Landscape Works of LCSD Lands B Planting Area: A. Along Chek Lap Kok Road & Tung Wing Road B. Along Coastal Maintenance Tracks C. Above Tunnel SHT East Portal D. Triangular Planting Area between CNAC Tower and HMA E. Between Flight Training Centre and HMA F. Next to HMA G. Next to Shaft 3





Planting Area:

- A. Next to HMA Administration Building
- B. Along Ramps M014 and M015
- C. Turf areas at Tunnel SHT East Portal
- D. Vertical Planting along Walls of Tunnel SHT East Portal

Contract No. HY/2011/03 – Establishment Works of Soft Landscape Works of AAHK Lands E Planting Area: A. Along Airport Road

- B. Along East Coast Road
- C. East Coast Road and Tung Fai Road
- D. Kwo Lo Wan Road, Shafts 1, 2 amd 3
- E. Outside CNAC Tower
- F.Tung Yiu Road