


Air Quality Monitoring Data

Project	Works	Date (yyyy-mm-dd)	Station	Time	Parameter	Results	Unit
HKLR	HY/2011/03	2021-10-06	AMS5	10:24	1-hr TSP	26	µg/m ³
HKLR	HY/2011/03	2021-10-06	AMS5	11:24	1-hr TSP	23	µg/m ³
HKLR	HY/2011/03	2021-10-06	AMS5	13:00	1-hr TSP	29	µg/m ³
HKLR	HY/2011/03	2021-10-12	AMS5	10:24	1-hr TSP	23	µg/m ³
HKLR	HY/2011/03	2021-10-12	AMS5	11:24	1-hr TSP	22	µg/m ³
HKLR	HY/2011/03	2021-10-12	AMS5	13:00	1-hr TSP	22	µg/m ³
HKLR	HY/2011/03	2021-10-18	AMS5	9:01	1-hr TSP	28	µg/m ³
HKLR	HY/2011/03	2021-10-18	AMS5	10:01	1-hr TSP	26	µg/m ³
HKLR	HY/2011/03	2021-10-18	AMS5	11:01	1-hr TSP	26	µg/m ³
HKLR	HY/2011/03	2021-10-22	AMS5	9:03	1-hr TSP	19	µg/m ³
HKLR	HY/2011/03	2021-10-22	AMS5	10:03	1-hr TSP	19	µg/m ³
HKLR	HY/2011/03	2021-10-22	AMS5	11:03	1-hr TSP	21	µg/m ³
HKLR	HY/2011/03	2021-10-28	AMS5	9:02	1-hr TSP	28	µg/m ³
HKLR	HY/2011/03	2021-10-28	AMS5	10:02	1-hr TSP	28	µg/m ³
HKLR	HY/2011/03	2021-10-28	AMS5	11:02	1-hr TSP	31	µg/m ³
HKLR	HY/2011/03	2021-10-05	AMS5	8:00	24-hr TSP	64	µg/m ³
HKLR	HY/2011/03	2021-10-11	AMS5	8:00	24-hr TSP	52	µg/m ³
HKLR	HY/2011/03	2021-10-15	AMS5	8:00	24-hr TSP	34	µg/m ³
HKLR	HY/2011/03	2021-10-21	AMS5	8:00	24-hr TSP	51	µg/m ³
HKLR	HY/2011/03	2021-10-27	AMS5	8:00	24-hr TSP	62	µg/m ³

Remarks:

1) The existing air quality monitoring location AMS6 - Dragonair / CNAC (Group) Building (HKIA) will be handed over to Airport Authority Hong Kong on 31 March 2021. 1hr and 24 hr air quality monitoring at AMS6 will be temporarily suspended starting from 1 April 2021.

Graphical Plot of 1-hour TSP at AMS5 and AMS6




Remark:

Date

1) The existing air quality monitoring location AMS6 - Dragonair / CNAC (Group) Building (HKIA) was handed over to Airport Authority Hong Kong on 31 March 2021. 1-hr TSP monitoring at AMS6 was temporarily suspended starting from 1 April 2021.

Air Quality Monitoring Data (24-hour)



Remarks:

Date

- 1) The existing air quality monitoring location AMS6 - Dragonair / CNAC (Group) Building (HKIA) was handed over to Airport Authority Hong Kong on 31 March 2021. 24-hr TSP monitoring at AMS6 was temporarily suspended starting from 1 April 2021.
- 2) Due to timer problem, 24-hr TSP monitoring at AMS5 – Ma Wan Chung Village was rescheduled from 2 July 2021 to 5 July 2021 .
- 3) Due to malfunction of High Volume Sampler (HVS) at AMS5 - Ma Wan Chung Village, 24-hr TSP monitoring time on 14 July 2021 at AMS5 was cancelled. The HVS was repaired on 19 July 2021. The 24-hr TSP monitoring at AMS5 was resumed on 20 July 2021.

Noise Monitoring Data


Project	Works	Date (yyyy-mm-dd)	Station	Start Time	Wind Speed, m/s	1st set 5mins	2nd set 5mins	3rd set 5mins	4th set 5mins	5th set 5mins	6th set 5mins	Overall (30mins)*	Unit
HKLR	HY/2011/03	2021-10-06	NMS5	10:48	<5	Leq: 52.1	Leq: 51.4	Leq: 56.3	Leq: 53.7	Leq: 52.6	Leq: 55.1	Leq: 57	dB(A)
						L10: 54.0	L10: 52.0	L10: 60.0	L10: 56.5	L10: 54.5	L10: 58.0	L10: 60	
						L90: 50.0	L90: 49.0	L90: 49.5	L90: 49.5	L90: 49.5	L90: 50.5	L90: 53	
HKLR	HY/2011/03	2021-10-12	NMS5	11:01	<5	Leq: 58.0	Leq: 54.2	Leq: 55.4	Leq: 53.6	Leq: 55.6	Leq: 56.7	Leq: 59	dB(A)
						L10: 58.7	L10: 55.5	L10: 56.0	L10: 54.5	L10: 57.5	L10: 59.0	L10: 60	
						L90: 52.5	L90: 52.0	L90: 52.0	L90: 52.0	L90: 53.5	L90: 52.5	L90: 55	
HKLR	HY/2011/03	2021-10-18	NMS5	9:24	<5	Leq: 58.4	Leq: 57.5	Leq: 57.0	Leq: 58.3	Leq: 52.3	Leq: 53.1	Leq: 60	dB(A)
						L10: 60.0	L10: 60.0	L10: 60.5	L10: 62.0	L10: 54.5	L10: 55.5	L10: 62	
						L90: 51.5	L90: 50.5	L90: 50.0	L90: 50.0	L90: 49.5	L90: 49.5	L90: 53	
HKLR	HY/2011/03	2021-10-28	NMS5	9:35	<5	Leq: 62.1	Leq: 57.8	Leq: 61.6	Leq: 58.9	Leq: 57.1	Leq: 57.1	Leq: 63	dB(A)
						L10: 63.0	L10: 58.0	L10: 63.5	L10: 61.5	L10: 57.5	L10: 57.5	L10: 64	
						L90: 57.0	L90: 56.0	L90: 57.0	L90: 56.5	L90: 55.5	L90: 55.5	L90: 59	

Remark:

(1)* A facade correction of +3 dB(A) was applied to the measured noise level.

Graphical Plot of Noise Levels at NMS5

Continuous Noise Monitoring Data (NMS5)



Remark:

(1) A facade correction of +3 dB(A) was applied to the measured noise level.