Establishment Inspection Checklist

| Cover | ing Period: | Period 5 1 November 2021 – 31 December 2021 | Reported By: | Joyd | e Wor | ng | |
|--------|---|---|--|---------------------------------|--------------|------------------------|------------------------|
| Time: | | 09:30 a.m. – 12:00 p.m. | Weather Condi | lition: Fine (15 December 2021) | | | per 2021) |
| Partic | ipants: | Alan Lam (Arup), Derek Ng (Ch | ina State) and Th | neo Chan (R | amboll |) | · |
| | | | | | | | |
| 1 | Zoning Accor (HyD/LU) | ding to Maintenance Authorities | | N/A or not observed | Yes | No | Remarks / Photo |
| 1.1 | health (manua | ovided to all plants to ensure satisfa I and automatic irrigation)? | | $\overline{\checkmark}$ | | | Not observed |
| 1.2 | Are tree stakes chaffing of barl | s, guys and ties provided properly for k? | safety and avoid | \checkmark | | | N/A No tree planted |
| 1.3 | Are trees or limb overhanging braches pruned? | | \checkmark | | | N/A No tree planted | |
| 1.4 | to replace dea | nal weather conditions, are proper ac d plants, repair damaged plants, bed er, frim up all other plants and immed plants and plants debris from the site? | I in all plants that diately thereafter, | \checkmark | | | N/A |
| 1.5 | Are litter and d | ebris removed? | | \checkmark | | | Not observed |
| 1.6 | Are planting ar | eas matched with the approved lands | scape plan? | | \checkmark | | |
| 1.7 | Is planting patt | ern matched with the approved lands | scape plan? | | \checkmark | | |
| 1.8 | Are planting I landscape plan | ocations and spacing matching win? | th the approved | | \checkmark | | |
| 1.9 | Are the plantil | ng species on the site matched win? | ith the approved | | \checkmark | | |
| 1.10 | Are the plants | in satisfied condition? | | | | \checkmark | See Photo P1 & P2 |
| | | | | | | | |
| 2 | Zoning Accor (LCSD) | ding to Maintenance Authorities | | N/A or not observed | Yes | No | Remarks / Photo |
| 2.1 | | vided to all plants to ensure satisfact I and automatic irrigation)? | ory growth and | | \checkmark | | |
| 2.2 | Are tree stakes chaffing of barl | s, guys and ties provided properly for k? | safety and avoid | | \checkmark | | |
| 2.3 | Are trees or lim | nb overhanging braches pruned? | | \checkmark | | | Not observed |
| 2.4 | to replace dead have blown over | nal weather conditions, are proper act d plants, repair damaged plants, bed er, frim up all other plants and immed plants and plants debris from the site? | in all plants that liately thereafter, | | | \checkmark | See Photo P3 to P13 |
| 2.5 | Are litter and d | ebris removed? | | \checkmark | | | Not observed |
| 2.6 | Are planting ar | eas matched with the approved lands | scape plan? | | \checkmark | | |
| 2.7 | Is planting patt | ern matched with the approved lands | scape plan? | | \checkmark | | |
| 2.8 | Are planting lo | cations and spacing matching with th | e approved | | \checkmark | | |
| 2.9 | • • | g species on the site matched with th | ne approved | | \checkmark | | |
| 2.10 | Are the plants | in satisfied condition? | | | | \checkmark | See Photo P3 to P13 |

Contract No. HY/2011/03 Hong Kong- Zhuhai- Macao Bridge Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Establishment Inspection Checklist

| 3 | Zoning According to Maintenance Authorities (TD or Others) | N/A or not observed | Yes | No | Remarks / Photo |
|------|---|---------------------|--------------|--------------|------------------------|
| 3.1 | Is watering provided to all plants to ensure satisfactory growth and health (manual and automatic irrigation)? | | \checkmark | | |
| 3.2 | Are tree stakes, guys and ties provided properly for safety and avoid chaffing of bark? | \checkmark | | | N/A No tree planted |
| 3.3 | Are trees or limb overhanging branches pruned? | \checkmark | | | N/A No tree planted |
| 3.4 | After exceptional weather conditions, are proper action implemented to replace dead plants, repair damaged plants, bed in all plants that have blown over, frim up all other plants and immediately thereafter, remove dead plants and plants debris from the site? | \checkmark | | | N/A |
| 3.5 | Are litter and debris removed? | \checkmark | | | Not observed |
| 3.6 | Are planting areas matched with the approved landscape plan? | | \checkmark | | |
| 3.7 | Is planting pattern matched with the approved landscape plan? | | | | |
| 3.8 | Are planting locations and spacing matching with the approved landscape plan? | | \checkmark | | |
| 3.9 | Are the planting species on the site matched with the approved landscape plan? | | \checkmark | | |
| 3.10 | Are the plants in satisfied condition? | | | \checkmark | See Photo P14 |
| | | | | | |
| 4 | Zoning According to Maintenance Authorities (AAHK) | N/A or not observed | Yes | No | Remarks / Photo |
| 4.1 | Is watering provided to all plants to ensure satisfactory growth and health (manual and automatic irrigation)? | | \checkmark | | |
| 4.2 | Are tree stakes, guys and ties provided properly for safety and avoid chaffing of bark? | \checkmark | | | N/A |
| 4.3 | Are trees or limb overhanging braches pruned? | \checkmark | | | N/A |
| 4.4 | After exceptional weather conditions, are proper action implemented to replace dead plants, repair damaged plants, bed in all plants that have blown over, frim up all other plants and immediately thereafter, remove dead plants and plants debris from the site? | \checkmark | | | N/A |
| 4.5 | Are litter and debris removed? | \checkmark | | | Not observed |
| 4.6 | Are planting areas matched with the approved landscape plan? | | \checkmark | | |
| 4.7 | Is planting pattern matched with the approved landscape plan? | | \checkmark | | |
| 4.8 | Are planting locations and spacing matching with the approved landscape plan? | | \checkmark | | |
| 4.9 | Are the planting species on the site matched with the approved landscape plan? | | \checkmark | | |
| 4.10 | Are the plants in satisfied condition? | | | \checkmark | See Photo P15 |
| | | | | | |
| 5 | General Document | N/A or not observed | Yes | No | Remarks / Photo |
| 5.1 | Are the records of watering, fertilizing, weeding, pruning and mowing kept for checking? | | \checkmark | | |
| | | | | | |

Follow up actions for previous Site Audit:

HyD - Along Expressway of HKLR:

- 1. The maintenance authorities were reminded to remove the weeds (unwanted species) promptly.
- 2. The maintenance authorities were reminded to replace the unhealthy plants.

LCSD - Between Flight Training Centre and HMA:

- 3. Proper maintenance was provided. (See Photo F1)
- 4. The Contractor was reminded to provide proper maintenance.
- 5. The Contractor was reminded to provide proper maintenance.
- 6. The Contractor was reminded to provide proper maintenance.
- 7. The Contractor was reminded to provide proper maintenance.
- 8. The Contractor was reminded to provide proper maintenance.

LCSD - Next to Shaft 3:

- 9. The Contractor was reminded to provide proper maintenance.
- 10. The Contractor was reminded to provide proper maintenance.
- 11. The Contractor was reminded to provide proper maintenance.
- 12. The Contractor was reminded to replace the unhealthy plants / provide proper maintenance.
- 13. Proper maintenance was provided. (See Photo F2)
- 14. The Contractor was reminded to provide proper maintenance.

TD / Others – Next to HMA Admiration Building:

- 15. The maintenance authorities were reminded to remove the weeds (unwanted species) promptly.
- 16. The weeds were removed and maintenance is in progress. (See Photo F3)

AAHK - Along Airport Road:

- 17. The Contractor was reminded to replace the plants with unsatisfied condition.
- 18. The weeds were removed and maintenance is in progress. (See Photo F4)

Observations:

HyD – Along Expressway of HKLR:

- 1. Serious weeds affecting planted species were observed. (See Photo P1).
- 2. Plants with unsatisfied condition (i.e. unhealthy plants) were observed. (See Photo P2)

LCSD - Between Flight Training Centre and HMA:

- 3. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P3)
- 4. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P4)
- 5. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P5)
- Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P6)
- 7. Plants with unsatisfied condition were observed. (See Photo P7)
- 8. Tree with unsatisfied condition (i.e. fallen tree) was observed. (See Photo P8)

LCSD - Next to Shaft 3:

- 9. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P9)
- 10. Tree with unsatisfied condition (i.e. fallen tree) was observed. (See Photo P10)
- 11. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P11)
- 12. Trees with unsatisfied condition (i.e. fallen tree) were observed. (See Photo P12)
- 13. Tree with unsatisfied condition was observed. (See Photo P13)

TD / Others – Next to HMA Admiration Building:

14. Serious weeds affecting planted species were observed. (See Photo P14)

AAHK - Along Airport Road:

15. Plants with unsatisfied condition were observed. (See Photo P15)

Corrective Actions (if any):

HyD – Along Expressway of HKLR:

- 1. The maintenance authorities should be reminded to remove the weeds (unwanted species) promptly.
- 2. The maintenance authorities should be reminded to replace the unhealthy plants.

LCSD – Between Flight Training Centre and HMA:

- 3. The Contractor was reminded to provide proper maintenance.
- 4. The Contractor was reminded to provide proper maintenance.
- 5. The Contractor was reminded to provide proper maintenance.

Contract No. HY/2011/03 Hong Kong- Zhuhai- Macao Bridge Hong Kong Link Road Section between Scenic Hill and Hong Kong Boundary Crossing Facilities

Establishment Inspection Checklist

- 6. The Contractor was reminded to provide proper maintenance.
- 7. The Contractor was reminded to provide proper maintenance.
- 8. The Contractor was reminded to provide proper maintenance.

LCSD - Next to Shaft 3:

- 9. The Contractor was reminded to provide proper maintenance.
- 10. The Contractor was reminded to provide proper maintenance.
- 11. The Contractor was reminded to provide proper maintenance.
- 12. The Contractor was reminded to replace the unhealthy plants / provide proper maintenance.
- 13. The Contractor was reminded to provide proper maintenance.

TD / Others - Next to HMA Admiration Building:

14. The maintenance authorities should be reminded to remove the weeds (unwanted species) promptly.

AAHK - Along Airport Road:

15. The Contractor was reminded to replace the plants with unsatisfied condition.

General Conclusion:

During the site inspection, a number of trees with unsatisfied condition (i.e. fallen tree) were observed at LCSD Area. In addition, serious weeds and plants with unsatisfied condition were observed at HyD, TD/Others and AAHK Areas.

Proper planting maintenances should be provided on the planting areas / trees to enhance the aesthetic degree, and ensure planting species/conditions are matched with the approval landscape plan.

| Reported by | | | 13% |
|---|------------|--------|------------------------------------|
| (ET's Representative): | Joyce Wong | Title: | Environmental Team |
| Signature: | Wry | Date: | 15 December 2021 |
| Reviewed by (RSS Landscape Representative): | Alan Lam | Title: | RWS I |
| Signature: | Law | Date: | 1 January 2022 |
| Contractor's Representative: | Denk Ng | Title: | AEO |
| Signature: | In | Date: | 1 January 2022 |
| Checked by (IEC's Representative): | Theo Chan | Title: | Assistant Environmental Consultant |
| Signature: | M | Date: | 1 January 2022 |

| Location | | Photo Record | | | | |
|---|---|---|--|--|--|--|
| LCSD | | | | | | |
| | Photo F1 – Proper maintenance was provided. | Photo F2 – Proper maintenance was provided. | | | | |
| TD / Others – Next to HMA Admiration Building | Photo F3 - The weeds were removed and maintenance is in progress. | | | | | |

| AAHK – | Along | Airport |
|--------|-------|---------|
| | Road | |



Photo F4 - The weeds were removed and maintenance is in progress.

| Location | | Photo Record | |
|-----------------------------------|---|---|---|
| HyD – Along Expressway of HKLR | Photo P1- Serious weeds affecting planted species were observed. | Photo P2 - Plants with unsatisfied condition (i.e. unhealthy plants) were observed. | |
| LCSD | Photo P3 - Trees with unsatisfied condition (i.e. fallen tree) were observed. Between Flight Training Centre and HMA | Photo P4 - Trees with unsatisfied condition (i.e. fallen tree) were observed. Between Flight Training Centre and HMA | Photo P5 - Trees with unsatisfied condition (i.e. fallen tree) were observed. Between Flight Training Centre and HMA |

Photo P6 - Trees with unsatisfied condition (i.e. fallen Photo P7 - Plants with unsatisfied condition were Photo P8 - Tree with unsatisfied condition (i.e. fallen tree) tree) were observed. was observed. observed. Between Flight Training Centre and HMA Between Flight Training Centre and HMA Between Flight Training Centre and HMA LCSD Photo P9 - Trees with unsatisfied condition (i.e. fallen Photo P10 - Tree with unsatisfied condition (i.e. fallen Photo P11 - Trees with unsatisfied condition (i.e. fallen tree) was observed. tree) were observed. tree) were observed. Next to Shaft 3 Next to Shaft 3 Next to Shaft 3

| LCSD | Photo P12 - Trees with unsatisfied condition (i.e. fallen tree) were observed. Next to Shaft 3 | Photo P13 - Tree with unsatisfied condition (i.e. fallen tree) was observed. Next to Shaft 3 | |
|---|---|---|--|
| TD / Others – Next to HMA Admiration Building | Photo P14 - Serious weeds affecting planted species were observed. | | |

| AAHK – Along Airport Road | Photo P15 - Plants with unsatisfied condition were observed. | |
|------------------------------|--|--|
| | | |
| | | |
| | | |
| | | |

Recent Condition on Site



Photo 01: LCSD Area - Zone G



Photo 02: LCSD Area - Zone G



Photo 03: LCSD Area – Zone B



Photo 04: LCSD Area - Zone B



Photo 05: LCSD Area – Zone C



Photo 06: LCSD Area – Zone C



Photo 07: LCSD Area - Zone D



Photo 08: LCSD Area - Zone D



Photo 09: LCSD Area – Zone E



Photo 10: LCSD Area - Zone E



Photo 11: LCSD Area – Zone E




Photo 12: AA Area – Zone D

Annex A

Location Plan

Contract No. HY/2011/03 – Maintenance Authorities for Landscape Works



Annex B

Planting Schedule

AAHK LAND PLANTING SCHEDULE

| TREE PLANTING | | | | |
|---------------|--------------------|--------------|-------------------|--------------|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | SPACING (mm) |
| BV | Bauhinia variegata | 宮粉羊蹄甲 | 3500(H) x 50(DBH) | (As shown) |

| SHRUB PLANTING | | | | | | |
|----------------|----------------------|--------------|------------------|------------------|--------------|------------------|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY |
| OF | Osnabthus fragrans | 桂花 | 600(H) x 300(SP) | Ac2 | (As shown) | - |
| NO | Nerium oleander | 夾竹桃 | 600(H) x 300(SP) | Ac4 | (As shown) | - |
| BG | Bougainvillea glabra | 光葉子花 | 600(H) x 300(SP) | AG1 / As2 | 750 | $2/m^2$ |
| DC | Dhadadandran ann | 41.甲白 | 200/U) v 150/CD) | Ac3 | (As shown) | - |
| PS | Rhododendron spp. | 杜鵑 | 300(H) x 150(SP) | As2 | 480 | 5/m ² |

| TURFING | | | |
|--------------|----------------|--------------|-----------|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) |
| ZS | Zoysia sp. | 結縷草 | 150(H) |

| HYDROSEEDING | | | | | |
|--------------|------------------|--------------|--|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | | | |
| Cda | Cynodon dactylon | 百慕達草 | | | |
| Pno | Paspalum notatum | 百喜草 | | | |
| Lpe | Loium perenne | 黑麥草 | | | |

HYD LAND PLANTING SCHEDULE

| SHRUB PLANTING | | | | | | | | |
|----------------|-----------------------|--------------|-----------|-----------------------|--------------|-------------------|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | | |
| LI | Lagerstroemia indica | 細葉紫薇 | 600(H) | HG5 | 1000 | 1/m ² | | |
| RS | Rhododendron spp. | 杜鵑 | 300(H) | HG1 / HG5 / HG6 / HG7 | 380 | 8/m ² | | |
| AA | Agave angustifolia | 狹葉龍舌蘭 | 300(H) | HG3 | 700 | $2/m^2$ | | |
| IC | Ixora chinensis | 龍船花 | 300(H) | HG6 | 380 | 8/m ² | | |
| *NH | Nephrolepis hirsutula | 毛葉腎蕨 | 300(H) | HG7 | 270 | 16/m ² | | |
| | | | | | | | | |

| GROUNDCOVER PLANTING | | | | | | | |
|----------------------|-----------------------|--------------|-----------|-----------------------|--------------|------------------|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | |
| LM | Lantana montevidensis | 小葉馬纓丹 | 150(H) | HG1 / HG3 / HG4 / HG7 | 380 | 8/m ² | |

NOTES:

* Variation work request by SCI for additional planting work to increase density.

TD/OTHERS LAND PLANTING SCHEDULE

| SHRUB PLANTING | SHRUB PLANTING | | | | | | | | |
|----------------|---------------------------|--------------|-----------|------------------|--------------|-------------------|--|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | | | |
| CP | Caesalpinia pulcherrima | 洋金鳳 | 300(H) | Ms4 | 750 | $2/m^2$ | | | |
| CH | Calliandra haematocephala | 紅絨球 | 300(H) | Ms4 | 750 | $2/m^2$ | | | |
| MA | Malvaviscus arboreus var. | 懸鈴花 | 300(H) | Ms4 | 750 | $2/m^2$ | | | |
| HS | Hippeastrum spp. | 朱頂紅 | 300(H) | MG7 | 350 | 10/m ² | | | |
| IT | Iris tectorum | 鳶尾 | 300(H) | MG7 | 240 | 20/m ² | | | |
| NH | Nephrolepis hirsutula | 毛葉腎蕨 | 300(H) | MG7 / Ms4 | 450 | 6/m ² | | | |
| SR | Strelitzia reginae | 鶴望蘭 | 300(H) | MG7 | 480 | 5/m ² | | | |

| GROUNDCOVER PLANTING | | | | | | | | |
|----------------------|-------------------------------|--------------|-----------|------------------|--------------|------------------|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | | |
| TS | Tradescantia spathacea'Dwarf' | 紫露草 (矮蚌花) | 150(H) | Ms4 | 450 | 6/m ² | | |
| SP | Syngonium podophyllum | 合果芋 | 150(H) | MG7 | 480 | 5/m ² | | |

| CLIMBER PLANTING | | | | | | | | |
|------------------|-------------------------|--------------|-----------|------------------|--------------|------------------|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | | |
| EA | Epipremnum aureum | 綠蘿 | 600(L) | Ms4 | 450 | 6/m ² | | |
| EA Epipreminum | Lpipremilani aureum | 徐水糸隹 | 000(L) | Mz1 | 500 | - | | |
| FP | Ficus pumila | 薜荔 | 600(L) | Mz1 | 500 | - | | |

| TURFING | | | |
|--------------|----------------|--------------|-----------|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) |
| ZS | Zoysia sp. | 結縷草 | 150(H) |

| HYDROSEEDING | | | | | | |
|--------------|------------------|--------------|--|--|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | | | | |
| Cda | Cynodon dactylon | 百慕達草 | | | | |
| Pno | Paspalum notatum | 百喜草 | | | | |
| Lpe | Loium perenne | 黑麥草 | | | | |

LCSD LAND PLANTING SCHEDULE

| TREE PLANTING | | | | | | | | |
|---------------|---------------------------------|--------------|-------------------|--------------|--|--|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | SPACING (mm) | | | | |
| BV | Bauhinia variegata | 宮粉羊蹄甲 | 3500(H) x 75(DBH) | (As shown) | | | | |
| TM | Terminalia mantaly | 小葉欖仁樹 | 3500(H) x 75(DBH) | (As shown) | | | | |
| AL | Albizia lebbek | 大葉合歡 | 3500(H) x 75(DBH) | (As shown) | | | | |
| SS | Senna siamea | 鐵刀木 | 3500(H) x 75(DBH) | (As shown) | | | | |
| BX | Bauhinia variegata var. Candida | 白花洋紫荊 | 3500(H) x 75(DBH) | (As shown) | | | | |
| BP | Bauhinia purpurea | 紅花羊蹄甲 | 3500(H) x 75(DBH) | (As shown) | | | | |
| PR | Plumeria rubra | 雞蛋花 | 2000(H) x 25(DBH) | (As shown) | | | | |
| GR | Grevillea robusta | 銀樺 | 2000(H) x 25(DBH) | (As shown) | | | | |
| CV | Callistemon viminalis | 串錢柳 | 2000(H) x 25(DBH) | (As shown) | | | | |
| TC | Tabebuia chrysantha | 黃花風鈴木 | 2000(H) x 25(DBH) | (As shown) | | | | |
| TP | Thespesia populnea | 恒春黃槿 | 2000(H) x 25(DBH) | (As shown) | | | | |
| AC | Acacia confusa | 臺灣相思 | 150 - 900(H) | (As shown) | | | | |
| RM | Ravenala madagascariensis | 旅人蕉 | 2500(H) | (As shown) | | | | |
| CO | Caryota mitis | 魚尾葵 | 2500(H) | (As shown) | | | | |
| PL | Phoenix Ioureiroi | 刺葵 | 2500(H) | (As shown) | | | | |
| SN | Strelitzia nicolai | 大鶴望蘭 | 2500(H) | (As shown) | | | | |

LCSD LAND PLANTING SCHEDULE

| SHRUB PLANTIN | SHRUB PLANTING | | | | | | | | |
|---------------|-----------------------------------|--------------|-----------|------------------|--------------|-------------------|--|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | | | |
| AG | Agave americana | 龍舌蘭 | 300(H) | LG4 | 1000 | 1/m ² | | | |
| AA | Agave angustifolia | 狹葉龍舌蘭 | 300(H) | LG3 | 1000 | 1/m ² | | | |
| BG | Bougainvillea glabra | ルギフサ | 300(H) | LG1 | 750 | 2/m ² | | | |
| В | bougaiiiviilea giabra | 光葉子花 | 300(11) | LG8 | 1000 | 1/m ² | | | |
| CU | Cuphea hyssopifolia 細葉雪茄花 300(H) | LT5 | 450 | 6/m ² | | | | | |
| 00 | Сирпеа пузѕорнона | 本書加化 | l | Ls3 | 380 | 8/m ² | | | |
| HR | Hibiscus rosa-sinensis 大紅花 300(H) | LT4 | 750 | 2/m ² | | | | | |
| HIK | 1 11012002 1029-2111611212 | 八 於上 1 G | 300(11) | LG5 | 1000 | 1/m ² | | | |
| HS | Hippeastrum spp. | 朱頂紅 | 300(H) | LG7 | 270 | 16/m ² | | | |
| IT | Iris tectorum | 鳶尾 | 300(H) | LG7 / Ls2 | 215 | 25/m ² | | | |
| 1 | Lagaratroomia indica | 細葉紫薇 | 300(H) | LT4 | 750 | 2/m ² | | | |
| LI | Lagerstroemia indica | <u> </u> | 300(11) | Ls2 | 1000 | 1/m ² | | | |
| MA | Malvaviscus arboreus var. | 懸鈴花 | 300(H) | LT4 | 750 | 2/m ² | | | |
| NH | Nanhralania hirautula | 毛葉腎蕨 | 300(H) | LG7 / Ls3 | 380 | 8/m ² | | | |
| INIT | Nephrolepis hirsutula | 七条月熈 | 300(H) | LG8 | 1000 | 1/m ² | | | |
| NO | Nerium oleander | 夾竹桃 | 300(H) | LT4 | 750 | 2/m ² | | | |
| | | | | LT1 | 550 | 4/m ² | | | |
| PM | Phyllanthus myrtifolius | 錫蘭葉下珠 | 300(H) | LT2 | 380 | 8/m ² | | | |
| | | | | Ls3 | 480 | 5/m ² | | | |
| RS | Phododondron can | 杜鵑 | 300/П/ | LT3 | 600 | 3/m ² | | | |
| | Rhododendron spp. | 11年月前 | 300(H) | LG6 / Ls2 / Ls3 | 380 | 8/m ² | | | |
| SR | Strelitzia reginae | 鶴望蘭 | 300(H) | LG7 / Ls2 | 480 | 5/m ² | | | |

LCSD LAND PLANTING SCHEDULE

| GROUNDCOVER | GROUNDCOVER PLANTING | | | | | | | | |
|--------------|-------------------------------|--------------|-----------|-------------------------------|--------------|-------------------|--|--|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | | | |
| OJ | Ophiopogon japonicus | 麥冬 | 150(H) | LG3 / LG4 / LG6 | 240 | 20/m ² | | | |
| SP | Syngonium podophyllum | 合果芋 | 150(H) | LG7 | 360 | 9/m ² | | | |
| TS | Tradescantia spathacea'Dwarf' | 练 <u>性</u> | 150(H) | LG1 / LG5 | 350 | 10/m ² | | | |
| | тайеѕсаниа ѕраинасеа Джан | /女 叶 1 G | 150(11) | LG8 | 1000 | 1/m ² | | | |
| | Wedelia trilobata | 蟛蜞菊 | | LG2 | 450 | 6/m ² | | | |
| WT | | | 150(H) | *LG2 in Planter L22 to L26 | 225 | 23/m ² | | | |
| ZC | Zephyranthes Candida | 蔥蓮 | 150(H) | LG3 | 240 | 20/m ² | | | |
| ZR | Zephyranthes rosea | 玫瑰蔥蓮 | 150(H) | LG4 / LG6 | 240 | 20/m ² | | | |
| TS1 | Tradescantia spathacea | 大蚌花 | 150(H) | *LG5 in Planter L22 to L26 | 175 | 38/m ² | | | |

| CLIMBER PLANTING | | | | | | | |
|------------------|-------------------|--------------|-----------|------------------|--------------|------------------|--|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) | Planting Pattern | SPACING (mm) | UNIT QTY | |
| EA | Epipremnum aureum | 綠蘿 | 600(L) | LG8 | 1000 | 1/m ² | |

| TURFING | | | |
|--------------|----------------|--------------|-----------|
| SPECIES CODE | BOTANICAL NAME | CHINESE NAME | SIZE (mm) |
| ZS | Zoysia sp. | 結縷草 | 150(H) |

NOTES:

* Variation work request by SCI for additional planting work to increase density.

Contract No. HY/2011/03 - Establishment Works of Soft Landscape Works of HyD/LU




Planting Area:

- A. Along expressway of HKLR
- B. Tunnel SHT West Portal Slope
- C. Others

Contract No. HY/2011/03 – Establishment Works of Soft Landscape Works of LCSD Lands A G В Planting Area:

| Planting Alea. |
|--|
| A. Along Chek Lap Kok Road & Tung Wing Road |
| B. Along Coastal Maintenance Tracks |
| C. Above Tunnel SHT East Portal |
| D. Triangular Planting Area between CNAC Tower and HMA |
| E. Between Flight Training Centre and HMA |
| F. Next to HMA |
| G. Next to Shaft 3 |

Contract No. HY/2011/03 - Establishment Works of Soft Landscape Works of TD or Others Area



Planting Area:

- A. Next to HMA Administration Building
- B. Along Ramps M014 and M015
- C. Turf areas at Tunnel SHT East Portal
- D. Vertical Planting along Walls of Tunnel SHT East Portal

