
FILE: 3M64 (Rev.00) Layout HZMB - (3M64 Rolling Prog) 3-Months Rolling Programme (ER Part 5 & SCC 27(9)) Sheet 1 of 7 TASK filters: 3M63, 3M64, HZMB No Level Effort (Sep 2017 to Nov 2017) Activity ID Activity Name 10 | 17 | 24 08 | 15 | 3 MONTHS PROGRAMME HY/2011/03 (Sep 2017 to Nov 2017)(Rev0) WORKS IN SOUTH AREA - CH 13+516 to CH 15+050 (SCENIC HILL TUNNEL, MT & CCT) **Reclamation Works** Outstanding Reclamation Works - SWCH 0+000 to SWCH 0+450 Seawall Construction SWCH 0+000 to SWCH 0+080 - 80m SW1550 South Area - Seawall, Trimming & Laying Geotextile along seawall line South Area - Seawall, Trimming & Laying Geotextile along seawall line South Area - Seawall, Rockfill Core SW1560 South Area - Seawall, Rockfill Core South Alea - Seawall, Underlayer Rock SW1570 South Area - Seawall, Underlayer Rock South Area - Seawal , Rock armour (1st layer) South Area - Seawall, Rock armour (1st layer) SW1580 SWCH 0+080 to SWCH 0+150 - 70m South Area - Seawall, Trimming & Laying Geotextile along seawall line SW1590 South Area - Seawall, Trimming & Laying Geotextile along seawall line SW1640 South Area - Seawall, Rockfill Core South Area - Seawall, Rockfill Core SW1650 South Area - Seawall, Underlayer Rock South Alea - Seawall, Underlayer Rock South Airea - Seawal, Rock armour (1st layer) SW1660 South Area - Seawall, Rock armour (1st layer) Area 1: Outstanding Remedial Works to Seawall - SWCH 0+530 to SWCH 0+800 (270m) **Permanent Seawall** A1143 South Area Remedial Works - Seawall, Rockfill core A1123 South Area Remedial Works - Seawall, Underlayer Rock A1133 South Area Remedial Works - Seawall, Rock armour (1st layer) South Area Remedial Works - Seawall, Rock armour (1st layer) **PR10 Box Culvert Construction** Pre-Work Backfilling from Shaft 3 A4990 Backfilling from Shaft 3 A5000 Mass Filling to Blinding Level Mass Filling to Blinding Level A5010 Blinding layer placement (by other sub-contractor) Blinding layer placement (by other sub-contractor) Spill Trap (Stage 1) Structure Base Slab Outer Formwork Erection Outer Formwork Erection A238784 A238794 Rebar Fixing A238804 Kicker Formwork Erection Kicker Formwork Erection A238814 Concreting Concreting Wall & Top Slab A238824 Falsework Erection Falsework Erection A238834 Rebar Fixing Rebar Fixing Formwork Erection A238844 Formwork Erection Concreting A238854 Concreting PR10 Box Culvert Extension (Stage 1) Structure Construction (Bay 1-6) Bay 1 (7.79m length) Base Slab Outer Formwork Erection A4860 Outer Formwork Erection Rebar Fixing A4870 Rebar Fixing A4930 Kicker Formwork Erection Kicker Formwork Concreting A4940 Concreting A5020 Concreting Concreting Wall & Top Slab A4950 Falsework Erection A4960 Rebar Fixing Rebar Fixing A4970 Formwork Erection Formwork Er Bay 2 (12m length) Base Slab A238304 Outer Formwork Erection Outer Formwork Erection Rebar Fixing A238314 Rebar Fixing Kicker Formw A238324 Kicker Formwork Erection Bay 4 (19.65m length) Outer Formwork Erection A238464 Outer Formwork Erection A238474 Rebar Fixing Rebar Fixing Kicker Formwork Erection A238484 Kicker Formwork Erection Concreting A238494 Concreting Wall & Top Slab Falsework Erection A238504 Falsework Erection A238514 Rebar Fixing Rebar Fixing A238524 Formwork Erection Formwork Erection Concreting A238534 Concreting Bay 5 (10m length) Base Slab A238544 Outer Formwork Erection Outer Formwork Erection A238554 Rebar Fixing A238564 Kicker Formwork Erection Kicker Formwork Erection A238574 Concreting Concreting Wall & Top Slab A238584 Falsework Erection Falsework Erection Rebar Fixing A238594 Rebar Fixing A238604 Formwork Erection Formwork Erection Concreting A238614 Concreting Bay 6 (9.454m length) Base Slab A238624 Outer Formwork Erection Outer Formwork Erection A238634 Rebar Fixing Kicker Formwork Erection A238644 Kicker Formwork Erection A238654 Concreting Concreting Wall & Top Slab A238664 Falsework Erection A238674 Rebar Fixing Rebar Fixing A238684 Formwork Erection Formwork Erection A238694 Concreting Concreting Bay 7-8 (9.155m length) Base Slab Outer Formwork Erection A238704 Outer Formwork Erection A238714 Rebar Fixing Rebar Fixing A238724 Kicker Formwork Erection Kicker Formwork Erection Concreting A238734 Concreting Wall & Top Slab A238744 Falsework Erection Falsework Erection A238754 Rebar Fixing Rebar Fixing Formwork Erection A238764 Formwork Erection Concreting A238774 Concreting Reinstatement for temporary diversion, to Highway (Stage 2) Reinstatement for Bay 1-2 A238864 Isolation panel installation Isolation panel installation Dewatering A238874 Coring holes on existing box culvert for rebar lapping A238884 Coring holes on existing box culvert for rebar lapping Base Slab A238894 Outer Formwork Erection Outer Formwork Erection Rebar Fixing Rebar Fixing A238904 A238914 Kicker Formwork Erection Kicker Formwork Erection Concreting A238924 China State Construction Engineering (Hong Kong) Ltd -Prepared by MM Works Programme Date Revision Checked Approved Works Programme Contract No. HY/2011/03 - HZMB, Hong Kong Link Road 13-Sep-17 WC SYT ♦ Works Programme 中国连条人在(有人)
CHINA STATE CONSTRUCTION ENGRG. (HONG KONG) LTD. 中國建築工程(春港)有限公司 Milestone , Section between Scenic Hill and HKBCF Milestone Works Programme



FILE: 3M64 (Rev.00) Layout HZMB - (3M64 Rolling Prog) 3-Months Rolling Programme (ER Part 5 & SCC 27(9)) Sheet 3 of 7 TASK filters: 3M63, 3M64, HZMB No Level Effort (Sep 2017 to Nov 2017) Activity ID Activity Name 10 17 24 01 08 15 22 29 05 12 Shaft 3 (incl North & South Shaft) - RC Structure - wall & OHVD, T001 area (bay 6/6) Shaft 3 (incl North & South Shaft) - RC Structure - wall & OHVD, T001 area (bay 6/6) CCT Works over Reclaimed Area at Ch 14+212 to Ch 15+050 (828m) CCT Works - on New Reclamation [490m Approx.] CCT Works in Remaining Section [325m Approx.][Ch 14+375 to Ch 14+700] Civil & Structurals Works ELS - Tunnel SHT- C&CT (T1.9.1 + Ext. Ch14+315 to Ch14+452/(Ch14+322 to Ch14+474) CCT RC Works(T1.9.1+Extension) T002 (1.9.1) - Roadworks (Road formation, Surfacing and Road Marking) SHT9720-160 SHT C&CT (T1.9.1) - T002 - Road marking, furnitures, 1st half SHT C&CT (T1.9.1) - T002 - Road marking, furnitures, 1sthaff SHT9720-170 SHT C&CT (T1.9.1) - T002 - Road marking, furnitures, remaining half SHT C&CT (T1.9:1) - 70:02 - Road marking, furnitures, remaining half [001 (1.9.1) - Roadworks (Road formation, Surfacing and Road marking) SHT9730-110 SHT C&CT (T1.9.1) - T001 - Road formation (mass concrete), 2nd half SHT9730-120 SHT C&CT (T1.9.1) - T001 - Road surfacing (base course), 1st half SHT C&CT (T1.9.1) - T001 - Road surfacing (base course), 1st half SHT C&CT (T1.9.1) - T0.01 - Road surfacing (base course), remaining hal SHT9730-130 | SHT C&CT (T1.9.1) - T001 - Road surfacing (base course), remaining half SHT, C&CT (T1,9.1) - T0 01 - Road surfacing (stone, mastic asphalt), 1st half SHT9730-140 SHT C&CT (T1.9.1) - T001 - Road surfacing (stone mastic asphalt), 1st half SHIT C&CT (11,9.1) - T001 - Road surfacing (stone mastic asphalt), remaining half SHT9730-150 SHT C&CT (T1.9.1) - T001 - Road surfacing (stone mastic asphalt), remaining half SHT C&CT (T1.9.1) - T001 - Road marking, furnitures 1st half SHT9730-160 SHT C&CT (T1.9.1) - T001 - Road marking, furnitures, 1st half SHT C&CT (11.9.1) - 1001 - Road marking, furniture's SHT9730-170 SHT C&CT (T1.9.1) - T001 - Road marking, furnitures, remaining half ELS - Tunnel SHT- C&CT (T1.12 Ch 14+264 to Ch 14+315)/(Ch 14+257 to Ch 14+322) T001 RC Structure T001 - Utilities Trough SHT7710 SHT C&CT (T1.12) - T001 Utility Trough, 27/54m SHT C&CT (T1:12) - T001 Utility Trough, 27/54m SHT C&CT (T1.12);- 7001 Utility Trough, 54/54m SHT C&CT (T1.12) - T001 Utility Trough, 54/54m T001 - Black Paint SHT C&CT (T1.12) - T001 Black Paint (54m) SHT7715 ELS - Tunnel SHT- C&CT (T1.9.2 Ch 14+452 to Ch 14+597)/(Ch 14+474 to Ch 14+612) Excavation & Lateral Support (T1.9.2) T001 (1.9.2) - Utilities Trough SHT1868-795 SHT C&CT (T1.9.2) - T001 (100m/148m) SHT C&CT (T1,9.2) - T001 (100m/148m) SHT C&CT (T1.9.2) - T001 (148 m/ 148 m) SHT1868-805 SHT C&CT (T1.9.2) - T001 (148m/148m) CCT Works for HAT East w/ Emergency Pedestrian Passage HAT Plant Building and Cut & Cover Tunnel, East Area [303m Approx.] RC CCT Work (Ch 0+768 to Ch0+940) Backfilling (Ch0+768 to Ch0+940) HAT East C&CT - Waterproof, Backfilling and strut removal 150m/172m length HAT East C&CT - Waterproof, Backfilling and strut removal 150m/172m length HAT East C&CT - Waterproof, Backfilling and strut removal 172m/172m length HAT1869-120 HAT East C&CT - Waterproof, Backfilling and strut removal 172m/172m length RC Works Access Shaft and Columns to GL **Access Shaft** HAT1071-160 HAT Maint. Access Shaft - Wall & Top Slab -Formworks, rebars, concrete, 2/3 bays(service shaft) HAT Maint, Access Shaft'- Wall & Top Slab -Formworks, rebars, concrete, 2/3 bays(service shaft) HAT Maint. Access Shaft - Wall & Top Slab -Formworks, rebars, concrete, 3/3 bays HAT Maint Access Shaft - Wall & Top Slab - Formworks, rebars, concrete, 3/3 bays RC CCT Work(Ch 0+940 to Ch 1+140) Base slab(Ch 0+940 to Ch 1+140) HAT1868-975 Base Slab - Formworks.Rebars, Concrete, 200m / 200m Wall Stem + Top Slab (Ch 0+940 to Ch 1+140) HAT1868-1005 Wall stem + Top slab - Formworks, Rebars, Concrete, 120m / 200m HAT1868-1015 Wall stem + Top slab - Formworks, Rebars, Concrete, 160m / 200m HAT1868-1025 Wall stem + Top slab - Formworks Rebars, Concrete, 200m / 200m HAT (Ch 0+768 to 1+195 -Utility Trough, E&M, TCSS (Works under Stage 7 & Section 2) HAT - E&M & Utilities Installation HAT [East O&CT] - Building services, 1st part HAT [East C&CT] - Building services, 1st part A239174 HAT East C&CT - Building services, 2nd part A239274 HAT [East C&CT] - Building services, 2nd part HAT [East C&CT] - Building services, 3rdpart HAT East C&CT - Building services, 3rdpart A239284 HAT [East C&CT] - signal cables, 1st half A239184 HAT [East C&CT] - signal A239314 HAT [East C&CT] - signal cables, remaining half HAT - Tunnel Cladding HAT [East C&CT] - Cladding brackets, LHS, 1st half A239124 **HAT Utility Trough Utility Trough** HAT [East C&CT] - Utility trough, 1st 75m A238274 HAT [East C&CT] - Utility trough, 1st 75m HAT [East C&CT] - Utility trough, next 75m (Cum = 150m) A239244 HAT [East C&CT] - Utility trough, next 75m (Cum =150m) A238214 HAT [East C&CT] - Utility trough, next 75m (Cum =225m) HAT [East C&CT] - Utility frough, next 75m (Cum =225m) HAT [East C&CT] - Utility trough, next 80m (Cum =305m) HAT [East C&CT] - Utility A238224 TCSS Civil Prov. Works (under Stage 7) A239254 HAT [East C&CT] - TCSS civil prov. works, 1st 75 m (inside tunnel) HAT [East C&CT] - TCSS civil prov. works, 1st 75 m (inside tunnel) HAT [East C&CT] - TCSS civil prov. works, next 75 m, (Qum. = 150m) (inside HAT [East C&CT] - TCSS civil prov. works, next 75 m, (Cum. = 150m) (inside tunnel) A239264 A238264 HAT [East C&CT] - TCSS civil prov. works, next 75 m, (Cum. = 225m) (inside tunnel) HAT [East C&CT] - TCSS civil prov. works, next 75 m, (Cu HAT [East C&CT] - TCSS civil prov. works, next 80 m, (Cum. = 305m) (inside tunnel) ■ HAT [East C&CT] - TCSS civil prov A239104 HAT [East C&CT] TCSS civil prov. works, east ramp area A239114 Box Culvert Extension to outfall PR14 (457m Approx.) Box Culvert Extension to outfall PR14 (South Area, Bay S1 to S22) BC1110-211 PR14 South Area - Backfiling works, 19/22 bays PR14 South Area - Backtiling works, 19/22 bays BC1110-122 PR14 South Area - Base Slab (formwork, rebars, concrete), 22/22 bays PR14 South Are a - Wall & roof slab (formwork, tebars, shuttering wall, concrete), 22/22 bays BC1110-142 PR14 South Are a - Wall & roof slab (formwork, rebars, shuttering wall, concrete), 22/22 bays BC1110-181 PR14 South Area - Connection to Existing outfall PR14 South Area - Connection to Existing outfall PR14 South Area - Backfiling works, 22/22 bays BC1110-221 PR14 South Area - Backfiling works, 22/22 bays Security Fence LR.2010-76 Security Fence - Fence installation and fixing - 150/1,098 m Security Fence - Fence installation and fixing 150/1,098 m LR.2010-22 Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 150/368 nos. Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 150/368 hos Security Fence - Excavation, backfilling to formation & compaction 200/368 nos. LR.2010-3 Security Fence - Excavation, backfilling to formation & compaction 200/368 nos. LR.2010-4 Security Fence - Excavation, backfilling to formation & compaction 250/368 nos. Security Fence Excavation, backfilling to formation & compaction 250/368 nos. Security Fence - Footing (bottom & upper part), Formworks, rebais, concrete - 200/368 nos. LR.2010-33 Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 200/368 nos. Security Fence - Fence installation and fixing - 300/1,098 m. LR.2010-86 Security Fence - Fence installation and fixing - 300/1,098 m. LR.2010-5 Security Fence - Excavation, backfilling to formation & compaction 300/368 nos. Security Fence - Excavation, backfilling to formation & compaction 300/368 nos. Security Fence - Footing (bottom & upperpart), Formworks, rebars, concrete - 250/368 nos. Security Fence Footing (bottom & upperpart), Formworks, repars, concrete - 250/368 no LR.2010-44 Security Fence - Fence installation and fixing - 450/1,098 m. Security Fence - Fence installation and fixing - 450/1,098 m. LR.2010-96 LR.2010-6 Security Fence - Excavation, backfilling to formation & compaction 368/368 nos. Security Fence - Excavation, backfilling to formation & compaction 368/368 nos. LR.2010-106 Security Fence - Fence installation and fixing - 600/1,098 m. Security Fence - Fence installation and fixing - 600/1,098 m. Security Fence - Footing (bottom part), Formworks, repars, concrete - 300/368 nos LR.2010-55 Security Fence - Footing (bottom part), Formworks, rebars, concrete - 300/368 nos. LR.2010-116 Security Fence - Fence installation and fixing - 736/1,098 m. Security Fence - Fence installation and fixing -736/1,098 m. Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 368/368 nos. Security Fence - Footing (bottom & upper part), Formworks, rebars, concre LR.2010-66 Security Fence - Fence installation and fixing - 886/1,098 m. Security Fence - Fence installation and fixing -886/1,098 m. LR.2010-126 Security Fence Fence installation and fixing - 1,098/1,098 m. LR.2010-136 Security Fence - Fence installation and fixing - 1,098/1,098 m WORKS IN HAM(HIGHWAY OPERATION & MAINTENANCE AREA) & HAT CCT **Administration Building ABWF & External Works Builder Works** HMA4130 HMA Admin. Bldg. - Builders works for rel.Rms for TCSS (KD7-Stage 6), 2nd part HMA Admin, Bldg. - Builders works for rel. Rms for TCSS (KD7-Stage 6), 2nd part HMA Admin, Bidg.-1/F-ail other area (blk work-rendering; screeding; part, walls, waterproofing (incl. H2D test) 3rd part HMA4102 HMA Admin. Bldg.- 1/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test) 3rd part HIMA Admin. Bldg.- R/F-all other area (blk work+rendering, screeding, part. walls; waterproofing(incl. H2Q test) 2nd part HMA4121 HMA Admin. Bldg.- R/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test) 2nd part HMA4092 HMA Admin. Bldg.- G/F- all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test)3rd Part HMA Admin. Bldg.- G/F, all other area (blk work+rendering, screeding, part. walls; waterproofing(incl. H2O test)3rd Part. HMA Admin. Bldg.- R/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test),3rd part HMA Admin, Biog.- R/F-all other area (blk work-rendering; screeding; part, walls; waterproofing (incl. H2O test), 3 HMA4122 **External Works** HMA4040 HMA Admin. Bldg. - Eastern Face - Glass curtain wall, doors, windows (incl. water test) HIMA Admin, Bldg. - Eastern Face - Glass curtain wall, doors, windows (incl. water test) HMA4200 HMA Admin. Bldg. - Roof skylight +other external finishes (incl. water test) HMA Admin. Bldg. - Roof skylight +other external finishes (incl. water test) HMA4070 HMA Admin. Bldg. - Southern Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Southern Face - Glass curtain wall, doors, windows (incl. water test) HIMA Admin. Bldg. - Northern Face - Glass curtain wall, doors, windows (incl. water test) HMA4150 HMA Admin. Bldg. - Northern Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin, Bldg. - Western Face - Glass curtain wall, doors, windows (incl. water test) HMA4140 HMA Admin. Bldg. - Western Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Eastern Face - Spray granite textured coating HMA Admin, Bldg. - Eastern Face - Spray granite textured coating HMA4160 HMA Admin. Bldg. - Southern Face - Spray granite textured coating HMA Admin. Bldg. - Southern Face - Spray granite textured coating HMA4170 HMA4180 HMA Admin. Bldg. - Western Face - Spray granite textured coating HMA Admin. Bldg. - Western Face - Spray granite textured coating HMA Admin, Bldg. - Northern Face - Spray granite textured coating HMA4190 HMA Admin. Bldg. - Northern Face - Spray granite textured coating **E&M Works Building Services** 1st Fix HMA Admin. Bldg. - Building Services 1st fix - 1/F - East Zone HMA Admin, Bldg, - Building Services 1st fix - 1/F - East Zone HMA4214 HIMA Admin. Bldg. - Building Services 1st fix - G/F - East Zone HMA4210 HMA Admin. Bldg. - Building Services 1st fix - G/F - East Zone

