(Jan 2018 to Mar 2018) Activity ID 3 MONTHS PROGRAMME HY/2011/03 (Jan 2018 to Mar 2018)(Rev0) WORKS IN SOUTH AREA - CH 13+516 to CH 15+050 (SCENIC HILL TUNNEL, MT & CCT) Outstanding Reclamation Works - SWCH 0+000 to SWCH 0+450 **Seawall Construction** SWCH 0+000 to SWCH 0+080 - 80m South Area - Seawall, Trimming & Laying Geotextile along seawall line South Area - Seawall, Trimming & Laying Geotextile along seawall line SW1560 South Area - Seawall, Rockfill Core South Area - Seawall, Rockfill Core SW1570 South Area - Seawall, Underlayer Rock South Area - Seawall, Underlayer Rock South Area - Seawall, Rock armour (†st layer) South Area - Seawall, Rock armour (1st layer) SW1580 SWCH 0+080 to SWCH 0+150 - 70m SW1590 South Area - Seawall, Trimming & Laying Geotextile along seawall line South Area - Seawall, Trimming & Laying Geotextile along seawall line South Area - Seawall, Rockfill Core SW1640 South Area - Seawall, Rockfill Core SW1650 South Area - Seawall, Underlayer Rock South Area - Seawall, Underlayer Rock South Area - Seawall, Rock armour (1st layer) South Area - Seawall, Rock armour (1st layer) SW1660 **PR10 Box Culvert Construction** Pre-Work Backfilling from Shaft 3 A4990 Backfilling from Shaft 3 A5003 Sheet Piling Works, 362/362 nos Sheet Piling Works, 362/362 nos A5010 Blinding layer placement (by other sub-contractor) Blinding layer placement (by other sub-contractor) Spill Trap (Stage 1) Wall & Top Slab A238824 Falsework Erection A238834 Rebar Fixing A238844 Formwork Erection A238854 PR10 Box Culvert Extension (Stage 1) Structure Construction (Bay 1-6) Bay 1 (7.79m length) **Base Slab** Outer Formwork Erection A4860 A4870 Kicker Formwork Frection A4930 A4940 Concreting Wall & Top Slab Falsework Erection Palsework Erection A4950 A4960 Rebar Fixing A4970 Formwork Erection Formwork Erection Concreting A4980 Concreting Bay 2 (12m length) Base Slab A238304 Outer Formwork Erection Outer Formwork Erection Rebar Fixing Rebar Fixing A238314 A238324 Kicker Formwork Erection Kicker Formwork Erection Concreting: A238334 Concreting Wall & Top Slab A238344 Falsework Erection Falsework Erection A238354 Rebar Fixing Rebar Fixing A238364 Formwork Erection Formwork Erection Concreting Concreting A238374 Bay 3 (12m length) Base Slab Outer Formwork Frection Outer Formwork Erection A238384 A238394 Rebar Fixing Rebar Fixing Kicker Formwork Erection A238404 Kicker Formwork Erection A238414 Concreting Concreting Wall & Top Slab Falsework Erection Falsework Erection A238424 A238434 Rebar Fixing A238444 Formwork Erection Formwork Erection A238454 Concreting Bay 4 (19.65m length) Base Slab A238464 Outer Formwork Erection Outer Formwork Erection Rebar Fixing Rebar Fixing A238474 A238484 Kicker Formwork Erection Concreting A238494 Concreting Wall & Top Slab A238504 Falsework Erection Falsework Erection Rebar Fixing A238514 Rebar Fixing A238524 Formwork Erection Formwork Erection Concreting A238534 Concreting Bay 5 (10m length) Base Slab Outer Formwork Erection Outer Formwork Erection A238544 A238554 Rebar Fixing Kicker Formwork Election
Concreting Kicker Formwork Erection A238564 A238574 Concreting Wall & Top Slab Falsework Erection Falsework Erection A238584 A238594 Rebar Fixing Formwork Erection
Concreting A238604 Formwork Erection A238614 Concreting Bay 6 (9.454m length) Base Slab A238624 Outer Formwork Erection Outer Formwork Erection Rebar Fixing Rebar Fixing A238634 A238644 Kicker Formwork Erection Kicker Formwork Erection Concreting A238654 Concreting Wall & Top Slab A238664 Falsework Erection Falsework Erection A238674 Rebar Fixing Rebar Fixing A238684 Formwork Erection Formwork Erection Concreting A238694 Concreting Bay 7-8 (9.155m length) **Base Slab** Outer Formwork Erection Outer Formwork Erection A238704 A238714 Rebar Fixing Rebar Fixing Kicker Formwork Erection Kicker Formwork Erection A238724 A238734 Concreting Concreting Wall & Top Slab A238744 Falsework Erection Falsework Erection A238754 Rebar Fixing Rebar Fixing Formwork Erection
Concreting A238764 Formwork Erection A238774 Reinstatement for temporary diversion, to Highway (Stage 2) Reinstatement for Bay 1-2 A238864 Isolation panel installation Isolation panel installation Dewatering A238874 Dewatering A238884 Coring holes on existing box culvert for rebar lapping Coring hales on existing box culvert for rebar lapping Prepared by MM Works Programme Works Programme China State Construction Engineering (Hong Kong) Ltd -Date Checked Approved Contract No. HY/2011/03 - HZMB, Hong Kong Link Road Works Programme SYT 06-Jan-18 WC 中國建築工程(香港)有限公司 ♦ Works Programme , Section between Scenic Hill and HKBCF CHINA STATE CONSTRUCTION ENGINEERING (HONG KONG) LTD. Milestone Milestone

3-Months Rolling Programme (ER Part 5 & SCC 27(9)

Layout HZMB - (3M68 Rolling Prog)_B

TASK filters: 3M68, HZMB No Level Effort.

FILE: 3M68 (Rev.00)

Sheet 1 of 7

FILE: 3M68 (Rev.00) 3-Months Rolling Programme (ER Part 5 & SCC 27(9) Layout HZMB - (3M68 Rolling Prog)_B Sheet 3 of 7 TASK filters: 3M68, HZMB No Level Effort. (Jan 2018 to Mar 2018) Activity ID 31 07 14 21 28 T001 (AR, AEL, Shaft 3, T1.12) - Tunnel Cladding SHT9730-200 SHT @ AR, AEL, Shaft 3 & T1.12- T001 - Cladding brackets SHT @ AR, AEL, Shaft 3 & T1.12- T001 - Cladding panels SHT9730-340 SHT @ AR, AEL, Shaft 3 & T1.12- T001 - Cladding panels T001 (AR. AEL. Shaft 3, T1.12) - E&M & Utilities Installation SHT @ AR, AEL, Shaft 3 & T1.12 - T001 - E&M works, firemain and hydrants SHT @ AR, AEL, Shaft 3 & T1.12 - T001 - E&M works, firemain and hydrants \$HT @ AR, AEL, \$haft 3 & T1.12 - \$\frac{1}{7}001 - E&M works lighting SHT @ AR, AEL, Shaft 3 & T1.12 - T001 - E&M works lighting SHT9730-210 SHT9730-370 SHT @ AR, AEL, Shaft 3 & T1.12- T001 - E&M works, other fire services equipment SHT @ AR, AEL, Shaft 3 & T.1.12- T001 - E&M works, other fire services equipment SHT @ AR, AEL, Shaft 3 & T1.12- T001 - E&M works, ventilation SHT @ AR, AEL, Shaft 3 & T1.12- T001 - E&M works, ventilation SHT9730-350 SHT9730-380 SHT @ AR, AEL, Shaft 3 & T1.12 - T001 - E&M works, T & C SHT @ AR, AEL, Shaft 3 & T1.12 - T001 - E&M works, T & C CCT T1.9.2 & T1.9.1 Utility Trough, E&M, TCSS (Stage 4a, Stage 6 & Section 1) T002 (1.9.1 & 1.9.2) - Tunnel Cladding SHT9730-270 SHT C&CT (T1.9.1 & T1.9.2) -T002 - Cladding brackets SHT C&CT (T1.9.1 & T1.9.2) -T002 - Cladding brackets SHT C&CT (T1.9.1 & T1.9.2) - T002 - Cladding panels SHT9730-280 SHT C&CT (T1.9.1 & T1.9.2) - T002 - Cladding panels T002 (1.9.1 & 1.9.2) - E&M & Utilities Installation SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, ventilation SHT9730-300 \$HT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, ventilation SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M; works, firemain and hydrants SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, firemain and hydrants SHT9730-310 SHT9730-320 SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, other fire services equipment SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, other fire services equipment SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works lighting SHT C&CT (T1.9.1 & T1.9.2) - T002 + E&M works lighting SHT9730-290 SHT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, T & C \$HT C&CT (T1.9.1 & T1.9.2) - T002 - E&M works, T & C SHT9730-330 T001 (1.9.1 & 1.9.2) - Tunnel Cladding SHT9730-180 SHT C&CT (T1.9.1 & T1.9.2) - T001 - Cladding brackets SHT C&CT (T1.9.1 & T1.9.2) - T001 - Cladding brackets SHT9730-190 SHT C&CT (T1.9.1 & T1.9.2)) - T001 - Cladding panels SHT C&CT (T1.9.1 & T1.9.2)) - T001 - Cladding panels T001 (1.9.1 & 1.9.2) - E&M & Utilities Installation SHT9730-220 SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works lighting SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works lighting SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, ventilation SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, ventilation SHT9730-230 SHT9730-240 SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, firemain and hydrants SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, firemain and hydrants SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, other fire services equipment SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, other fire services equipment SHT9730-250 SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, T & C SHT C&CT (T1.9.1 & T1.9.2) - T001 - E&M works, T & C SHT9730-260 FSD Inspection (SHT: MT & CCT Area) A10000 Submit FS 314 A10010 Submit FS 501 - Request for Inspection FS Inspection A10020 FS Inspection Issue of FS Certificate CCT Works for HAT East w/ Emergency Pedestrian Passage HAT Plant Building and Cut & Cover Tunnel, East Area [303m Approx.] RC CCT Work (Ch 0+768 to Ch0+940) Backfilling (Ch0+768 to Ch0+940) HAT East C&CT - Waterproof, Backfilling and strut removal 172m/172m length HAT East C&CT - Waterproof, Backfilling and strut removal 172m/172m length HAT1869-120 **RC Works Access Shaft and Columns to GL Access Shaft** HAT1071-160 HAT Maint. Access Shaft - Wall & Top Slab -Formworks, rebars, concrete, 2/3 bays(service shaft) HAT Maint. Access Shaft - Wall & Top Slab -Formworks, rebars, concrete, 3/3 bays RC CCT Work(Ch 0+940 to Ch 1+195) Retaining Wall (Ch 1+044 to Ch 1+182) Retaining Wall - Formworks, Rebars, Concrete, 138m / 138m HAT (Ch 0+768 to 1+195 -Utility Trough, E&M, TCSS (Works under Stage 7 & Section 2) HAT - E&M & Utilities Installation A239174 HAT [East C&CT] - Building services, 1st part HAT [East C&CT] - E&M works, lighting, 1st half A239214 A239274 HAT [East C&CT] - Building services, 2nd part A239344 HAT [East C&CT] - E&M works, lighting, 2nd half HAT [East C&CT] - E&M works, lighting, 2nd half HAT [East C&CT] - E&M works, ventilation, 1st half HAT [East C&CT] - E&M works, ventilation, 1st half A239194 A239284 HAT [East C&CT] - Building services, 3rd part HAT [East C&CT] - Building services, 3rd part HAT [East C&CT] - E&M works, other fire services eqpts., 1st half HAT [East C&CT] - E&M works, other fire services eqpts., 1st half A239224 HAT [East C&CT] - signal cables, 1st half HAT [East C&CT] - signal cables, 1st half A239184 HAT [East C&CT] - E&M works, other fire services eqpts., 2nd half HAT [East C&CT] - E&M works, other fire services egpts., 2nd half A239354 HAT [East C&CT] - E&M works, ventilation, remaining half A239324 HAT [East C&CT] + E&M works, ventilation, remaining half HAT [East C&CT] - signal cables, remaining half A239314 HAT [East C&CT] - signal cables, remaining half HAT [East C&CT] - E&M works, T & C A239234 IAT [East C&C HAT [East C&CT] - E&M works, firemain and hydrants HAT [East C& A239204 **HAT - Tunnel Cladding** A239364 HAT [East C&CT] - Setting out/Preparation & materials delivery HAT [East C&CT] - Setting out/Preparation & materials delivery A239124 HAT [East C&CT] - Cladding brackets, LHS, 1st half HAT [East C&CT] - Cladding brackets, LHS, 1st half A239134 HAT [East C&CT] - Cladding panels, LHS, remaining half HAT [East C&CT] - Cladding pane HAT [East C&CT] - Cladding brackets, RHS, 1st half A239144 **HAT Utility Trough** TCSS Civil Prov. Works (under Stage 7) HAT [East C&CT] TCSS civil prov. works, east ramp area A239114 A238264 HAT [East C&CT] - TCSS civil prov. works, next 76 m, (Cum. = 276m) (inside tunnel) **Utility Trough** HAT [East C&CT] - Utility trough, next 127m (Cum =427m) A238214 Security Fence LR.2010-76 Security Fence - Fence installation and fixing - 150/1,104 m LR.2010-22 Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 150/368 nos. LR.2010-3 Security Fence - Excavation, backfilling to formation & compaction 200/368 nos. Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 368/368 nos. LR.2010-66 Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 368/368 nos LR.2010-86 Security Fence - Fence installation and fixing - 300/1,104 m. LR.2010-4 Security Fence - Excavation, backfilling to formation & compaction 250/368 nos. LR.2010-33 Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 200/368 nos. LR.2010-96 Security Fence - Fence installation and fixing - 450/1,104 m. LR.2010-44 Security Fence - Footing (bottom & upperpart), Formworks, rebars, concrete - 250/368 nos. Security Fence - Excavation, backfilling to formation & compaction 300/368 nos. LR.2010-5 LR.2010-106 Security Fence - Fence installation and fixing - 600/1,104 m. LR.2010-6 Security Fence - Excavation, backfilling to formation & compaction 368/368 nos. LR.2010-116 Security Fence - Fence installation and fixing - 736/1,104 m. Security Fence - Footing (bottom part), Formworks, rebars, concrete - 300/368 nos. Security Fence - Footing (bottom part), Formworks, rebars, concrete - 300/368 nos LR.2010-55 LR.2010-126 Security Fence - Fence installation and fixing - 886/1,104 m. Security Fence - Fence installation and fixing - 886/1,104 m. Security Fence - Fence installation and fixing - 1,104/1,104 m. Security Fence - Fence installation and fixing - 1,104/1,104 m. LR.2010-136 WORKS IN HAM(HIGHWAY OPERATION & MAINTENANCE AREA) & HAT CCT **ABWF & External Works Builder Works** HMA Admin. Bldg. - Builders works for rel.Rms for TCSS (KD7-Stage 6), 2nd part HMA Admin. Bldg. - Builders works for rel.Rms for TCSS (KD7-Stage 6), 2nd part HMA4130 HMA Admin. Bldg.- 1/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test) 3rd part HMA Admin. Bldg. 1/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test) 3rd part HMA4102 HMA Admin. Bldg.- G/F- all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test)3rd Part HMA Admin. Bldg., G/F- all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test) 3rd Part HMA4092 HMA4122 HMA Admin. Bldg.- R/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test),3rd part HMA Admin. Bldg.: R/F-all other area (blk work+rendering; screeding; part. walls; waterproofing(incl. H2O test),3rd part **External Works** HMA4040 HMA Admin. Bldg. - Eastern Face - Glass curtain wall, doors, windows (incl. water test) HIMA Admin. Bldg. - Eastern Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Roof skylight +other external finishes (incl. water test) HMA4200 HMA Admin. Bldg. - Roof skylight +other external finishes (incl. water test) HMA4070 HMA Admin. Bldg. - Southern Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Southern Face - Glass curtain wall, doors, windows (incl. water test) HMA4150 HMA Admin. Bldg. - Northern Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Northern Face - Glass curtain wall, doors, windows (incl. water test) HMA4140 HMA Admin. Bldg. - Western Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Western Face - Glass curtain wall, doors, windows (incl. water test) HMA Admin. Bldg. - Eastern Face - Spray granite textured coating HMA4160 HMA Admin. Bldg. - Eastern Face - Spray granite textured coating HMA Admin. Bldg. - Southern Face - Spray granite textured coating HMA4170 HMA Admin. Bldg. - Southern Face - Spray granite textured coating HMA Admin. Bldg. - Western Face - Spray granite textured coating

HMA4180 HMA Admin. Bldg. - Western Face - Spray granite textured coating HMA4190 HMA Admin. Bldg. - Northern Face - Spray granite textured coating

HMA Admin. Bldg. Lift Installation - 2nd fix and lift equipment installation

Building Services

2nd Fix

E&M Works

HMA Admin. Bldg. - Building Services 2nd fix - G/F - East Zone HMA4218 HMA Admin. Bldg. - Building Services 2nd fix - G/F - West Zone HMA4220 HMA Admin. Bldg. - Building Services 2nd fix - 1/F - East Zone HMA4222 HMA Admin. Bldg. - Building Services 2nd fix - 1/F - West Zone HMA4224

Final Fix

HMA4000-120

HMA4234 HMA Admin. Bldg. - Building Services final fix - G/F - West Zone HMA Admin. Bldg. - Building Services final fix - 1/F - West Zone HMA4244 HMA Admin. Bldg. - Building Services final fix - G/F - East Zone HMA4254 HMA4264 HMA Admin. Bldg. - Building Services final fix - G/F - East Zone HMA Admin. Bldg. - Building Services Testing & Commissioning HMA4274 Lift Installation

MA Admin. Bldg. - Building Services 2nd fix - G/F - East Zone HMA Admin. Bldg. - Building Services 2nd fix - G/F - West Zone HIMA Admin. Bldg. - Building Services 2nd fix - 1/F - East Zone HMA Admin. Bldg. - Building Services 2nd fix - 1/F - West Zone

HMA Admin. Bldg. - Building Services final fix - G/F - West Zone HMA Admin. Bldg. - Building Services final fix - 1/F - West Zone HMA Admin. Bldg. - Building Services final fix - G/F - East Zone HMA Admin. Bldg. - Building Services final fix - G/F - East Zone

HMA Admin. Bldg. - Building Services Testing & Commissioning

HMA Admin. Bldg. Lift Installation - 2nd fix and lift equipment installation

HMA Admin. Bldg. - Northern Face - Spray granite textured coating

Security Fence - Fence installation & fixing, 750/900 m.

Security Fence - Fence installation & fixing, 900/900 m.

Security Fence - Fence installation & fixing, 600/900 m.

Security Fence - Fence installation & fixing, 750/900 m.

Security Fence - Fence installation & fixing, 900/900 m.

Security Fence - Footing (bottom & upper part), Formworks, rebars, concrete - 300/300 nos.

LR.2010-065

LR.2010-075

LR.2010-085

FILE: 3M68 (Rev.00) Sheet 7 of 7		3-Months Rolling Programme (ER Part 5 & SCC 27(9) (Jan 2018 to Mar 2018)		Layout HZMB - (3M68 Rolling Prog)_E TASK filters: 3M68, HZMB No Level Effort
ivity ID	Activity Name	·	2017 December	January February March
A4850	M010: Final wearing co	ourse and road marking and traffic signs, road lighting lamps & T&C, remaining half	03 10 17 24 31 07	14 21 28 04 11 18 25 04 04 04 04 04 04 04 0