


Weather condition within the reporting period varied between sunny to rainy. The overall monitoring results were not affected by weather conditions.

Major construction works undertaken within the reporting period include Additional land GI, trial pits & lab testing; Channel re-construction at Area 1; Construction of pile caps; Drainage works; Installation of pier head segment; Land piling; Pier construction; Pre-drilling works; Re-alignment of Cheung Tung Road; Relocation of MTR fence; Slope works; Tree survey, felling and transplanting; and Utility surveys.

Marine works within the reporting period include Additional marine ground investigation (GI) and laboratory testing; Construction of pile caps; Installation of pier head and deck segment; Launching gantry assembly; Marine piling; Marine platform installation and uninstallation; and Pier construction.

TSP monitoring at ASR8 was suspended on 26 November and 2 December 2016 due to rejection of access to the monitoring station.



Weather condition within the reporting period varied between sunny to rainy. The overall monitoring results were not affected by weather conditions.

Major construction works undertaken within the reporting period include Additional land GI, trial pits & lab testing; Channel re-construction at Area 1; Construction of pile caps; Drainage works; Installation of pier head segment; Land piling; Pier construction; Pre-drilling works; Re-alignment of Cheung Tung Road; Relocation of MTR fence; Slope works; Tree survey, felling and transplanting; and Utility surveys.

Marine works within the reporting period include Additional marine ground investigation (GI) and laboratory testing; Construction of pile caps; Installation of pier head and deck segment; Launching gantry assembly; Marine piling; Marine platform installation and uninstallation; and Pier construction.

TSP monitoring at ASR8 was suspended on 26 November and 2 December 2014 due to rejection of access to the monitoring station.