

MATERIALAB CONSULTANTS LIMITED

Room 723 & 725, 7/F, Block B,
Profit Industrial Building,
1-15 Kwai Fung Crescent, Kwai Fong,
Hong Kong.


Tel : (852)-24508238
Fax : (852)-24508032
Email : mcl@fugro.com

Materialab

Report No.: 0165/15/ED/0820

Figure 3

Water Quality Monitoring Stations



- LEGEND**
- IS IMPACT STATIONS
 - CS CONTROL / FAR FIELD STATIONS
 - SR SENSITIVE RECEIVERS STATIONS
 - IS IMPACT STATIONS (RELOCATED)
 - SR SENSITIVE RECEIVERS STATIONS (RELOCATED)
 - CS CONTROL / FAR FIELD STATIONS (RELOCATED)

SETTING OUT SCHEDULE

MONITORING STATIONS	CO-ORDINATES	
	EASTING	NORTHING
IS5	811579	817106
IS(M)6	812101	817873
IS7	812244	818777
IS8	814251	818412
IS(M)9	813273	818850
SR5(N)	812569	821475
IS(M)11	813362	820716
IS(M)16	814328	819497
IS17	814539	820391
SR3	810525	816456
SR4(N)	814705	817859
IS10(N)	812942	820881
SR6	805837	821818
SR7	814293	821431
SR10A	823741	823495
SR10B(N)	823683	823187
CS(M)3(N)	808814	822355
CS(M)5	817990	821129
CS4	810025	824004
CS6	817028	823992
CSA	818103	823064
IS10	812577	820670
SR5	811489	820455
CS(M)3	809989	821117