





Appendix E

Graphical Presentation of Air Quality Monitoring Results
and Construction Noise Monitoring Results





Remarks:

1. Air quality monitoring location AMS7B was temporary suspended, effective from 10 December 2020.
2. According to the email date 11 August 2021, EPD have no comment on the Proposal for Relocation of Monitoring Location AMS 7B, the monitoring location AMS 7B are proposed to be relocated by alternative monitoring location AMS 7C for air quality monitoring. The monitoring location AMS 7C has resumed air quality monitoring on 5 October 2021.



Remarks:

1. Air quality monitoring location AMS7B was temporary suspended, effective from 10 December 2020.
2. According to the email date 11 August 2021, EPD have no comment on the Proposal for Relocation of Monitoring Location AMS 7B, the monitoring location AMS 7B are proposed to be relocated by alternative monitoring location AMS 7C for air quality monitoring. The monitoring location AMS 7C has resumed air quality monitoring on 5 October 2021.



Remarks:

1. NMS2: Façade Measurement
2. NMS3C: Free-field measurement (+3dB (A) correction has been applied), reduction to 65dB (A) during school examination periods will be applied.