Summary of Site Audit in the Reporting Month

| Parameters | Date | Observations and Recommendations | Follow-up |
|-------------------------------------|--------------|---|--------------|
| Air Quality | 7 July 2021 | Observation: Temporarily stockpile should be covered. (VCP) | 8 July 2021 |
| | 15 July 2021 | Observation: Water spray should be provided at the exposed area. (SPTI) | 16 July 2021 |
| Noise | NA | | |
| Water Quality | 21 July 2021 | Observation: Stagnant water should be cleared. (VCP) | 21 July 2021 |
| | 21 July 2021 | Observation: Sandbag should be provided near the drainage to prevent surface runoff. (NPTI) | 23 July 2021 |
| | 28 July 2021 | Observation: Stagnant water should be cleared after raining. (VCP) | 28 July 2021 |
| Chemical and Waste Management | 7 July 2021 | Observation: Waste Container should be provided for good housekeeping. (VCP) | 9 July 2021 |
| | 28 July 2021 | Observation: Waste generated at the site should be cleared regularly. (VCP) | 29 July 2021 |
| Land Contamination | NA | | |
| Landscape and Visual Impact | NA | | |
| Permit / Licenses | NA | | |
| Others | NA | | |