Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
Complaint No.	Received Date	Received Time	Source	Category	Companie Details	Location		Status	Remarks
COM-2012-008	22-Oct-2012	16:41	EPD	Environmental (Water Pollution)	X先生防疫束漏機對出現發達大機能量,否污水接到導口(使疑是热污), 污除環境,要求跟進及回導。(Photos attached), The "phonomenon Was observed over the past week. The photos attached were taken on 19.10.2012, 22.10.2012 and 23.10.2012	Portion X	The pelican barge as shown in the photos provided on 24 October 2012 did not belong to the Contractor.	Closed	-
COM-2012-009	05-Nov-2012	-	1823 CASE: 1- 391341859	Environmental (Noise and light)	The citizen complained about noise and light pollution from the barges working on the Zhuhai Macau Bridge project. Barge machinery working to about 10pm at night and sometimes can be heard intermittently through the night. The noise is more audiole because the machinery is sited onlover the water.	Portion X	The Contractor has adjusted the emission angle of the lights on working vessels with a view to minimizing the glaring effect to the adjoining residential areas	Closed	-
COM-2012-009(2)	11-Nov-2012	-	1823 CASE: 1- 391341859	Environmental (Noise, water quality & air quality)	The complainant noted that the barges are still working on a Sunday, up until 10pm at night, very noisy, causing pollution of the water and at times expelling black smoke from their engines. A photograph taken at 10.40am on Sunday 11 November 2012 was attached.	Portion X	-	Closed	-
COM-2012-009(3)	14-Nov-2012	-	1823 CASE: 1- 391341859	Environmental (Noise)	The compainant did not accept the reply. He further said that "All staff has to do is come out either at night or a Sunday to check, so easy. If this continues I will have no choice to call the police out."	Portion X	The Contractor has taken the following further mitigation measures for the reclamation works: (a) Mitgation Measures for Noise Musancor: • Improvement of noise oxyres onto the generators / motors on barges; and • Increase Requency of applying bulknation to all moving parts and gear wheels of the working barges. (b) Mitgation Measures for Smoke Emission: • Increase Requency of maintenance and checking or engines on barges that may emit smoke; and • Installation! replacement of smoke suppression device such as all filter, at engines where necessary.	Closed	-
COM-2012-010(1)	06-Nov-2012	-	<hzmbenquiry@hyd. ov.hk></hzmbenquiry@hyd. 	g Environmental (Noise)	The compainant stated that lately work has started opposite Le Bleu Deux estate using barges. The work in process is generated high well of noise from gowered toots used on those barges. Even if the noise was acceptate) on weekdays during daytime, it is definitely creating nuisance to local resident at night (past 7µm) and on Sunday. Basically as 5 November 12 exeming, he could not leave his window open as the elevel of noise preven his baby to sleep and he could not even hear the TV in his flat. The noise coming from the site is higher then the sounds from my TV. He would like how what measure you are planning to put in place to address this issue. He did not think that the current level of noise are acceptable past 7pm and on Sunday.	Portion X	-	Closed	-
COM-2012-010(2)	15-Nov-2012	-	<hzmbenquiry@hyd. ov.hk></hzmbenquiry@hyd. 	g Environmental (Noise & air quality)	The noise can be very amoying, on dops depending of the wind direction, you are making more noise than the plene taking off I measured I miyedli), to give you and each the disturbance you are creating again. I would also fit to bring an other tropic basite the noise. Since the beginning of the filling operation, very strong small of exhaust pipe gas can be small in the missionial area and 11 think this is a hauge health concern for the local population. On certain days when the wind is blowing towards the residential areas. I have the feeling that there is a diesel engine running in my living room! I would like to know how you are planning to address this?	Portion X	-	Closed	-

Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
COM-2012-010(3)	15-Nov-2012	-	EPD	Environmental (Noise, water quality & air quality)	The complainant has copied his reply from HyD dated 15 Nov 2012 to EPD and Health Department and he further complained on the following issues: • Noise nuisance generated by diesel engine; • Smell of exhaust pipe gas in his residence; and • Suspector maine water pollution (see enclosed photo). The complainant also requested EPD to install noise and air quality monitoring at Le Bleu Deux estate.		Noise from blowing horn from vessels and barges and Metallic Parts thrown on Ground • Reminided the Contractor to request the captains of the vessels and barges not blowing the horn except in case of emergency or prevention of ship collisions/serious cashed matters; • The supervision teams would enhance their tight control on the vessels and barges working at that location, and monitor the situation and take corresponding actions; and • To enhance the work force of RSS to supervise each step of construction activities and the use of hand tools until the completion of the site office excerts on the Barges during Marine Operation • Notes from Engines and Crames of the Barges during Marine Operation • Installation of notice overse on the exercises on all working barges:	Closed	-
COM-2012-010(4)	19-Nov-2012	22:25 hrs.	EPD	Environmental (Air quality and Noise)	The complainant filed again a complaint for the strong exhaust pipe fumes smell coming for the construction site in Tung Chung tonight as well as the extremely high level of noise as at at 10:30 pm (19/11/12).	WA6	- Increase frequency of applying lubricant to all moving parts and gear wheels of the working barges to avoid generation of abnormal sound; and - Review of working hours for the reclamation works and switching off all unnecessary machinery and plants at night time and Sundays. Notes from over concretators		
COM-2012-010(5)	24-Nov-2012 25-Nov-2012	13:49 hrs 22:02 hrs.	ЕРО (сс tо HyD) ЕРО (сс tо HyD)	Environmental (Air quality and Noise)	The noise is coming for the following sources: - power generator - engines from the barges used for marine operation - noise from the cranes use of the construction barges. - engine from the boat used to transport staff in and out - boats blowing their horn late in the evening and at night Gas emissions: - power generators - power gener	WA6 Portion X	• All generators and the other screened or covered by adequate sound reducing materials: • All generators and the other screened or covered by adequate sound reducing materials: • All generators aduated in front of Le Bien Deux estate and the Sevakhof and at 1900 hns, accept two generators will be kept running up to 2200hrs and one generator will be kept running overnight for maintaining minimum power requirement, and • Arrangement will to EP ower HKL (dCIP) for the permanent power supply to the site officient has been chased in a matter of urgency. The use of power generators will be terminated in phase starting from 6 December 2012. Exhaust Fune Emission • Tight control on using the machine and generators in the vicinity of Le Bieu Deux estate, and • Costely monitor the frequency on engine cleansing and replacement of dust filter. Change of Sea Water in Yellow • The Contractor was reminded to move their vessels and barges at areas with adequate water depth as practically as possible.		
COM-2012-012(1)	13-Nov-2012	22:27 hrs.	HyD	Environmental (Noise)	Once again your site continues to work late. The attached photo was taken at 10.15pm on Tuesday 13 Nov. The machinery used on the barges is very noisy. Why do you continue to work till 10pm and why do you work on a Sunday. Surely this is classified as a construction site for which you are in breach of various ordinances. An early reply is appreciated.	Portion X	The following further mitigation measures during the course of the reclamation works will be taken: Installation of noise covers onto the generators / motors on all working barges; Increase frequency of applying bulcant to all moving parts and gear wheels of the working barges to avoid generation of abnormal sound; and Review of working hours for the reclamation works and switching off all unnecessary machinery and plants at nightlime and Sundays.	Closed	-
COM-2013-015	17-Jan-2013	-	EPD	Environmental (Air)	The compalement raised that construction dust was arising from construction site of China State Contruction Engineering (Hong Kong) Ltd near Siu Ho Wan Sewage Treatment Works due to insufficient dust suppression and inadequate wheel washing.	WA3	The Contractor of HY/201103 would take the following actions with immediate effect. To ensure no loosed earth material exposed at the edges of eth stockpiled earth materials i.e. to prevent erosion by wind and water To cover the stockpiled earth material by adequate targrapmin; To enhance the frequency of watering (3 times per day) onto existing haul road and other area as appropriate; and To install a water spinkler system to enhance the existing dust suppression measures once the water point is ready for water supply by WSD.	Closed	

Complaint No.	Received Date	Received Tim	e Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
COM-2013-016	18-Jan-2013	-	EPD	Environmental (Water)	The complainant advised that turbid water and concrete/cement has been arising from the Hong Kong-Zhuhai-Macao Bridge Hong Kong Projects to marine water. The complainant did not specify the soure of the turbid water and concrete/cement.	N/A	-	Closed	-
COM-2013-018	02-Mar-2013	-	НуD	Environmental (Noise)	The complainant advised that "It seems that the Contractor's cranes operating on the barges are again in need of bit of lubricant, as this evening i.e. 2 March 2013, the cranes are again polluting the neighborhood with intelerable noise." The complainant requested Mr. Ng from EPD to take note of this complaint and expected a detailed report.	Portion X	The Contractor has been reminded to continue the process of applying lubricant/ grease to all barges which are to be worked in the site area near Le Bleu Deux.	Closed	-
COM-2013-018 (2)	04-Mar-2013	-	EPD	Environmental (Noise)	The complainant complained that the cranes operating on the barges for the HZMB HK project generating squaak noise in the evening of 1 March 2013 causing an annoyance to him/her.	Portion X	The Contractor implemented the following measures : - Brilding given to the operator for the proper operation of marine vessels; - Keep adequate routine maintenance : - Minimize the quantities of plant after 7pm; & - Review the working hours of night time works and switch off all unnecessary machinery and plants at night time.	Closed	-
COM-2013-018 (3)	13-Mar-2013	-	HyD	Environmental (Noise)	The complainant asked what noise mitigation the Contractor was taking. The complainant pointed out that the noise in question was so strong that it woke up his baby girl.	Portion X	-	Closed	-
COM-2013-018 (4)	22-Mar-2013 24-Mar-2013	14:19 hrs 10:28 hrs	НуD	Environmental (Noise)	The completent completent completent that The lifting appliance was operated gently and settly to keep the noise emission as low as possible 'when how settle was up in baby', "utilicative was regularly applied to smoothen all moving parts and gear wheels of the working barges' that did not seem to be the case at all. The completent pointed that the crane operating at 10:27 hrs on 24 March 2012 needed lubricant.	Portion X	The Contractor will keep on closely monitoring the situation and carry out the necessary noise mitigation measures while barges are working in the site area nearby residential area.	Closed	-
COM-2013-018 (5)	31-Mar-2013	10:25 hrs	HyD	Environmental	The complainant complained that noise emitted from a crane at 10:19 hrs. The complainant further complained that noise	Portion Y	-	Closed	-
	1-Apr-2013	10:32 hrs		(Noise)	was generated from a barge at 07:30 hrs.				
COM-2013-018 (6), (7) & (9)	15-Apr-2013	15:41 hrs	EPD	Environmental (Noise)	The complainant complained that machinery noise generated from the construction sile near Tung Chung Development Pler operating for the hong Kong-Zhuha-Macao Bifel Hong Kong during the normal working hours on 6 April 2013 and 13 April 2013 and the late evening of 10 April 2013 causing nuisance to public.	Portion X	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours and non-restricted hours, the Contractor has implemented the following additional measures: - Operating barge by experienced operators only. - Keeping adequero truthe maintenance for barges e.g. application of lubricants into moving parts in order to minimize squeak - Resping adequero truthe maintenance for barges e.g. application of lubricants into moving parts in order to minimize squeak - Resping adequerotion maintenance for barges e.g. application of lubricants into moving parts in order to minimize squeak - Resping adequerotion of early equipment where practicable. - Remind subcontractor only vell-maintening dark should be operated on-site. - Minimized the quantities of plant used after 7pm as far as practicable; - Speed up of construction works in order to shorten the duration (days) of potential noise impact/nuisance to the surrounding environment; and - Regular review of working hours for right time works and exitch of all unnecessary machinery and plants at night time.	Closed	-

Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
COM-2013-018 (11)	28-Apr-2013	15:44	EPD	Environmental (Noise)	The complainant complained that machinery noise generated from the reclamation site near Tung Chung Development Pler at around 22:00 of 28 April 2013 causing nuisance to public.	Portion X	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours, the Contractor has implemented the following additional measures: - Briefing given to the operator of the targets for proper operation of mainre vessels; - Operating barge by experiment operators only; - Keeping adequet enutine mantemations for bargets e.g. application of lubricants into moving parts in order to avoid squeak noise; - Install noise covers order only equipment where practicable. - Remind subcontractor only well-maintained plant shall be operated on-site. - Speed up of construction works in order to shorten the duration (days) of potential noise impact/nuisance to the surrounding environment; and - Regular review of working hours for night time works and switch off all unnecessary machinery and plants at night time.	Closed	-
COM-2013-022	08-Apr-2013	-	EPD	Environmental (Water)	The complaint alleged that oil was dumped from various vessels operating for HZMB HK projects near Tung Chung Development Pier over the past few months. Photos were provided by the complainant.	Portion X	The Contractor has checked the photos provided by the complainant and confirmed that the vessels and boats shown in the photos do not being to Contract No. ht/Y2011/03.As this complaint is not related to this Contract, no follow up action is required. The Contractor has reminded their subcontractors to implement the measures recommended in the Spill Response Plan (SRP) in case of accidential release of oils from vessel.	Closed	-
COM-2013-022(2)	23-May-2013	09:15 hrs	EPD	Environmental (Water)	This complaint was a follow-up of a previous complaint received by EPD on 8 April 2013 regarding oil slicks caused by vessels. It was alleged that oil was still being dumped from various vessels operating for HZMB HK projects near Tung Chung Development Fier over the past few months. On the other hand, the complainant would also like to know whether the owners of the vessels could present engine oil disposal records for the vessels which supported the HZMB project.	Portion X	The Contractor has reminded their subcontractors to implement the measures recommended in the Spill Response Plan in case of accidential release of oils from vessel and handle the chemical waste (waste oil) in accordance with the requirements provided in the EM&A Manual.	Closed	-
COM-2013-023	02-May-2013	-	HyD	Environmental (Noise)	The complainant alleged that there were metal parts dropped on the ground creating noise at 12:58 on 1 May 2013	WA6	If there are metal handling works, the Contractor will not carry out the metal handling works in early morning in order to minimize potential noise disturbance as far as practicable in future.	Closed	-
COM-2013-024	23-May-2013	09:50 hrs	EPD	Environmental (Noise)	A complaint was received on 23 May 2013 regarding noise generated from dropping metal parts on numerous occasion on the pier opposite Le Blau Deux at around 08.45 to 10:00 hrs of 18 May 2013 and loading/unloading activities creating noise disturbance by the contractor of HY/2011/03.	WA6	If there are metal handling works, the Contractor will not carry out the metal handling works in early morning in order to minimize potential noise disturbance as far as practicable in future.	Closed	-
COM-2013-027	29-Jun-2013	10:02 hrs	RSS	Environmental (Noise)	A complaint was received on 29 June 2013 regarding noise generated from the works area near the site office (WA6) around 10:00 hrs on 29 June 2013	WA6	The Contractor was recommended to minimize the potential noise impacts generated from the construction sites as far as practicable in future.	Closed	-
COM-2013-033	13-Sep-2013	Around 22:00 hrs	RSS	Environmental (Noise)	A complaint was received regarding the noise nuisance from barge at about 22:20 hrs on 13 September 2013 and 02:30 hrs on 14 September 2013.	Portion X	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours, the Contractor has implemented the following additional measures: - Minimized the quantities of plant used after 7 pm as far as practicable; and - Resultar review dworking hours for night time works and switch off all unnecessary machinery and plants at night time.	Closed	-
COM-2013-034	17-Sep-2013	-	HyD	Environmental (Noise)	A complaint was received on 17 September 2013 regarding the noise nuisance from tree transplanting activities in the morning of 14 September 2013.	Portion Y	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours, the Contractor has implemented the following additional measures: - Minimized the quantities of plant used after 7 pm as far as practicable; and - Benutize maken undertained hum and and a with of all unconcessor machiners and plants at night time.	Closed	-
COM-2013-037	8-Oct-2013 9-Oct-2013 16 Oct-2013		Supervising Officer's Representative	Environmental (Noise)	The complainant complained the noise from barge operation from 21:30 to 22:30 hrs on 4 October 2013. The complained met event allow barge were heard starting from 21:00 hrs on 7 October 2013. The complainant complained that it was very noisy at the noon of 14 October 2013.	Portion X	The Contractor has been reminded to comply with CMP conditions for construction works undertaken during restricted hours. To minimize the potential noise impect during restricted hours, the Contractor has implemented the following additional measures: -minimize the quantities of plant used during restricted hours as far as practicable; and -equilar review of working duration for restricted hours works and switch off all unnecessary machinery and plants during restricted hours.	Closed	-

Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
COM-2013-041	31-Oct-2013	21:52 hrs	EPD	Environmental (Noise)	A complaint was received on 31 October 2013 regarding the noise generated from a barge being moved by a tug boat in the morning of 31 October 2013 (around 05:55).	N/A	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours, the Contractor has implemented the following additional measures: - mimize the quantilise of plant used during restricted hours as far as graciticable; and - regular review of working duration for restricted hours works and switch off all unnecessary machinery and plants during the night- time and early morning period (7pm to 7am).	Closed	-
COM-2013-043	11-Nov-2013	-	EPD	Environmental (Noise)	A complaint was received on 11 November 2013 regarding a barge moving through the southern channel of HyD's construction site after 23:00 hrs on 8 November 2013.	Portion X	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours, the Contractor has implemented the following additional measures: - mimize the quantilise of plant used during restricted hours as far as graciticable; and - regular review of working duration for restricted hours works and switch off all unnecessary machinery and plants during restricted hours.	Closed	-
COM-2013-045	27-Dec-2013	-	HyD	Environmental (Noise)	A complaint was received on 27 December 2013 regarding barges operating at the south channel of Portion X in the afternoon of 26 December 2013.	Portion X	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during restricted hours. To minimize the potential noise impact during restricted hours, the Contractor has implemented the following additional measures: - mimize the quantilise of plant used during restricted hours as far as gracicable; and - regular review of working duration for restricted hours works and switch off all unnecessary machinery and plants during restricted hours.	Closed	-
COM-2014-046	16-Jan-2014	17:22 hrs	HyD	Environmental (Air Quality)	A complaint was received on 16 January 2014 regarding heavy exhausts generated at around 8 a.m. and 10 a.m. over past few months and or even midnight.	N/A	The Contractor has implemented the following measure to minimize exhaust fumes generated from machinery: - Maintenance for the all machinery regularly.	Closed	-
COM-2014-048	18-Jan-2014	-	EPD	Environmental (Other: Blackish mud)	A complaint was received on 18 January 2014 regarding blackish mud along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014.	Portion X	Based on the investigation results. It is considered that the blackish mud raised in the complaint was not related to HKLR03 Contract. In this case, no follow up action is required.	Closed	-
COM-2014-050	24-Mar-2014	-	EPD	(Other: Dredged	A complaint was received by EPD on 24 March 2014. The complainant advised that there was dhedged material found being mixed with soil in the construction site of Hong Kong-Zhuha-Macao Bridge Hong Kong Link Road Project in the vicinity of CAD breadquarters and transported out of the site. The complainant suspected that there was improper disposal of dredged marine sediment.		Based on the investigation results, it is considered that the complaint is invalid. In this case, no follow up action is required.	Closed	-
COM-2014-051	29-Apr-2014	-	SOR		A complaint was received on 29 April 2014 regarding loud bang coming from the site at 21:37 hrs on 28 April 2014.	Portion X	Based on the Contractor's site dairy and our investigation, no non-compliance was identified.	Closed	-
COM-2014-053	02-May-2014	-	EPD	(Noise) Environmental (Noise)	A complaint was received by EPD on 1 May 2014. The complainant advised that there was noise nuisance arising during the evening of 1 May 2014.	Portion X	The Contractor has been reminded to comply with CNP conditions for construction works undertaken during treatriced hours. To minimize the potential noise impact during restricted hours, the Contactor has implemented the following additional measures: - minimize the quantities of plant used during restricted hours as for as practicable; and - regular review of working duration for restricted hours works and switch off all unnecessary machinery and plant during restricted hours.	Closed	-
COM-2014-063	03-Dec-14	-	Arup	Environmental (Noise)	According to Anap's email to CSCE and DCV.IV on 3 December 2014, "A resident living in Le Bleu Duex addressed a complete to CE of HyD at about 2014 hrs test night. He complained about the noise nuisence coming from site office since 19:30 hrs last night, epetilively metal parts had been dropped on the ground by people who seem to be loading or unleading a boat at the pier. Noise was still going on right now at 20:04."	WA6	Based on the investigation results, it is found that the noise complaint is not related to Contract No. HY/2011/03. In this case, no follow up action is required.	Closed	-

Complaint No.		Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
OM-2014-065	24-Dec-14	Nil	EPD	Environmental (Water Qulity)	A complaint was received on 24 December 2014 regarding the increase of marine refuse (water bottles and debris) along the shore from Yat Tung to Tai O, where the complainant considered might be in relation to the HZMB project(s).	Portion X	Based on the investigation results, it is considered that the complaint is unlikely related to HKLR03 Contract. Nevertheless, the Contractor is reminded to implement all recommended mitigation measures for waste management and avoid dumping rubbish into the sea.	Closed	-
DM-2015-066	08-Apr-15	Nil	EPD (An email forwarded by Arup)	Environmental (Dust)	According to Arup's email to CSCE on 8 April 2015, the ET was informed that a complaint had been received by EPD at about 18:29 hrs on 2 Apr 2015 regarding construction dust from construction site (S15) at Kwo Lo Wan Road, Tung Chung.'	S15	Based on the Contractor's information and our investigation, no non-compliance was identified. The Contractor is reminded to continuously implement the dust suppression measures to minimize potential dust impact.	Closed	-
OM-2015-068	10-Apr-15	Nil	EPD (An email forwarded by Arup)	Environmental (Noise)	According to Arup's email to CSCE on 10 April 2015, it is noted that EPD received a noise complaint from a resident of Caribbean Coast. According to the complainant, he was disturbed by noise from construction activities of the HZMB Project during waterinds and holidays. The complainant was referring to hose activities carried out between Scenic Hill and HKBCF because the complainant mentioned the contractor was China State.	N/A	Based on the information provided and our investigation, the Contractor had complied with the conditions laid down in Construction Noise Permit (CNP) Nos. GW-RS0113-15 and GW-RS0356-15. Hence, no nor-compliance was identified. The Contractor base been reminded to comply with CNP conditions for construction works undertaken during restricted hours and incommended to implement the following measures to minimize the potential noise impact during restricted hours. Inimize the quantities of part used during restricted hours as far a pradicable; and regular releved working duration for restricted hours works and switch off all	Closed	-
DM-2015-074	16-Jul-15	Nil	EPD	Environmental (Wastewater)	According to EPD's email to Highways Department, ET, SOR and ENPO, a compaint was received on 16 July 2015 regarding vastewater splanking for whiches to packettina it Tung Fai Road. The complainant complained that wastewater was splashed to people waiting at the bus stop near Civil Aviation Department Headquarters Office Building when vehicles leaving the HZMB site to Tung Fai Road.	Tung Fai Road	unencerson mobilese root steet during setting bours. Based on the investigation results, it is considered that the complaint is unlikely related to HKLR03 Contract. The Contractor has been reminded to slow down their vehicles when leaving the concerned construction site.	Closed	-
DM-2015-076	17-Jul-15	Nil	EPD (An email forwarded by ENPO)	Environmental (Noise)	According to EPD's email to ENPO on 17 July 2015, it is noted that EPD received a noise complaint from public. The complainant said that helps was disturbed by the noise generated from construction sites of the HZMB Project during the digvitue period of past few Sundays. Afterwards, EPD contacted the compliannt and confirmed that the noise was generated from construction sites along Kwo Lo Wan Road and signs of "China State Construction Engineering (HK) Ltd" were noted.	Kwo Lo Wan Road	Based on the information provided and our investigation, the Contractor compiled with the conditions laid down in Construction Noise Permit (CNP) Nos. GW-R50733-15 and GW-R50740-15 and no noncompilance was found. The Contractor has been remined to comply with CNP conditions for construction works undertaken during restricted hours and recommended to implement the following measures to minimize the potential noise impact during restricted hours: - minimize the quantities of plant used during restricted hours as far as practicable; and - regular review of working duration for restricted hours works and switch of all unnecessary machinery and plant during restricted hours.	Closed	-
OM-2015-079	07-Dec-15	Nil	ENPO (EPD referred the email from Complainant to ENPO)	Environmental (Water Quality)	According to ENPO's email to SOR and ET on 7 December 2015, a complaint was received by EPD on 2 December 2015 regarding used reality new HAIK, work site. The complainant metriosed that it moved to Tung Chung einse July and It was the second time I saw similar situation polluting the sea. Last time It was even worse in red colour. Please look into this matter and let me know what was being dropped into the sea and whether it was hazardous to the sea." EPD has contacted the complainant and obtained the additional information from the complainant. EPD suspected that the incident happened in the afternoon on 28 November 2015.	Portion X	According to the information provided by the Contractor, the denick barge belongs to Contract No. HY/201103. The occonrend estimated plane was likely to be caused by stiming up of mul in the seaked by the denick barge sailed at the nakigation channel situated at shallow water zone where the water depth ranging from 3.25m – 3.75m. Public fill materials were placed on the denick barge. The barge was in good conditions with no materials being dumped into the sea. The Contractor has been implementing the mitigation measure as specified in the implementation. Schedule of Environmental Mitigation Measures that is all vessels to be sized such that adequate clearance is maintained between vessels and the sea bed at all states of the tide to ensure that undue turbidity is not generated by turbulence form vessel movement or propeller wash. The Contractor is commend to arrange vessels to move out of the site area during high tide to avoid the disturbance to the seabed in all averse.	Closed	-
OM-2016-087	28-Jun-16	Nil	EPD	Environmental (Water Quality)	According to EPD's email, a complaint was received on 28 June 2016 regarding polluted water discharge incident opposite to Tung Chung Development Pier.	N/A	The Contractor has designated competent persons to operate, check and maintain individual wastewater treatment plant as an existing control measures, in case of breakdown of wastewater treatment plants, no discharge of wastewater will be allowed until repair is completed to resume the normal operation of the treatment plants. The discharge of wastewater traiting trainings have been providing for the staff and workers for each of the wastewater treatment plants. The discharged into open channel.	Closed	-
DM-2016-098	11-Nov-16		ENPO (EPD referred the email from Complainant to ENPO)	Environmental (Water Quality)	According to ENPO's email to the Environmental Team, Supervising Officer's Representative and Contractor on 11 November 2016, it is noted that EPD received a complaint lodged by a member of the public regarding sediment plume generated by a vessel namet "Rigidad" (Chang Sheng 308) during the vases Itravelling from construction site of Hong Kong-Zhuhai- Macao Bridge near Scenic Hill to Tung Chung New Development Ferry Pier.	Portion X	The Contractor has been reminded to schedule the vessel to move in / out of the construction site during higher tide and minimize number of trips to avoid the stirring up of the seabed mud when the vessel travelling in very shallow water areas as much as practicable. As the Contractor was reminded to implement environmental miligation measures in accordance with Environmental Mitigation Implementation Schedule (EMIS).	Closed	-
DM-2016-099	02-Dec-16		ENPO (EPD referred the email from Complainant to ENPO)	Environmental (Other: Slurry on public road)	It was noted from ENPO's email to the Environmental Team, Supervising Officer's Representative and Contractor on 2 December 2016 that EPD received a complaint lodged by a member of the public regarding slurry on East Coast Road. The complained considered the slurry might reliate to the construction site of China Harbour Engineering Company Limited next to a hotel.	East Coast Road	During the weekly site inspection undertaken on 7 December 2016, no slurry was observed at the section of East Coast Road adjoining the site boundary of Contract No. HY/2011/03. The Contractor has constructed wheel washing facilities at all the site accesses, including the ore next the site access of Chrin Harbour Engineering Company Limited next to the Marriet Hotel (which is believed to be the hotel mentioned by the comparison), to wash and clean at which be before allowing them to beare the conducted by water truck at least thinks on the section of East Coast Road adjoint the site boundary of Contract No. HY/2011/03 to minimize dust emission. Based on the investigation results, it is considered that the complaint unlikely related to Contract. No. HY/2011/03. Not Markanding that, the Contractor has been reminded to clean wheels and body of vehicles as usual before allowing them to leave construction site.	Closed	-
OM-2016-100	14-Dec-16		ENPO (Contract No. HY/2010/02 project team received an environmental complaint referred by Government's hotline (1823) on 2 December 2016. ENPO forwarded the Complaint to Contract No. HY/2011/03.)	Environmental (Other: mud/ derbris on public road)	It was noted from ENPO's email to the Environmental Team, Supervising Officer's Representative and Contractor on 14 Decomber 2016 that EPD received a complaint lodged by a member of the public regarding muddebris on public read. The complaints comparised that "the whole stretch of EaC locast Road S Tung Fair Road is tury disguilaring. The stone stretch is the whole stretch of the Rac locast Road S Tung Fair Road is tury disguilaring. The stone stretch is the stone stretch and the stretch is the stone stretch and the stretch and the stone when it rains or when the road washing trucks are out h becomes a muddy mess. Cars and padestimes are covered in duats or mud, cars are hit by stones is a daily hazard. Washing of construction which is inducquies at the stand and and and is carried out onto the reads. Oversight of road conditions are not carried out by the Airpot Authority. An alternative route should be created for the large number of construction vehicles as they drive fast."	East Coast Road and Tung Fai Road	During the ET's inspection on 7 December 2016 (weekly routine inspection) and 16 December 2016, no mud or debris was observed at the section of East Coast Road adjoining the site boundary of Contract No. HY/2011/03. We well as the section of Tang F4 Road leading to the site access of Contract No. HY/2011/03. The Contractor provide wine variaring faillites at all the site before allowing them to leave the construction set (VT2)11/03. The Contractor provide wine variaring faillites at all the site before allowing them to leave the constructions let to ensure that no mud or detrix would be brought to the public area. It was before allowing them to leave the constructions let to ensure that no mud or detrix would be brought to the public area. It was before allowing them to leave at the weaking facilities and the respective or da section between the wheel washing facilities and the site accesses of East Coastal Road and of Tung Fai Road were paved with concrete. High pressure jets were also provided at the wheel washing facilities or cleaning of vehicles before the wholes were allowed to leave the construction site. In addition, regular watering at the section of East Coast Road adjoining the site boundary of Contract No. HY/2011/03 was conducted by water trucks at least twice pred by to minimize dust emission. Based on our investigation result, it is considered that the complain is unlikely related to Contract No. HY/2011/03. Notwithstanding that, the Contractor has been reminded to clean the wheels and body of vehicles as usual before allowing them to leave construction site.	Closed	
COM-2016-103	14-Dec-16		ENPO (EPD referred the email from Compleinant to ENPO)	Environmental (Noise)	It was noted from ENPO's email to the Environmental Team, Supervising Officer's Representative and Contractor on 14 December 2016 that EPD received a noise complaint todged by a member of public. The complaint twas about hammening noise generated from construction tests an indinghi in the past month. The complainant touch noi tentify the source but suspected that the noise was generated from HZMB Project. It was also noted from ENPO's email on 21 December 2016 that EPD supemented that the complainant ives in Beaview Crescent. The complainant sometimes heard noise created by impacting metals or metal/ground, particularly in December 2016.	N/A	The Contractor confirmed that no hammering works was conducted and no impact noise was generated at midnight in November 2016 and December 2016. The Contractor complied with the conditions liad down CNP No. GVH-R5740-16 and no non-compliance was found. Based on our investigation result, it is considered that the compliant is unlikely related to Cortact. No. HY/2011/03. In this case, no follow up action is required. However, the Contractor has been reminded to comply with the conditions stipulated in the Construction Noise Permit for construction works undertaken during restricted hours: - minimize the potential noise impact during restricted hours: - regularly review the working duration for restricted hours works; and - switch off all unnecessary machinery and plant during restricted hours.	Closed	

Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
XXX-2017-104	09-Jan-17	Nil	IEC (EPD referred the email from Complainant to IEC)	(Other: Cleanliness	It was noted from IEC's email to the Environmental Team. Supervising Officer's Representative and Contractor or 9 January 2017 that IEC's email to the comparint logged by a member of the public (a bus operator at the HKIA) regarding cleanliness problem at East Coast Road and Tung Fai Road.	Road and	During the ET's inspection on 10 January 2017, it was observed that the Contractor provided wheet washing facilities at all the site scenses, including the one accessing East Coast Road and the one accessing Tung EI a Road, to wash and che and it whicks before allowing them to leave the construction site to ensure that no mud or decisi would be brought to the public area. No mud was observed at the section of Tung Fai Road leading to the site access of Contract No. HY/201103. However, some mud was observed at the section of Tung Fai Road leading to the site access of Contract No. HY/201103. However, some mud was observed at the section of Tung Fai Road leading to the site access of Contract No. HY/201103. However, some mud was observed at the section of Tung Fai Road leading to the the compliant is related to Contract No. HY/201103. However, some mud was observed at the section of Tung Fai Road leading to the the compliant is related to Contract No. HY/201103. However, some mud was been reminded to clean the wheels and body of vehicles as usab before allowing them to leave construction site. Road sweep will be employed to seve pair ong the Caset Road whore per veek and remove the deposited mud underneath the valuer-filed barrier to facilitate the road-washing water to be drained away from the carriageway. It should be of note that the ground level of site boundary of HY/201103 adjing into East Coast Road will be indexed to enhance dust suppression: 1. Stockpile along East Coast Road will be reduced in height and compacted as far as practicable 2. Jaular cavel will be demarcated to prevent vehicles from grain (in non-wetted suffacts. 3. Site access S16 will be thoroughly cleaned and all whicles will be stopped for second washing after being washed in the wheel washing bay. 4. Water spinklers will be installed and operated at the stockpiles behind the water-filled barriers along East Coast Road.	Closed	
COM-2017-108	23 February 2017 and 2 March 2017	Nil	Airport Authority Hong Kong (AAHK) via SOR / Referred to ENPO by HyD	(Air quality, Water	AHK stated in their email to SOR on 23 February 2017 that there was sand/muddy water accumulating along the water barriers at East Coast Road Southbound. AAHK also lodged a complaint to HjO, which HjO referred to ENPO on 1 March 2017 (received by ET on 2 March 2017). AAHK reported that the cleanines of Last Coast Road remained unsatisfactory with dust all over the water barriers/traffic aids, and sands accumulating along the carriageway.	East Coast Road	During ET's observation on 3 and 13 March 2017, properly functioning wheel washing facilities were provided to wash all vehicles prior to leaving the site. The section of road between the wheel washing facilities and the site access (S25) was hard paved and no mud' sit was observed at the concenter for ads ecitor and the site access. As the ground level of site boundary of HY2011103 adjoining the East Coast Road is lower than that of East Coast Road, the possibility of muddy water seepage from S25 to East Coast Road is low. Based on cur investigation result, the compliant is unifiely to be related to Contract No. HY2011103. Nevertheless, the Contractor has been reminded to strictly upkeg the proper practice of washing all vehicles leaving the site access (S25). Also, the Contractor has reade the majority of the temporary traffic signs to a higher level to avoid muddy water splashing on them. Also, the temporary traffic signs will be cleaned regularly.	Closed	-
COM-2017-112	27 March 2017		ENPO (EPD referred the email from Complement to ENPO)		It was noted from ENPO's email to the Environmental Team. Supervising Office's Representative and Contractor on 28 March 2017 Mite EPD received an ansies compliant todgod by a resident of Contruly Link on 27 March 2017. The comparing was about "即说 (e. 26 March 2017) 大力十時后, 电光频影力并常是需要是,是服整度是没是没想改进大模式人工品的工程设计。绝望一直至深度,另今早轻现 任或影过海面受到一大局劳治(只用片); 以上都想起是大概工程所指成的污形(rie. *AI around ten ofcock last night (i.e. 26 March 2017), there was interminent very load vision colsider. According to observation, the noise should be from the Hong Kong-Zhuñua-Marca Bridge project near the artificial Island, the noise lasted until late at night. In this morning, there was a plume of pollution found on the sea (see photo). These should be caused by the bridge project."	Nil	Based on the information provided by the Contractor and our investigation, it was concluded that the Contractor had completed with the conditions laid own in CNPs No. CWR-551-135-146 and CWR-50001617 and that no no-compliance on water quality was found. It is considered that the complaint is unlikely related to Contract No. HY/201103. In this case, no follow up action is required. However, the Contractor has been reminded to comply with the conditions slipulated in the Construction Noise Permit for construction works undertaken during restricted hours and has been recommended to implement the following measures to minimize the proteinal noise impact during restricted hours: - nitrimize the number of machinery and plant used during restricted hours as far as practicable; - egistich off all unnecessary machinery and plant during restricted hours. - which off all unnecessary machinery and plant during restricted hours.	Closed	
COM-2017-113	20-Apr-17	Nil	ENPO (EPD referred the email from Complainant to ENPO)	Environmental (Water quality)	It was noted from ENPO's email to the Environmental Team, Supervising Officer's Representative and Contractor on 20 April 2017 that EPD received a complaint on 19 April 2017 lodged by a green group. The complaint was about ************************************	Portion X	Based on the information provided by the Contractor and ET's investigation, it was suspected that the concerned silt plume may be caused by sea current. There was no evidence that the concerned silt plume was caused by any activities arising from the Contract. The Contractor was reminded once again to implement the mitigation measure as specified in the Implementation Schedule of Environmental Mitigation Measures. The Contractor is also recommended to fully and properly maintain the silt curtain throughout the works in accordance with the requirements in the Updated EMAA Manual through undertaking monthly measurement on the overlapping and separation openings for vessels access for prompt rectification.	Closed	-
COM-2016-095(3)	27-May-17	Nil	SOR (HyD referred the email from Complement to SOR)	Environmental (Noise)	It was noted from SOR's enail to the Environmental Team and Contractor on 26 May 2017 that HyO received a complaint on 12 May 2017 lodged by a member of public. The complaint was about "We'd like to follow up on this case. Pis hep tapping the second seco	Near Dragonair / CNAC (Group) Building (HKIA)	Upon the receipt of the complaint in May 2017; the Contractor had been instructed to immediately install additional noise barriers at the appropriate location and cover the breaker thy with accustic materials as noise mitigation measure against the noise emissione source (rock breaking work). Also, gaps and openings at joints in the barrier material have been minimized. The nock breaking work). Also, gaps and openings at joints in the barrier material have been minimized. The nock breaking work was completed on 31 May 2017 and the rock threaking machine had been demobilized off site. According to information from Contractor, removal CAD materials will be carried out at the site near CAD and CHAC buildings in the future. As such, noise nuises generated from a site will be minimized. Notwithatending that, the Contractor has been reminded to implement noise mitigation measures on the site to minimize any potential nuiseance to the public. Based on cur investigation result, it is considered that the complaint is tilty related to Contract No. HY/201103. The Contractor has implemented the following measures on minimize the potential noise impact. - Additional noise barriers have been enclud in the active working area to further mitigate the associated noise emissions as far as - Cover the treaker tip with accustic material. - Noise barriers have been located as close as possible to the noise source. Also, gaps and openings at joints in the barriers material have been minimized. working and the duration noise impact/nuisence to the surrounding. - Minimize the quantities of noisy plant as far as practicable. - Regular review of working duration and switch off all unnecessary machinery and plant.	Closed	
COM-2016-095(4)	15-Aug-17	Nil	нур	Environmental (Noise)	HyD received a complaint concerning the rock breaking works near CNAC Buildings, as described below: "I am writing to let you know re-captioned works interrupted seriously our staff daily office works. Understand the rock encountered was much storaget than the original expected, the rock breaking works near CNAC Towe has been never ending. Recently a baldcace is working nearby and no noise barriers/sound prode were set up. Please take corrective action asp. Kindly advise us when this buildcacing work is scheduled to complete."	Dragonair /	The major nock breaking works near CNAC Tower were substantially completed on 31 May 2017. However, survey record revealed that miror nock breaking timming work was required at the formation level for the construction of box cutvert no. PR14. Hence, the Contractor test of hydralic breaker for miror nock breaking/timming work in the aftermoon on 15 August 2017. According to the second structure of the construction of box cutvert no. PR14. Hence, the Contractor test of hydralic breaker to hydralic breaker the hand future. ET conducted an fivestigation on 16 August 2017. The atthet concerned location. No significant hydralic breaker the hydralic breaker the hydralic breaker the hand head at the concerned holds and hydralic breaker the hydralic breaker. The atthet has conducted an end on the site. Baad on our investigation result. His considered that the complement his for hydralic breaker the hydralic breaker the history breaker to hydralic breaker. The conducted at the concerned hydralic breaker to be conducted? I for the hydralic breaker the history work (is not hydralic breaker the history work was been only minor rock breaking trimming work was been during the hydralic breaker. The conducted at the Contractor has been recommended to implement the following measures to minimize the potential noise impact them inner rock breaking trimming work was been constructed. I hydralic breaker the history the horize base of the history the horize base of the hydralic breaker the history the hydralic breaker the hydralic breaker the hydralic breaker th	Closed	

Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
COM-2017-122	03-Oct-17	Nil	1823 Integrated Call Centre received a complaint lodged by a member of the public on 30 september 2017. SOR referred the complaint details from 1823 - HyD to ET on 3 Oct 2017	Environmental (Other: Cleanliness problem at Tung Fai Road)	1823 Integrated Call Cathe received a complaint lodged by a member of the public regarding deanliness problem at Turging Fit Road, a described bolow: "祝好大概山前編合理题话 11级活题方理制出。已社记期使,思想我源大偶地意其中一面出人口,經常有大量重型工程申籍造出地意。每逢有日士或 量型申輕經驗時, 超图沙應開超引起"沙塵麼",够保巴士的荣客使遵狭。以助有漏水申讓水減低沙塵,現在漏水車都沒有 出現。 要求部門改贏沙應問題。"	S16	During the ET's inspection on 3 October 2017, it was observed that the Contractor did provide wheel washing facility with high pressure jiels at the site access 516 at Tung E at Road to wash and clean all whick lasher caliving them to lave the construction site to ensure that no mut or detrix would be brought to the public area. It was also observed that the Contractor did provide water bowers to theroughly clean Tung F at Road. No mut was observed at the section of Tung F at Road teading to the eila access 516 of Contract No. HY/2011/03. Another inspection was conducted on 12 October 2017, the section of the road between the wheel washing facility and the site access 516 was hard paved and no mud/sit was observed at the concerned road section and the site access 516. Although Contract No. HY/2011/03 is the only construction site connecting to the Tung Fai Road and the mentioned bus top, wheel washing facility with high pressure jets is provided at the site access 516 to wash and clean all vehicles before allowing them to leave the construction is related to Contract. No. HY/2011/03. Nevertheless, in order to enhance dust suppression measures, the Contractor will increase the frequency of road cleaning by water bowser from three times per day to four times per day, subject to regular relave with intervant Stakhoddre is in the vicinity.	Closed	-
COM-2017-129	08-Jan-18	Nil	ENPO's email to the Supervising Officers Representative and Contractor on 8 January 2018 that HyD received a complaint lodged by a member of the public regarding cleanliness problem at East Coast Road on 29 December 2017	(Other: Cleanliness	HVO resorted a complaint logicet by a member of the public regarding desaliness problem at East Coast Road on 29 December 2017. The complaint details are described below: "投資人投算於大幅(此業保護、因進我讓大幅工程的沙層原題、留門交前"方無期流道中及吸重非處理情觀沙層原題。但有 算細稿は上級問題的處理成改大如理想。均括人表式活動中在透水面的描意時,只是同語電源、《表面中吸了地址。的沙應修所讓 出來的言葉描色滿沙層,以致有關沙塵除了未被吸走外,更導致道路沙塵沿液。要求部門監察有關來辦商、煩請部門證違及 回覆。*	East Coast Road	Based on our investigation result, there is no direct evidence showing that that the complaint is related to Contract No. HY/2011/103. The Contractor has been reminded to implement the following measures to minimize dust impact/ improve cleanliness at East Coast Road: • display notice at site access to remind drivers to wash the wheels thoroughly before leaving the site. • manual control by rope stopping vehicles entering public road without wheel washing. • provide training for drivers to ensure that they can awater truck and provide maintenance to water truck and road sweeper if nacessary. • implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule as per the EMKA Manual. ET will also step up the site inspections to ensure the cleanliness of the concerned section of East Coast Road is properly maintained.	Closed	-
COM-2018-132	13, 14 February 2018	Nil	HyD (SOR referred the email from HyD to Contractor and ET) and EPD (ENPO referred the email from EPD to SOR, SOR sent the email to Contractor and ET)	Dust, Water Quality, Construction Waste, Notse and vibration	The complaint was received from the SOR's email on 13 February 2018 with the following details: "We have witnessed increased construction activities causing concerns such as nuisance, air and water pollution, construction was leaded in the sum of the sum of the sum onlines. Nuisance – construction noise and vibration Ar and Water Pollution – poor disc control causing air pollution Construction Waste Landfill Hill – increased height, size and degree of the slope of the construction waste landfill Moreover, we are particularly concerned with the stability of the construction waste landfill hill, and has grown taller and larger in size with steep slopes which may cause potential danger and hazardous to the surrounding area. It is appreciated that if you can investigate on the issue, and rectify the situation to a safe and healthy condition. Please confirm when and how the rectification will be completed." Another complaint to EPD was received from the SOR's email on 14 February 2018. The complaint was the same as the abovementioned with two figures showing the location of Dragonair & CNAC (Group) Building and Cathay Dragon House.	Near Dragonair / CNAC (Group) Building (HKIA)	Based on our investigation result, the complaint was related to Contract No. HV/2011/03. The Contractor has implemented Environmental Mitigation Implementation Schedule as per the EM&A Manual. Also, the Contractor was reminided to remove the concerned stockpile of the fill materials as scon as possible to minimize the potential nuisance caused to the nearby sensitive receivers.	Closed	
Follow-ups of Complaint No COM- 0018-132	16 March 2018 and 21 March 2018	Nil	HyD (SOR referred the email from HyD ET) and EPD (ENPO referred SOR, who sent the email to the contractor and ET)	Dust and Construction Waste,	The complaint of 16 March 2018 was addressed to HyD and its details were as follows: *1) It was observed from daily photos that: a. Inadequate dust suppression measures implemented. b. Green tarp does not cover the entire pile of the waste land fill. C. Dry soil constantly being observed, and constantly picked-up by strong gusty winds within CLK area. d. Large boulders and steep slopes on waste landfill, with inadequate safety measures implemented. 20 Performed that the removal of the tackcipile. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and other relevant Regulations. 21 Please advise if the slope and setting of the piles of earth complies within Building and utber and value advised in the set should be used to advise the compliant of 121 March 2018 was addressed to PD and its details were as follows: "Re: Large construction landiff waste outside Cathy Program House, CLK, We refer to your letter ref. [EP3/N09/R500004678-18] dated 09 March 2018, would like to further draw your attention to the open sloced suppression measures implemented. 0 Green tarp does not cover the whole of the waste landfill, 0 Dry all constrainty bakeved, and constanty picket-up strong gusty winds within CLK area. - Large boulders and and steep slopes on waste	Near Dragonair / CNAC (Group) Building (HKIA)	Based on our investigation result, the complaint was related to Contract No. HY/2011/03. It was noted that no Action and Limit Level exceedances of 1-hr and 24-hr TSP were recorded at air monitoring station AMS6- Dragonal Eukling during the peotics from watering on the stochalter was cheeved underlater alfewards. The Contract has been continuously reminded to properly implement Environmental Mitigation Measures as per the EM&A Marual. The Contractor was also reminded to properly implement Environmental Mitigation Measures as per the EM&A Marual. The Contractor was also reminded to remove the concerned stochalter was cheeved underlater alfewards. The better that indicate a stochast was also reminded to remove the concerned stochalter was cheeved underlater alfewards. The the potential nuisance caused to the nearby sensitive receivers.	Closed	-
COM-2018-142	29 June 2018 & 6 July 2018	Nil	EPD (EMPO network the small to SPR, Contractor and ET)	Ncise	It is annexisted that if source, continue to investigate on the issue, provide close monitorion of the situation, and The compilatin of 29 June 2018 was received from DPI and its details were as follows:- EPD have recently received a complaint regarding frequent noise from construction works next to Cathay Dragon House, facing Tung Chung direction. The complaint details are discribed as below: "We would like to raise your attention and forward a complaint regarding frequent noise from construction works next to our Cathay Dragon House, facing Tung Chung direction. Them the video into below, it seems like the noise is mainly from the breaking of rocks using powered mechanical equipment. https://www.dorpbox.com/s/634s12p3op3959/IIMG_3137.MOV?dI=0 Our colleagues at Cathay Dragon House, has complaint that such disturbance has been going on for a week and works are carried out throughout the whole day. Please advise whether: Such noisy works have been carried out with EPD or Highways' "Approved Permit"; The noise level have been limited by your permit; Any regular monitoring works or report have been sent to your department. When will be work/noise stops; Furthermore, Muse work involues email 18 April 2018 that the works should have completed end April 2018. Why is the works ling ong no? M to all thermore in the letter dated 11 April 2018, you would conduct site inspections, Have you noticed any non- compliance?	Near Dragonair / CNAC (Group) Building (HKIA)	seed on our inveligation result, the completint was related to Contract No. HV(201162. The Contractor hes injugemented Environmental Mitigation Inglementation Schoola as per the EMAA Manual, such as courre he braker top with multiter minimize the quartities of noisy plant as far as practicable. Although the rock breaking works outside the Cathay Dragot House/ Dragmark & CNAC (Group) Building were completed on 9 July 2018. the Contractor has been continuously reminded to properly implement Environmental Mitigation Measures as per the EMAA Manual to minimize the potential noise nuisance caused to the public/ surrounding.	Olosed	

Complaint No.	Received Date	Received Time	Source	Category	Complaint Details	Location	Improvement Measures Taken	Status	Remarks
					¹ A further complaint was received on 6 July 2018 from EPD and its details were as follows:- "Further to our previous complaints which are in vain, we would like to continue to put forward the complaint against the noise from the construction works next to Cathay Dragon House at CLK, which has never been ceased and been causing great disturbance to the accommodations (aviation control centre) and staff within our Cathay Dragon building and CNAC tower. Below is the time schedule our staff regarding the noise disturbance from the site which is frequent and continuous.				
					Date Time Date Time 3 July 2018 8:30am – 11:30am, 1:30pm – 5:30pm 4 July 2018 8:30am – 11:30am, 1:30pm – 5:30pm 5 July 2018 8:30am – 11:30am, 1:30pm – 5:30pm				
					Please advise what has been your action upon this matter. This has been intolerable for months. If there is nothing that your depts, can impose to stop the disturbance, we may need to seek other alternative complain channel.				
					Your immediate action on this matter is highly appreciated." "We would like to get your urgent attention to the noise nuisance matters that is occurring outside Cathay Dragon House (facing seaside Tung Chung). Three have been extreme noisy works conducted, without proper noise mitigation matter, with noise DB levels reaching 70-1008, and is seriously affecting our company operations.				
					Please urgenty attend to the matter and advise further on the email below, and implement the proper noise reducing and mitigation procedures.				
COM-2018-158	24-Dec-18	10:17 AM	HyD (SOR referred the email from HyD to Contractor, ET and IEC/ENPO on 10:17 am, on 24 Dec 2018)	Other: Construction work on Sunday Morning	The details of the complaint were as follows: Email received by HyD on 23 December 2018 at 10:49hrs "How come someone is doing some construction work on sunday morning (23/12/18, 10:30am)??? Looks like your christmas holidays i going to turn into an investigation holiday!!! Looking forwards to hearing from you? I am sure David will be more than happy to assist your investigation over the holidays!!"	N.A.	Based on our investigation result, the concerned work activity compiled with the valid CNP. In this case, no follow up action is required. However, the Contractor has been reminded to comply with the conditions stipulated in the Construction Noise Permit for construction works undertaken during restricted hours.	Closed	-
					Email received by HyD on 23 December 2018 at 11:11hrs "by the way have you usue a "premit to annoy people" based on merit to operate a crane this sunday? If not I am looking forwards to know the action you will take. Don't estate to contact Chief Lam he will surely be very happy to provide any assistance you need to find out who is the rogue employee working under him so you can take the necessary lead action."				
/A	03-Apr-19	Nil	EPD (ENPO referred the email from EPD to HyD, SOR, Contractor and ET) through email	Dust	Email received by EPD on 3 April 2019 ***包括人来完清波建算鲜黄香内培液演大幅的地營正進行工程,工程期間會標起大量整土,引起污染,影響海堤灣鲜居民, 要求部門間進事宜,*	N.A.	Based on our investigation result, there is no cheevation of dust emissions arising from the Contract Na HY/201103. The Contract Na implemented the Environment Mitigation Implementation Schedule as per the EMAA Manual, the Contractor has been reminded to strictly maritain the dust mitigation measures during carrying out of their construction works to minimize the dust missingous to nextly ensetible recovery.	Closed	-
OM-2019-163	30-Apr-19	Nil	SOR referred details of complaint to Contractor, ET and IEC/ENPO through email	Waste	The details of the complaint were as follows:- ""ubdish and relies pieu by thy the road near a bus stop breeding numerous files and pests. huge annoyance and hygiene problem to the public. pls clean up."		Based on our investigation result, there was no observation of works in the area of complaint on issue of general refuse arising the Contract. No. HY/201103. The Contractor has implemented the Environmental Mitggation Implementation Schedule as per the EM&A Manual, the Contractor has been reminded to strictly maintain waste management procedures during their construction works to avoid the hygiene impacts to nearby sensitive receivers.	Closed	-
DM-2020-165	18-Mar-20	Nil	Hotline "1823" (SOR referred details of complaint to Contractor, ET and IEC/ENPO through email)	Waste	The details of the complaint were as follows:- "Rubbish are found along the landscape area at Tung Ylu Road. Dear 1823 officer, Regarding the captioned case, I have previously made my complaint to the Airport Authority (AA) on the subject. Yet, AA advises that the concerned area at Tung Ylu Road is not managed by the AA and suggests me to contact 1823 for follow up."	area at Tung	Based on our investigation result, there was no observation of works in the area of complaint on issue of general refuse arising from the Contract No. HY/2011(03, The Contractor has implemented the Environmental Mitigation Implementation Schedule as per the EM&A Manual, the Contractor has been reminded to strictly maintain waste management procedures during their construction works to avoid the hygiene impacts to nearby sensitive receivers.	Closed	
OM-2022-166	28-Jun-22	Nil	EPD (IEC/ENPO referred details of complaint to Contractor, ET and SOR through email)	Waste	The details of the complaint were as follows:- **周期完满除潮漏與重大海岸對出海面垃圾問題* 1. 近漠涌與所戴角機帶接點的大機附近,即赤鐵角南這附近的海旁有實種簡公室遵禁材料。原料及諷架;及海面有大堆沙丘 被重置原本; 2. 虹氣則L腿類分之海面有大堆沙丘及不少漂浮物件被重置數年。 上或位置(見附圖)的腦粉分丘及是不少漂浮物件被重置數年。 上或位置(見附圖)的腦粉分丘及是來的清解是與實裡推該清凍情的這葉材料。但現時准說漢大概已於2018年诺瓜及通 考確。上述現代的這些無材料及專用作者考望處理。」使用不當會這些原環所完。要有機對動發系行造成危險。有見及此 。我們希望、實過可定員跟進上述情况至不時作出監察,以證免海上意外發生及造成污染、	PR10	Based on our investigatyion result, there was no observation of works in the area of complaint on issue of general refuse arising from the Contract No. HY/2011/03. The Contractor has implemented the Environmental Mitigation Implementation Schedule as per the EM&A Manual. He Contractor has been reminded to strictly maintain waste management procedures during their construction works to avoid the hygiene impacts to nearby sensitive receivers.	Closed	-