

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2017-09-06	ASR8A	8:30	1-hr TSP	51	394	500		
TMCLKL	HY/2012/07	2017-09-06	ASR8A	9:32	1-hr TSP	28				
TMCLKL	HY/2012/07	2017-09-06	ASR8A	10:40	1-hr TSP	22				
TMCLKL	HY/2012/07	2017-09-12	ASR8A	8:25	1-hr TSP	97				
TMCLKL	HY/2012/07	2017-09-12	ASR8A	9:35	1-hr TSP	135				
TMCLKL	HY/2012/07	2017-09-12	ASR8A	10:43	1-hr TSP	154				
TMCLKL	HY/2012/07	2017-09-18	ASR8A	8:25	1-hr TSP	169				
TMCLKL	HY/2012/07	2017-09-18	ASR8A	9:30	1-hr TSP	105				
TMCLKL	HY/2012/07	2017-09-18	ASR8A	10:40	1-hr TSP	81				
TMCLKL	HY/2012/07	2017-09-21	ASR8A	8:28	1-hr TSP	55				
TMCLKL	HY/2012/07	2017-09-21	ASR8A	9:32	1-hr TSP	58				
TMCLKL	HY/2012/07	2017-09-21	ASR8A	10:38	1-hr TSP	43				
TMCLKL	HY/2012/07	2017-09-27	ASR8A	8:25	1-hr TSP	73				
TMCLKL	HY/2012/07	2017-09-27	ASR8A	9:27	1-hr TSP	136				
TMCLKL	HY/2012/07	2017-09-27	ASR8A	10:35	1-hr TSP	61				
				Average		85				
				Min.		22				
				Max.		169				

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2017-09-06	ASR9	8:41	1-hr TSP	73	393	500		
TMCLKL	HY/2012/07	2017-09-06	ASR9	9:43	1-hr TSP	21				
TMCLKL	HY/2012/07	2017-09-06	ASR9	10:50	1-hr TSP	29				
TMCLKL	HY/2012/07	2017-09-12	ASR9	8:35	1-hr TSP	119				
TMCLKL	HY/2012/07	2017-09-12	ASR9	9:47	1-hr TSP	137				
TMCLKL	HY/2012/07	2017-09-12	ASR9	10:55	1-hr TSP	169				
TMCLKL	HY/2012/07	2017-09-18	ASR9	8:35	1-hr TSP	206				
TMCLKL	HY/2012/07	2017-09-18	ASR9	9:42	1-hr TSP	89				
TMCLKL	HY/2012/07	2017-09-18	ASR9	10:50	1-hr TSP	117				
TMCLKL	HY/2012/07	2017-09-21	ASR9	8:40	1-hr TSP	57				
TMCLKL	HY/2012/07	2017-09-21	ASR9	9:44	1-hr TSP	41				
TMCLKL	HY/2012/07	2017-09-21	ASR9	10:48	1-hr TSP	51				
TMCLKL	HY/2012/07	2017-09-27	ASR9	8:36	1-hr TSP	97				
TMCLKL	HY/2012/07	2017-09-27	ASR9	9:38	1-hr TSP	97				
TMCLKL	HY/2012/07	2017-09-27	ASR9	10:50	1-hr TSP	189				
				Average		99				
				Min.		21				
				Max.		206				



Appendix G2 Air Quality Monitoring Results

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2017-09-06	ASR8A	11:42	24-hr TSP	17	178	260
TMCLKL	HY/2012/07	2017-09-12	ASR8A	11:45	24-hr TSP	50		
TMCLKL	HY/2012/07	2017-09-18	ASR8A	11:42	24-hr TSP	35		
TMCLKL	HY/2012/07	2017-09-21	ASR8A	11:40	24-hr TSP	21		
TMCLKL	HY/2012/07	2017-09-27	ASR8A	11:37	24-hr TSP	44		
						Average	33	
						Min.	17	
						Max.	50	



24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2017-09-06	ASR9	11:52	24-hr TSP	22	178	260
TMCLKL	HY/2012/07	2017-09-12	ASR9	11:57	24-hr TSP	47		
TMCLKL	HY/2012/07	2017-09-18	ASR9	11:52	24-hr TSP	45		
TMCLKL	HY/2012/07	2017-09-21	ASR9	11:50	24-hr TSP	25		
TMCLKL	HY/2012/07	2017-09-27	ASR9	11:52	24-hr TSP	45		
						Average	37	
						Min.	22	
						Max.	61	



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Launching gantry operation;; Installation of pier head and deck segments; and Slope work of Viaducts A, B & C.



Weather condition within the reporting period varied between sunny to rainy.
 Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Launching gantry operation; Installation of pier head and deck segments; and Slope work of Viaducts A, B & C.