

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2017-12-05	ASR8A	8:35	1-hr TSP	149	394	500		
TMCLKL	HY/2012/07	2017-12-05	ASR8A	9:37	1-hr TSP	133				
TMCLKL	HY/2012/07	2017-12-05	ASR8A	11:00	1-hr TSP	112				
TMCLKL	HY/2012/07	2017-12-11	ASR8A	8:00	1-hr TSP	83				
TMCLKL	HY/2012/07	2017-12-11	ASR8A	9:02	1-hr TSP	73				
TMCLKL	HY/2012/07	2017-12-11	ASR8A	10:04	1-hr TSP	65				
TMCLKL	HY/2012/07	2017-12-14	ASR8A	8:10	1-hr TSP	42				
TMCLKL	HY/2012/07	2017-12-14	ASR8A	9:12	1-hr TSP	31				
TMCLKL	HY/2012/07	2017-12-14	ASR8A	10:14	1-hr TSP	87				
TMCLKL	HY/2012/07	2017-12-20	ASR8A	8:05	1-hr TSP	126				
TMCLKL	HY/2012/07	2017-12-20	ASR8A	9:07	1-hr TSP	112				
TMCLKL	HY/2012/07	2017-12-20	ASR8A	10:09	1-hr TSP	121				
TMCLKL	HY/2012/07	2017-12-23	ASR8A	8:02	1-hr TSP	69				
TMCLKL	HY/2012/07	2017-12-23	ASR8A	9:04	1-hr TSP	57				
TMCLKL	HY/2012/07	2017-12-23	ASR8A	10:06	1-hr TSP	45				
TMCLKL	HY/2012/07	2017-12-29	ASR8A	8:06	1-hr TSP	133				
TMCLKL	HY/2012/07	2017-12-29	ASR8A	9:08	1-hr TSP	93				
TMCLKL	HY/2012/07	2017-12-29	ASR8A	10:10	1-hr TSP	92				
				Average		90				
				Min.		31				
				Max.		149				

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9



Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2017-12-05	ASR9	8:46	1-hr TSP	73	393	500		
TMCLKL	HY/2012/07	2017-12-05	ASR9	9:48	1-hr TSP	95				
TMCLKL	HY/2012/07	2017-12-05	ASR9	11:10	1-hr TSP	84				
TMCLKL	HY/2012/07	2017-12-11	ASR9	8:10	1-hr TSP	123				
TMCLKL	HY/2012/07	2017-12-11	ASR9	9:12	1-hr TSP	76				
TMCLKL	HY/2012/07	2017-12-11	ASR9	10:14	1-hr TSP	95				
TMCLKL	HY/2012/07	2017-12-14	ASR9	8:22	1-hr TSP	76				
TMCLKL	HY/2012/07	2017-12-14	ASR9	9:24	1-hr TSP	41				
TMCLKL	HY/2012/07	2017-12-14	ASR9	10:26	1-hr TSP	49				
TMCLKL	HY/2012/07	2017-12-20	ASR9	8:16	1-hr TSP	180				
TMCLKL	HY/2012/07	2017-12-20	ASR9	9:18	1-hr TSP	75				
TMCLKL	HY/2012/07	2017-12-20	ASR9	10:20	1-hr TSP	89				
TMCLKL	HY/2012/07	2017-12-23	ASR9	8:14	1-hr TSP	77				
TMCLKL	HY/2012/07	2017-12-23	ASR9	9:16	1-hr TSP	77				
TMCLKL	HY/2012/07	2017-12-23	ASR9	10:18	1-hr TSP	83				
TMCLKL	HY/2012/07	2017-12-29	ASR9	8:17	1-hr TSP	172				
TMCLKL	HY/2012/07	2017-12-29	ASR9	9:19	1-hr TSP	87				
TMCLKL	HY/2012/07	2017-12-29	ASR9	10:21	1-hr TSP	69				
				Average		90				
				Min.		41				
				Max.		180				

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2017-12-05	ASR8A	12:02	24-hr TSP	71	178	260
TMCLKL	HY/2012/07	2017-12-11	ASR8A	11:40	24-hr TSP	107		
TMCLKL	HY/2012/07	2017-12-14	ASR8A	11:52	24-hr TSP	53		
TMCLKL	HY/2012/07	2017-12-20	ASR8A	11:35	24-hr TSP	98		
TMCLKL	HY/2012/07	2017-12-23	ASR8A	11:55	24-hr TSP	151		
TMCLKL	HY/2012/07	2017-12-29	ASR8A	11:15	24-hr TSP	38		
					Average	86		
					Min.	38		
					Max.	151		



24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2017-12-05	ASR9	12:12	24-hr TSP	82	178	260
TMCLKL	HY/2012/07	2017-12-11	ASR9	11:52	24-hr TSP	110		
TMCLKL	HY/2012/07	2017-12-14	ASR9	12:05	24-hr TSP	61		
TMCLKL	HY/2012/07	2017-12-20	ASR9	11:46	24-hr TSP	99		
TMCLKL	HY/2012/07	2017-12-23	ASR9	12:06	24-hr TSP	172		
TMCLKL	HY/2012/07	2017-12-29	ASR9	11:26	24-hr TSP	45		
					Average	95		
					Min.	45		
					Max.	172		



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Launching gantry operation;; Installation of pier head and deck segments; and Slope work of Viaducts A, B & C.



Weather condition within the reporting period varied between sunny to rainy.
 Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Launching gantry operation; Installation of pier head and deck segments; and Slope work of Viaducts A, B & C.