


Appendix I-1 Noise Monitoring Results

Project	Works	Date (yyyy-mm-dd)	Station	Weather Condition	Time (hh:mm, 24hour)	Noise Level for 30-min, dB(A)			Limit Level dB(A)	Wind Speed (m/s)	Noise Meter Model/ID	Calibrator Model/ID
						Leq	L10	L90				
TMCLKL	HY/2012/07	2018-03-05	NSR1A	Sunny	9:34	63	64	60	75	0.3	RION NL31 (S/N 00603867)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018-03-08	NSR1A	Cloudy	10:08	65	67	64	75	0.3	RION NL31 (S/N 00603867)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018-03-14	NSR1A	Cloudy	9:30	64	65	62	75	0.3	RION NL31 (S/N 00603867)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018-03-20	NSR1A	Cloudy	9:25	64	65	61	75	1.2	RION NL31 (S/N 00603867)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018-03-26	NSR1A	Sunny	9:22	64	65	60	75	0.3	RION NL31 (S/N 00603867)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018-03-29	NSR1A	Sunny	10:12	63	65	60	75	0.5	RION NL31 (S/N 00603867)	RION NC73 (S/N 10486660)
						Min.	63					
						Max.	65					
						Average	64					

### Noise Monitoring Results at NSR 1A ( $L_{eq, 30min}$ )



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Installation of pier head and deck segments; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B, C & D.