

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2018-07-03	ASR8A	8:25	1-hr TSP	66	394	500		
TMCLKL	HY/2012/07	2018-07-03	ASR8A	9:27	1-hr TSP	64				
TMCLKL	HY/2012/07	2018-07-03	ASR8A	10:30	1-hr TSP	78				
TMCLKL	HY/2012/07	2018-07-09	ASR8A	8:00	1-hr TSP	68				
TMCLKL	HY/2012/07	2018-07-09	ASR8A	9:02	1-hr TSP	58				
TMCLKL	HY/2012/07	2018-07-09	ASR8A	10:10	1-hr TSP	48				
TMCLKL	HY/2012/07	2018-07-12	ASR8A	8:00	1-hr TSP	21				
TMCLKL	HY/2012/07	2018-07-12	ASR8A	9:02	1-hr TSP	46				
TMCLKL	HY/2012/07	2018-07-12	ASR8A	10:14	1-hr TSP	31				
TMCLKL	HY/2012/07	2018-07-18	ASR8A	8:02	1-hr TSP	47				
TMCLKL	HY/2012/07	2018-07-18	ASR8A	9:04	1-hr TSP	56				
TMCLKL	HY/2012/07	2018-07-18	ASR8A	10:10	1-hr TSP	53				
TMCLKL	HY/2012/07	2018-07-24	ASR8A	8:30	1-hr TSP	60				
TMCLKL	HY/2012/07	2018-07-24	ASR8A	9:32	1-hr TSP	28				
TMCLKL	HY/2012/07	2018-07-24	ASR8A	10:45	1-hr TSP	21				
TMCLKL	HY/2012/07	2018-07-30	ASR8A	8:00	1-hr TSP	63				
TMCLKL	HY/2012/07	2018-07-30	ASR8A	9:02	1-hr TSP	36				
TMCLKL	HY/2012/07	2018-07-30	ASR8A	10:11	1-hr TSP	19				
						Average			48	
						Min.			19	
						Max.	78			

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9



Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2018-07-03	ASR9	8:35	1-hr TSP	108	393	500		
TMCLKL	HY/2012/07	2018-07-03	ASR9	9:37	1-hr TSP	58				
TMCLKL	HY/2012/07	2018-07-03	ASR9	10:41	1-hr TSP	63				
TMCLKL	HY/2012/07	2018-07-09	ASR9	8:12	1-hr TSP	79				
TMCLKL	HY/2012/07	2018-07-09	ASR9	9:14	1-hr TSP	60				
TMCLKL	HY/2012/07	2018-07-09	ASR9	10:20	1-hr TSP	55				
TMCLKL	HY/2012/07	2018-07-12	ASR9	8:11	1-hr TSP	30				
TMCLKL	HY/2012/07	2018-07-12	ASR9	9:13	1-hr TSP	34				
TMCLKL	HY/2012/07	2018-07-12	ASR9	10:25	1-hr TSP	50				
TMCLKL	HY/2012/07	2018-07-18	ASR9	8:14	1-hr TSP	54				
TMCLKL	HY/2012/07	2018-07-18	ASR9	9:16	1-hr TSP	44				
TMCLKL	HY/2012/07	2018-07-18	ASR9	10:22	1-hr TSP	58				
TMCLKL	HY/2012/07	2018-07-24	ASR9	8:42	1-hr TSP	70				
TMCLKL	HY/2012/07	2018-07-24	ASR9	9:44	1-hr TSP	34				
TMCLKL	HY/2012/07	2018-07-24	ASR9	10:57	1-hr TSP	17				
TMCLKL	HY/2012/07	2018-07-30	ASR9	8:13	1-hr TSP	59				
TMCLKL	HY/2012/07	2018-07-30	ASR9	9:15	1-hr TSP	42				
TMCLKL	HY/2012/07	2018-07-30	ASR9	10:22	1-hr TSP	43				
						Average			53	
						Min.			17	
						Max.	108			

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A



Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2018-07-03	ASR8A	11:32	24-hr TSP	32	178	260
TMCLKL	HY/2012/07	2018-07-09	ASR8A	11:12	24-hr TSP	27		
TMCLKL	HY/2012/07	2018-07-12	ASR8A	11:16	24-hr TSP	18		
TMCLKL	HY/2012/07	2018-07-18	ASR8A	11:12	24-hr TSP	28		
TMCLKL	HY/2012/07	2018-07-24	ASR8A	11:47	24-hr TSP	31		
TMCLKL	HY/2012/07	2018-07-30	ASR8A	11:13	24-hr TSP	29		
						Average	28	
						Min.	18	
						Max.	32	

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2018-07-03	ASR9	11:43	24-hr TSP	44	178	260
TMCLKL	HY/2012/07	2018-07-09	ASR9	11:22	24-hr TSP	31		
TMCLKL	HY/2012/07	2018-07-12	ASR9	11:27	24-hr TSP	21		
TMCLKL	HY/2012/07	2018-07-18	ASR9	11:24	24-hr TSP	28		
TMCLKL	HY/2012/07	2018-07-24	ASR9	11:59	24-hr TSP	33		
TMCLKL	HY/2012/07	2018-07-30	ASR9	11:24	24-hr TSP	28		
						Average	31	
						Min.	21	
						Max.	44	



Weather condition within the reporting period varied between sunny to rainy.
 Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Installation of pier head and deck segments; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B, C & D.



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Installation of pier head and deck segments; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B,C & D.