

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2018-08-02	ASR8A	8:20	1-hr TSP	23	394	500		
TMCLKL	HY/2012/07	2018-08-02	ASR8A	9:22	1-hr TSP	53				
TMCLKL	HY/2012/07	2018-08-02	ASR8A	10:35	1-hr TSP	28				
TMCLKL	HY/2012/07	2018-08-08	ASR8A	8:20	1-hr TSP	67				
TMCLKL	HY/2012/07	2018-08-08	ASR8A	9:22	1-hr TSP	64				
TMCLKL	HY/2012/07	2018-08-08	ASR8A	10:30	1-hr TSP	46				
TMCLKL	HY/2012/07	2018-08-14	ASR8A	8:30	1-hr TSP	48				
TMCLKL	HY/2012/07	2018-08-14	ASR8A	9:32	1-hr TSP	50				
TMCLKL	HY/2012/07	2018-08-14	ASR8A	10:35	1-hr TSP	73				
TMCLKL	HY/2012/07	2018-08-23	ASR8A	8:35	1-hr TSP	94				
TMCLKL	HY/2012/07	2018-08-23	ASR8A	9:37	1-hr TSP	85				
TMCLKL	HY/2012/07	2018-08-23	ASR8A	10:42	1-hr TSP	77				
TMCLKL	HY/2012/07	2018-08-25	ASR8A	8:33	1-hr TSP	100				
TMCLKL	HY/2012/07	2018-08-25	ASR8A	9:35	1-hr TSP	140				
TMCLKL	HY/2012/07	2018-08-25	ASR8A	10:37	1-hr TSP	162				
TMCLKL	HY/2012/07	2018-08-29	ASR8A	8:32	1-hr TSP	75				
TMCLKL	HY/2012/07	2018-08-29	ASR8A	9:34	1-hr TSP	41				
TMCLKL	HY/2012/07	2018-08-29	ASR8A	10:41	1-hr TSP	66				
						Average			72	
						Min.			23	
						Max.	162			

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9



Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2018-08-02	ASR9	8:31	1-hr TSP	66	393	500		
TMCLKL	HY/2012/07	2018-08-02	ASR9	9:33	1-hr TSP	38				
TMCLKL	HY/2012/07	2018-08-02	ASR9	10:46	1-hr TSP	58				
TMCLKL	HY/2012/07	2018-08-08	ASR9	8:30	1-hr TSP	50				
TMCLKL	HY/2012/07	2018-08-08	ASR9	9:32	1-hr TSP	47				
TMCLKL	HY/2012/07	2018-08-08	ASR9	10:41	1-hr TSP	47				
TMCLKL	HY/2012/07	2018-08-14	ASR9	8:42	1-hr TSP	81				
TMCLKL	HY/2012/07	2018-08-14	ASR9	9:44	1-hr TSP	44				
TMCLKL	HY/2012/07	2018-08-14	ASR9	10:47	1-hr TSP	91				
TMCLKL	HY/2012/07	2018-08-23	ASR9	8:46	1-hr TSP	118				
TMCLKL	HY/2012/07	2018-08-23	ASR9	9:48	1-hr TSP	65				
TMCLKL	HY/2012/07	2018-08-23	ASR9	10:55	1-hr TSP	106				
TMCLKL	HY/2012/07	2018-08-25	ASR9	8:45	1-hr TSP	103				
TMCLKL	HY/2012/07	2018-08-25	ASR9	9:47	1-hr TSP	151				
TMCLKL	HY/2012/07	2018-08-25	ASR9	10:49	1-hr TSP	180				
TMCLKL	HY/2012/07	2018-08-29	ASR9	8:43	1-hr TSP	47				
TMCLKL	HY/2012/07	2018-08-29	ASR9	9:45	1-hr TSP	51				
TMCLKL	HY/2012/07	2018-08-29	ASR9	10:52	1-hr TSP	42				
						Average			77	
						Min.			38	
						Max.	180			

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2018-08-02	ASR8A	11:37	24-hr TSP	23	178	260
TMCLKL	HY/2012/07	2018-08-08	ASR8A	11:32	24-hr TSP	19		
TMCLKL	HY/2012/07	2018-08-14	ASR8A	11:37	24-hr TSP	25		
TMCLKL	HY/2012/07	2018-08-23	ASR8A	11:44	24-hr TSP	56		
TMCLKL	HY/2012/07	2018-08-25	ASR8A	11:39	24-hr TSP	66		
TMCLKL	HY/2012/07	2018-08-29	ASR8A	11:43	24-hr TSP	42		
						Average	39	
						Min.	19	
						Max.	66	



24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2018-08-02	ASR9	11:48	24-hr TSP	33	178	260
TMCLKL	HY/2012/07	2018-08-08	ASR9	11:43	24-hr TSP	28		
TMCLKL	HY/2012/07	2018-08-14	ASR9	11:49	24-hr TSP	20		
TMCLKL	HY/2012/07	2018-08-23	ASR9	11:57	24-hr TSP	53		
TMCLKL	HY/2012/07	2018-08-25	ASR9	11:51	24-hr TSP	70		
TMCLKL	HY/2012/07	2018-08-29	ASR9	11:54	24-hr TSP	48		
						Average	42	
						Min.	20	
						Max.	70	



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Installation of pier head and deck segments; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B, C & D.



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Installation of pier head and deck segments; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B,C & D.