


Appendix I-1 Noise Monitoring Results

Project	Works	Date (yyyy-mm-dd)	Station	Weather Condition	Time (hh:mm, 24hour)	Noise Level for 30-min, dB(A)			Limit Level dB(A)	Wind Speed (m/s)	Noise Meter Model/ID	Calibrator Model/ID
						Leq	L10	L90				
TMCLKL	HY/2012/07	2018/11/06	NSR1A	Sunny	10:00	64.6	66.5	60.6	75	0.5	RION NL52 (00131628)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018/11/12	NSR1A	Sunny	10:05	64.7	66.4	60.6	75	0.5	RION NL52 (00131628)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018/11/15	NSR1A	Sunny	10:00	65.1	67.6	62	75	0.5	RION NL52 (00131628)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018/11/21	NSR1A	Sunny	9:56	63.7	65.7	60.1	75	0.4	RION NL52 (00131628)	RION NC73 (S/N 10486660)
TMCLKL	HY/2012/07	2018/11/27	NSR1A	Cloudy	10:03	63.9	65.1	61.5	75	0.4	RION NL52 (00131628)	RION NC73 (S/N 10486660)
						Min.	63.7					
						Max.	65.1					
						Average	64					

Noise Monitoring Results at NSR 1A ($L_{eq, 30min}$)



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Reinstatement works of Cheung Tung Road; Abutment construction; Road works along North Lantau Highway; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B,C & D.

Marine works within the reporting period include Uninstallation of marine piling platform.