

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2018/12/03	ASR8A	8:40	1-hr TSP	138	394	500		
TMCLKL	HY/2012/07	2018/12/03	ASR8A	9:42	1-hr TSP	79				
TMCLKL	HY/2012/07	2018/12/03	ASR8A	10:45	1-hr TSP	69				
TMCLKL	HY/2012/07	2018/12/06	ASR8A	8:42	1-hr TSP	67				
TMCLKL	HY/2012/07	2018/12/06	ASR8A	9:44	1-hr TSP	57				
TMCLKL	HY/2012/07	2018/12/06	ASR8A	10:48	1-hr TSP	93				
TMCLKL	HY/2012/07	2018/12/12	ASR8A	8:55	1-hr TSP	133				
TMCLKL	HY/2012/07	2018/12/12	ASR8A	9:37	1-hr TSP	64				
TMCLKL	HY/2012/07	2018/12/12	ASR8A	10:40	1-hr TSP	300				
TMCLKL	HY/2012/07	2018/12/18	ASR8A	8:35	1-hr TSP	79				
TMCLKL	HY/2012/07	2018/12/18	ASR8A	9:37	1-hr TSP	129				
TMCLKL	HY/2012/07	2018/12/18	ASR8A	10:41	1-hr TSP	118				
TMCLKL	HY/2012/07	2018/12/21	ASR8A	8:37	1-hr TSP	60				
TMCLKL	HY/2012/07	2018/12/21	ASR8A	9:39	1-hr TSP	46				
TMCLKL	HY/2012/07	2018/12/21	ASR8A	10:43	1-hr TSP	51				
TMCLKL	HY/2012/07	2018/12/27	ASR8A	8:35	1-hr TSP	78				
TMCLKL	HY/2012/07	2018/12/27	ASR8A	9:37	1-hr TSP	74				
TMCLKL	HY/2012/07	2018/12/27	ASR8A	10:40	1-hr TSP	117				
				Average		97				
				Min.		46				
				Max.		300				

1-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9



Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)		
TMCLKL	HY/2012/07	2018/12/03	ASR9	8:30	1-hr TSP	164	393	500		
TMCLKL	HY/2012/07	2018/12/03	ASR9	9:32	1-hr TSP	77				
TMCLKL	HY/2012/07	2018/12/03	ASR9	10:34	1-hr TSP	60				
TMCLKL	HY/2012/07	2018/12/06	ASR9	8:30	1-hr TSP	87				
TMCLKL	HY/2012/07	2018/12/06	ASR9	9:32	1-hr TSP	64				
TMCLKL	HY/2012/07	2018/12/06	ASR9	10:38	1-hr TSP	141				
TMCLKL	HY/2012/07	2018/12/12	ASR9	8:25	1-hr TSP	130				
TMCLKL	HY/2012/07	2018/12/12	ASR9	9:27	1-hr TSP	68				
TMCLKL	HY/2012/07	2018/12/12	ASR9	10:30	1-hr TSP	75				
TMCLKL	HY/2012/07	2018/12/18	ASR9	8:25	1-hr TSP	122				
TMCLKL	HY/2012/07	2018/12/18	ASR9	9:27	1-hr TSP	81				
TMCLKL	HY/2012/07	2018/12/18	ASR9	10:30	1-hr TSP	106				
TMCLKL	HY/2012/07	2018/12/21	ASR9	8:26	1-hr TSP	70				
TMCLKL	HY/2012/07	2018/12/21	ASR9	9:28	1-hr TSP	56				
TMCLKL	HY/2012/07	2018/12/21	ASR9	10:33	1-hr TSP	61				
TMCLKL	HY/2012/07	2018/12/27	ASR9	8:25	1-hr TSP	53				
TMCLKL	HY/2012/07	2018/12/27	ASR9	9:27	1-hr TSP	61				
TMCLKL	HY/2012/07	2018/12/27	ASR9	10:30	1-hr TSP	94				
				Average		87				
				Min.		53				
				Max.		164				

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR8A

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2018/12/03	ASR8A	11:47	24-hr TSP	39	178	260
TMCLKL	HY/2012/07	2018/12/06	ASR8A	11:50	24-hr TSP	57		
TMCLKL	HY/2012/07	2018/12/12	ASR8A	11:42	24-hr TSP	63		
TMCLKL	HY/2012/07	2018/12/18	ASR8A	11:43	24-hr TSP	68		
TMCLKL	HY/2012/07	2018/12/21	ASR8A	11:45	24-hr TSP	48		
TMCLKL	HY/2012/07	2018/12/27	ASR8A	11:42	24-hr TSP	62		
						Average	56	
						Min.	39	
						Max.	68	

24-hour TSP Monitoring Results at Air Quality Monitoring Station ASR9



Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Parameter	Results (ug/m3)	Action Level (ug/m3)	Limit Level (ug/m3)
TMCLKL	HY/2012/07	2018/12/03	ASR9	11:36	24-hr TSP	48	178	260
TMCLKL	HY/2012/07	2018/12/06	ASR9	11:40	24-hr TSP	58		
TMCLKL	HY/2012/07	2018/12/12	ASR9	11:32	24-hr TSP	64		
TMCLKL	HY/2012/07	2018/12/18	ASR9	11:32	24-hr TSP	87		
TMCLKL	HY/2012/07	2018/12/21	ASR9	11:35	24-hr TSP	64		
TMCLKL	HY/2012/07	2018/12/27	ASR9	11:32	24-hr TSP	50		
						Average	62	
						Min.	48	
						Max.	87	



Weather condition within the reporting period varied between sunny to cloudy

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B, C & D.

Marine works within the reporting period include Uninstallation of marine piling platform.



Weather condition within the reporting period varied between sunny to cloudy.

Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B,C & D.

Marine works within the reporting period include Uninstallation of marine piling platform.