

Figure I1 Impact Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I2 Impact Monitoring – Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I3 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I4 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I5 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I6 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I7 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I8 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in surface waters during mid-flood tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I9 Impact Monitoring – Mean Level of Dissolved Oxygen (mg/L) in mid-depth waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and IS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management






Figure I10 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in mid-depth waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS(Mf)16.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I11 Impact Monitoring – Mean Level of Dissolved Oxygen (mg/L) in mid-depth waters during mid-flood tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and IS(Mf)5. (Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental Resources Management






Figure I12 Impact Monitoring – Mean Level of Dissolved Oxygen (mg/L) in mid-depth waters during mid-flood tide between 31 October 2013 to 28 February 2014 at IS(Mf)16.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I13 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management







Figure I14 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 1 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I15 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.
(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management






Figure I16 Impact Monitoring – Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-ebb tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I17 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I18 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management






Figure I19 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management






Figure I20 Impact Monitoring - Mean Level of Dissolved Oxygen (mg/L) in bottom waters during mid-flood tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**








Figure I21 Impact Monitoring – Mean Level of depth-averaged Turbidity (NTU) during mid-ebb tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I22 Impact Monitoring - Mean Level of depth-averaged Turbidity (NTU) during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental Resources Management






Figure I23 Impact Monitoring - Mean Level of depth-averaged Turbidity (NTU) during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management







Figure I24 Impact Monitoring - Mean Level of depth-averaged Turbidity (NTU) during mid-ebb tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I25 Impact Monitoring – Mean Level of depth-averaged Turbidity (NTU) during mid-flood tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management






Figure I26 Impact Monitoring - Mean Level of depth-averaged Turbidity (NTU) during mid-flood tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management








Figure I27 Impact Monitoring – Mean Level of depth-averaged Turbidity (NTU) during mid-flood tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I28 Impact Monitoring - Mean Level of depth-averaged Turbidity (NTU) during mid-flood tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**







Figure I29 Impact Monitoring - Mean Level of depth-averaged Suspended Solids (mg/L) during mid-ebb tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental
Resources
Management







Figure I30 Impact Monitoring - Mean Level of depth-averaged Suspended Solids (mg/L) during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I31 Impact Monitoring – Mean Level of depth-averaged Suspended Solids (mg/L) during mid-ebb tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental Resources Management






Figure I32 Impact Monitoring - Mean Level of depth-averaged Suspended Solids (mg/L) during mid-ebb tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I33 Impact Monitoring – Mean Level of depth-averaged Suspended Solids (mg/L) during mid-flood tide between 31 October 2013 to 28 February 2014 at CS(Mf)3 and CS(Mf)5.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

Environmental Resources Management






Figure I34 Impact Monitoring - Mean Level of depth-averaged Suspended Solids (mg/L) during mid-flood tide between 31 October 2013 to 28 February 2014 at IS(Mf)16 and IS(Mf)9 .
(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)






Figure I35 Impact Monitoring - Mean Level of depth-averaged Suspended Solids (mg/L) during mid-flood tide between 31 October 2013 to 28 February 2014 at IS8 and SR4.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**






Figure I36 Impact Monitoring - Mean Level of depth-averaged Suspended Solids (mg/L) during mid-flood tide between 31 October 2013 to 28 February 2014 at SR4a.

(Weather condition varied between sunny to rainy within the reporting period. Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.)

**Environmental
Resources
Management**

