



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include site office erection, fence relocation for Viaduct A, C & D and land piling at Viaduct B.

Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include site office erection, fence relocation for Viaduct A, C & D and land piling at Viaduct A.

Marine works within the reporting period include rockfill platform construction, marine piling platform installation and survey tower erection.