



Weather condition within June to August varied between sunny to rainy.

Major construction works undertaken within the reporting period include construction of pile cap superstructure of Viaduct B; fence installation and relocation of Area 2, Viaducts A, B, C & D; land piling at Viaduct B&D; piling platform installation for Viaducts B, C, D and E; site formation of workshop at Area 1; additional land GI, trial pits & lab testing; utility surveys; and slope work of Slope 9SE-B/C8, 9SE-B/C9 & 9SE-B/F9.

Marine works within the reporting period include construction of Pile caps at Viaduct B; marine piling platform installation; marine piling at Viaducts B, D & E; construction of rockfill platform at Viaduct D landing; and additional marine ground investigation (GI) and laboratory testing.



Weather condition within June to August varied between sunny to rainy.

Major construction works undertaken within the reporting period include construction of pile cap superstructure of Viaduct B; fence installation and relocation of Area 2, Viaducts A, B, C & D; land piling at Viaduct B&D; piling platform installation for Viaducts B, C, D and E; site formation of workshop at Area 1; additional land GI, trial pits & lab testing; utility surveys; and slope work of Slope 9SE-B/C8, 9SE-B/C9 & 9SE-B/F9.

Marine works within the reporting period include construction of Pile caps at Viaduct B; marine piling platform installation; marine piling at Viaducts B, D & E; construction of rockfill platform at Viaduct D landing; and additional marine ground investigation (GI) and laboratory testing.