


Noise Monitoring Results at NSR 1 ($L_{eq, 30min}$)



Weather condition within June to August varied between sunny to rainy.

Major construction works undertaken within the reporting period include construction of pile cap superstructure of Viaduct B; fence installation and relocation of Area 2, Viaducts A, B, C & D; land piling at Viaduct B&D; piling platform installation for Viaducts B, C, D and E; site formation of workshop at Area 1; additional land GI, trial pits & lab testing; utility surveys; and slope work of Slope 9SE-B/C8, 9SE-B/C9 & 9SE-B/F9.

Marine works within the reporting period include construction of Pile caps at Viaduct B; marine piling platform installation; marine piling at Viaducts B, D & E; construction of rockfill platform at Viaduct D landing; and additional marine ground investigation (GI) and laboratory testing.