


Weather condition within the reporting period varied between sunny to rainy.


Major construction works undertaken within the reporting period include Construction of pile cap superstructure of Viaducts B & C; Channel reconstruction at Area 1; Land Piling at Viaducts B, C & D; Pre-drilling works at Viaduct A; Construction of pile cap at Viaducts B & D; Additional land GI, trial pits & lab testing; Utility surveys; and Slope work of Slopes 9SE-B/C9, 9SE-B/C9 & 9SE-B/F9.

Marine works within the reporting period include Construction of Pile caps at Viaducts B, C & E; Marine piling platform installation &

uninstallation; Marine Piling at Viaducts B, C, D & E; and Additional marine ground investigation (GI) and laboratory testing.

TSP monitoring at ASR8 on 26 November and 2 December were cancelled due to rejection of access to monitoring station.





Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Construction of pile cap superstructure of Viaducts B & C; Channel reconstruction at Area 1; Land Piling at Viaducts B, C & D; Pre-drilling works at Viaduct A; Construction of pile cap at Viaducts B & D; Additional land GI, trial pits & lab testing; Utility surveys; and Slope work of Slopes 9SE-B/C9, 9SE-B/F9.

Marine works within the reporting period include Construction of Pile caps at Viaducts B, C & E; Marine piling platform installation & uninstallation; Marine Piling at Viaducts B, C, D & E; and Additional marine ground investigation (GI) and laboratory testing. TSP monitoring at ASR8 on 26 November and 2 December were cancelled due to rejection of access to monitoring station.