





Appendix F

Impact Air Quality
Monitoring Graphical
Presentation



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Reinstatement works of Cheung Tung Road; Abutment construction; Road works along North Lantau Highway; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B,C & D. Marine works within the reporting period include Uninstallation of marine piling platform.



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken within the reporting period include Reinstatement works of Cheung Tung Road; Abutment construction; Road works along North Lantau Highway; Asphalt paving; Sign gantries construction; Parapet installation; and Slope work of Viaducts A, B, C & D. Marine works within the reporting period include Uninstallation of marine piling platform.