





Appendix F

Impact Air Quality
Monitoring Graphical
Presentation



Weather condition within the reporting period varied between sunny to cloudy.
 Major construction works undertaken within the reporting period include slope work at Viaduct D and landscaping works at HKBCF.
 Marine works within the reporting period include reinstatement of seawall at seafront



Weather condition within the reporting period varied between sunny to cloudy.

Major construction works undertaken within the reporting period include slope work at Viaduct D and landscaping works at HKBCF.

Marine works within the reporting period include reinstatement of seawall at seafront