


Appendix G

## Impact Noise Monitoring Graphical Presentation

### Noise Monitoring Results at NSR 1A ( $L_{eq, 30min}$ )



*Weather condition within the reporting period varied between sunny to cloudy.*

*Major construction works undertaken within the reporting period include slope work of viaduct D, landscaping works at HKBCF.*

*Marine works within the reporting period include reinstatement of seawall at seafront.*