


Appendix G

Impact Noise Monitoring Graphical Presentation

Noise Monitoring Results at NSR 1A ($L_{eq, 30min}$)



Weather condition within the reporting period varied between sunny to rainy.

Major construction works undertaken during June and July 2019 included at-grade works and landscaping softworks at HKBCF and reinstatement of seawall at seafront. No major construction works were undertaken during August 2019.