


Weather condition within the reporting period varied between sunny to rainy. The overall monitoring results were not affected by weather conditions.

Major construction works undertaken within the reporting period include Predrilling at Viaduct F; Construction and installation of pile caps; Pier construction; Re-alignment of Cheung Tung Road; Additional land GI, trial pits & lab testing; Relocation of MTRC fence; Construction of land section of berth at Southern Landfall; Road works along North Lantau Highway; Installation of pier head and deck segments; and Slope work of Viaducts A, B & C.

Marine works within the reporting period include Construction and installation of pile caps; Uninstallation of marine piling platform; Construction of marine section of berth at southern landfall; Pier construction; Launching gantry operation; and Installation of deck segment and pier head segment.



Weather condition within the reporting period varied between sunny to rainy. The overall monitoring results were not affected by weather conditions.

Major construction works undertaken within the reporting period include Predrilling at Viaduct F; Construction and installation of pile caps; Pier construction; Re-alignment of Cheung Tung Road; Additional land GI, trial pits & lab testing; Relocation of MTRC fence; Construction of land section of berth at Southern Landfall; Road works along North Lantau Highway; Installation of pier head and deck segments; and Slope work of Viaducts A, B & C.

Marine works within the reporting period include Construction and installation of pile caps; Uninstallation of marine piling platform; Construction of marine section of berth at southern landfall; Pier construction; Launching gantry operation; and Installation of deck segment and pier head segment.