





Appendix D

Impact Air Quality  
Monitoring Graphical  
Presentation



Weather condition within the reporting period varied between sunny to rainy. The overall monitoring results were not affected by weather conditions. Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Launching gantry operation; Installation of pier head and deck segments; Asphalt paving, Constuction of sign ganties; Parapet and barriers installation and Slope work of Viaducts A, B,C & D.

Marine works within the reporting period include Uninstallation of marine piling platform.



Weather condition within the reporting period varied between sunny to rainy. The overall monitoring results were not affected by weather conditions. Major construction works undertaken within the reporting period include Pier construction; Re-alignment of Cheung Tung Road; Road works along North Lantau Highway; Launching gantry operation; Installation of pier head and deck segments; Asphalt paving, Constuction of sign ganties; Parapet and barriers installation and Slope work of Viaducts A, B,C & D. Marine works within the reporting period include Uninstallation of marine piling platform.