

Appendix H

Landfill Gas Monitoring
Results and Graphical
Presentation

Landfill Gas Monitoring Results on Methane Level



Project	Works	Date(yyyy-mm-dd)	Monitoring Location	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)		
TMCLKL	HY/2017/10	2019/05/02	Ventilation Plant Room	18:15	0	10.0	20.0		
TMCLKL	HY/2017/10	2019/05/02	Ventilation Plant Room	23:15	0				
TMCLKL	HY/2017/10	2019/05/03	Ventilation Plant Room	4:15	0				
TMCLKL	HY/2017/10	2019/05/03	Ventilation Plant Room	9:15	0				
TMCLKL	HY/2017/10	2019/05/04	Ventilation Plant Room	14:15	0				
TMCLKL	HY/2017/10	2019/05/04	Ventilation Plant Room	19:15	0				
TMCLKL	HY/2017/10	2019/05/06	Ventilation Plant Room	0:15	0				
TMCLKL	HY/2017/10	2019/05/06	Ventilation Plant Room	5:15	0				
TMCLKL	HY/2017/10	2019/05/07	Ventilation Plant Room	10:15	0				
TMCLKL	HY/2017/10	2019/05/07	Ventilation Plant Room	15:15	0				
TMCLKL	HY/2017/10	2019/05/08	Ventilation Plant Room	20:15	0				
TMCLKL	HY/2017/10	2019/05/08	Ventilation Plant Room	1:15	0				
TMCLKL	HY/2017/10	2019/05/09	Ventilation Plant Room	6:15	0				
TMCLKL	HY/2017/10	2019/05/09	Ventilation Plant Room	11:15	0				
TMCLKL	HY/2017/10	2019/05/10	Ventilation Plant Room	16:15	0				
TMCLKL	HY/2017/10	2019/05/10	Ventilation Plant Room	21:15	0				
TMCLKL	HY/2017/10	2019/05/11	Ventilation Plant Room	2:15	0				
TMCLKL	HY/2017/10	2019/05/11	Ventilation Plant Room	7:15	0				
TMCLKL	HY/2017/10	2019/05/14	Ventilation Plant Room	12:15	0				
TMCLKL	HY/2017/10	2019/05/14	Ventilation Plant Room	17:15	0				
TMCLKL	HY/2017/10	2019/05/15	Ventilation Plant Room	22:15	0				
TMCLKL	HY/2017/10	2019/05/15	Ventilation Plant Room	3:15	0				
					Average			0	
					Min.			0	
					Max.			0	

Landfill Gas Monitoring Results on Oxygen Level

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)		
TMCLKL	HY/2017/10	2019/05/02	Ventilation Plant Room	8:15	20.8	19.0	18.0		
TMCLKL	HY/2017/10	2019/05/02	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/03	Ventilation Plant Room	8:15	20.7				
TMCLKL	HY/2017/10	2019/05/03	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/04	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/04	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/06	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/06	Ventilation Plant Room	13:15	20.9				
TMCLKL	HY/2017/10	2019/05/07	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/07	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/08	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/08	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/09	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/09	Ventilation Plant Room	13:15	20.7				
TMCLKL	HY/2017/10	2019/05/10	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/10	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/11	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/11	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/14	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/14	Ventilation Plant Room	13:15	20.8				
TMCLKL	HY/2017/10	2019/05/15	Ventilation Plant Room	8:15	20.8				
TMCLKL	HY/2017/10	2019/05/15	Ventilation Plant Room	13:15	20.8				
				Average	20.8				
				Min.	20.7				
				Max.	20.9				


Landfill Gas Monitoring Results on Carbon Dioxide Level

Project	Works	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)		
TMCLKL	HY/2017/10	2019/05/02	Ventilation Plant Room	8:15	0.07	0.5	1.5		
TMCLKL	HY/2017/10	2019/05/02	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/03	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/03	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/04	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/04	Ventilation Plant Room	13:15	0.08				
TMCLKL	HY/2017/10	2019/05/06	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/06	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/07	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/07	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/08	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/08	Ventilation Plant Room	13:15	0.08				
TMCLKL	HY/2017/10	2019/05/09	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/09	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/10	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/10	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/11	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/11	Ventilation Plant Room	13:15	0.08				
TMCLKL	HY/2017/10	2019/05/14	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/14	Ventilation Plant Room	13:15	0.07				
TMCLKL	HY/2017/10	2019/05/15	Ventilation Plant Room	8:15	0.07				
TMCLKL	HY/2017/10	2019/05/15	Ventilation Plant Room	13:15	0.07				
					Average			0.07	
					Min.			0.07	
					Max.	0.08			



Weather condition within the reporting period was sunny to rainy

Major construction works undertaken within the reporting period include Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Toll Control Building, Electrical and Mechanical Works at Ventilation Plant Room, North Ventilation Room and Tunnel, Building Structure at Administration Building, Maintenance Depot, Fire Services Building, Customs and Excise Building and Satellite Control Building and Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Kiosk N2 and Underpass at C3 area.



Weather condition within the reporting period was sunny to rainy

Major construction works undertaken within the reporting period include Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Toll Control Building, Electrical and Mechanical Works at Ventilation Plant Room, North Ventilation Room and Tunnel, Building Structure at Administration Building, Maintenance Depot, Fire Services Building, Customs and Excise Building and Satellite Control Building and Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Kiosk N2 and Underpass at C3 area.