

Appendix H

Landfill Gas Monitoring
Results and Graphical
Presentation

Landfill Gas Monitoring Results on Methane Level

Project	Works	Date(yyyy-mm-dd)	Monitoring Location	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)
TMCLKL	HY/2017/10	2020-08-01	Main Control Building	8:15	0	10.0	20.0
TMCLKL	HY/2017/10	2020-08-01	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-03	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-03	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-04	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-04	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-05	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-05	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-06	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-06	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-07	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-07	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-08	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-08	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-10	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-10	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-11	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-11	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-12	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-12	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-13	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-13	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-14	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-14	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-15	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-15	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-17	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-17	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-18	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-18	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-19	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-19	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-20	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-20	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-21	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-21	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-22	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-22	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-24	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-24	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-25	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-25	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-26	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-26	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-27	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-27	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-28	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-28	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-29	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-29	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-08-31	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-08-31	Main Control Building	13:15	0		
					Average	0	
					Min.	0	
					Max.	0	