




Appendix G

Landfill Gas  
Monitoring Graphical  
Presentation



Weather condition within the reporting period was cloudy.

Major construction works undertaken within the reporting period include bar bending, timber formwork and concreting and Architectural Builder's Work and Finishes at Toll Control Building; electrical and Mechanical works at Ventilation Plant Room and North Ventilation Building, Building Structure at Administration Building and Maintenance Depot; Socket H-piling at Fire Services Department Building and Customs and Excise Department Building and Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Kiosk N2.



*Weather condition within the reporting period was cloudy.*

*Major construction works undertaken within the reporting period include bar bending, timber formwork and concreting and Architectural Builder's Work and Finishes at Toll Control Building; electrical and Mechanical works at Ventilation Plant Room and North Ventilation Building, Building Structure at Administration Building and Maintenance Depot; Socket H-piling at Fire Services Department Building and Customs and Excise Department Building and Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Kiosk N2.*