




Appendix G

Landfill Gas Monitoring
Results and Graphical
Presentation



Weather condition within the reporting period was sunny to rainy

Major construction works undertaken within the reporting period include Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Toll Control Building, Administration Building, Maintenance Depot, Underpass at C3 area, Kiosk N2 and Tunnel, Electrical and Mechanical Works at Ventilation Plant Room and North Ventilation Room, Building Structure at Fire Services Building, Customs and Excise Building, Satellite Control Building, Kiosk S1 and Toll Booth.



Weather condition within the reporting period was sunny to rainy
 Major construction works undertaken within the reporting period include Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Toll Control Building, Administration Building, Maintenance Depot, Underpass at C3 area, Kiosk N2 and Tunnel, Electrical and Mechanical Works at Ventilation Plant Room and North Ventilation Room, Building Structure at Fire Services Building, Customs and Excise Building, Satellite Control Building, Kiosk S1 and Toll Booth.