



Appendix G

Landfill Gas Monitoring  
Results and Graphical  
Presentation




Weather condition within the reporting period was sunny to rainy

Major construction works undertaken within the reporting period include

- Handover Inspection at Main Control Building;
- Electrical and Mechanical Works and Handover Inspection at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at Fire Services Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at Customs and Excise Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at N1;
- Electrical and Mechanical Works and Handover Inspection at Kiosk N2;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes, T&C and FSI at the Tunnel;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Soil Mix and Landscape Works at Northern Landfall and Southern Landfall.

## Landfill Gas Monitoring Results on Carbon Dioxide Level



Weather condition within the reporting period was sunny to rainy

Major construction works undertaken within the reporting period include

- Handover Inspection at Main Control Building;
- Electrical and Mechanical Works and Handover Inspection at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at Fire Services Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at Customs and Excise Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at N1;
- Electrical and Mechanical Works and Handover Inspection at Kiosk N2;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes, T&C and FSI at the Tunnel;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes and Handover Inspection at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Soil Mix and Landscape Works at Northern Landfall and Southern Landfall.